



May 4, 2018

Mr. Adam Fox, P.E.
Principal Engineer
Environmental Compliance Section
Bureau of Engineering and Construction
State of Connecticut Department of Transportation
2800 Berlin Turnpike, P.O. Box 317546
Newington, CT 06131-7546

Attention: Jason Coite, P.E. / Mandy Socolosky

Subject: On-Call Asbestos, Lead, Air Quality & Demolition Compliance
Agreement No. 04.27-01(15)
HazMat Inspection – One (1) Traffic Signal Intersection (079-210), Meriden, CT
ConnDOT Assignment No. 514-5706
ConnDOT Project No. 171-401
TRC Project No. 222165.5706.0710

Dear Mr. Fox:

TRC performed a limited survey for hazardous building materials associated with 1 traffic signal intersection (Int. No. 079-210) in Meriden, Connecticut. Results of the survey identified the following at the traffic signal span poles, mast arms, pedestals, crosswalk signal hoods/push buttons and controller cabinet replacements at the following Intersections:

Traffic Signal Int. No. 079-210, Route 5 at Westfield Rd. & Britannia St., Meriden

- All span poles were wood (unpainted). Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. No detectable amounts of lead in paint were found on the yellow crosswalk hoods/push buttons and grey painted metal controller cabinet.
- Since no detectable amounts of lead were present on painted metal surfaces of the crosswalk hoods/push buttons and controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.

Potential universal waste (UW) and Connecticut Regulated Waste (CRW) items associated with the traffic lights themselves, crosswalk signal hoods/buttons and controller cabinets (i.e. Hg lamps/PCB ballasts and/or printed circuit boards) are also likely present at the Intersection sites.

Laboratory data, inspector notes & project description information are attached.

If you have any questions, please call TRC at (860) 298-9692.

Very Truly Yours,

TRC

A handwritten signature in black ink, appearing to read "Stephen R. Arienti".

Stephen R. Arienti, CHMM
Senior Project Manager – Program Manager

Reviewed By:

A handwritten signature in black ink, appearing to read "Erik R. Plimpton".

Erik R. Plimpton, P.E., CHMM, CMC
Vice President – Engineer in Charge



Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer
 Site: ConnDOT - 1 Traffic Signal Intersection (79-210), Meriden, CT
 Project #: 222165.5706.0710
 Date(s): 1/29/2018
 Inspectors: Zac Smith

Number	Interior/ Exterior	Location	Int No.	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
1			Self Calibration										80.1	1/29/2018 10:13
2			0.0 Calibration							0.0	0.0	1.8	2.0	1/29/2018 10:15
3			0.7 Calibration							0.7	0.1	1.0	3.4	1/29/2018 10:15
4			1.6 Calibration							1.4	0.1	1.0	5.1	1/29/2018 10:15
5						VOID								
6						VOID								
7	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	0.1	0.2	5.0	2.0	1/29/2018 10:18
8	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	0.1	0.1	3.4	2.8	1/29/2018 10:18
9						VOID								
10						VOID								
11						VOID								
12						VOID								
13	Exterior	Cheshire	intersection 25-225	ne	signal hood		Metal	Yellow	Intact	0.9	0.1	1.1	4.2	1/29/2018 10:22
14	Exterior	Cheshire	intersection 25-225	ne	signal hood		Metal	Yellow	Intact	0.9	0.2	1.1	2.6	1/29/2018 10:22
15	Exterior	Cheshire	intersection 25-225	ne	signal hood		Metal	Yellow	Intact	0.9	0.1	1.1	4.2	1/29/2018 10:23
16	Exterior	Cheshire	intersection 25-225	ne	push to cross		Metal	Yellow	Intact	0.0	0.0	1.5	3.7	1/29/2018 10:24
17	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	0.1	0.0	3.1	22.3	1/29/2018 10:28
18	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	1.0	0.1	1.1	20.7	1/29/2018 10:29
19						VOID								
20	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Black	Intact	0.1	0.0	3.0	21.2	1/29/2018 10:31
21	Exterior	Cheshire	intersection 25-225	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/29/2018 10:35
22	Exterior	Cheshire	intersection 25-225	ne	span pole		Metal	Grey	Intact	0.0	0.0	1.0	7.6	1/29/2018 10:37
23						VOID								
24	Exterior	Southington	intersection 131-233	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.9	4.2	1/29/2018 11:14
25	Exterior	Southington	intersection 131-233	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	2.5	3.7	1/29/2018 11:14
26	Exterior	Southington	intersection 131-233	ne	span pole		Metal	Grey	Intact	0.0	0.0	2.0	4.2	1/29/2018 11:15
27	Exterior	Southington	intersection 131-233	nw	span pole		Metal	Grey	Intact	0.0	0.0	1.0	2.6	1/29/2018 11:16
28	Exterior	Southington	intersection 131-233	se	span pole		Metal	Grey	Intact	0.0	0.0	1.0	1.7	1/29/2018 11:17
29	Exterior	Plainville	intersection 109-201	e	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	3.4	1/29/2018 11:56
30	Exterior	Plainville	intersection 109-201	e	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.5	1/29/2018 11:56
31	Exterior	New Britain	intersection 088-247	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.5	1/29/2018 12:23
32	Exterior	New Britain	intersection 088-247	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	3.1	1/29/2018 12:23
33	Exterior	New Britain	intersection 088-247	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	1.9	6.8	1/29/2018 12:27
34	Exterior	New Britain	intersection 088-247	ne	signal hood		Metal	Yellow	Intact	1.2	0.1	1.1	5.4	1/29/2018 12:27
35	Exterior	New Britain	intersection 088-247	se	signal hood		Metal	Yellow	Intact	0.0	0.0	2.3	4.8	1/29/2018 12:28
36	Exterior	New Britain	intersection 088-279	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.1	2.5	1/29/2018 13:29
37	Exterior	New Britain	intersection 088-279	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	3.7	1/29/2018 13:29
38	Exterior	New Britain	intersection 088-279	se	span pole		Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/29/2018 13:32
39	Exterior	New Britain	intersection 088-279	se	span pole		Metal	Grey	Intact	0.0	0.0	1.3	4.5	1/29/2018 13:32

Lead paint includes paint found to contain **any detectable** amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise



Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer
 Site: ConnDOT - 1 Traffic Signal Intersection (79-210), Meriden, CT
 Project #: 222165.5706.0710
 Date(s): 1/29/2018
 Inspectors: Zac Smith

Number	Interior/ Exterior	Location	Int No.	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
40	Exterior	New Britain	Intersection 088-279	se	push to cross sign		Metal	Green	Intact	0.1	0.2	4.8	2.5	1/29/2018 13:39
41	Exterior	New Britain	Intersection 088-279	se	push to cross sign		Metal	Green	Intact	0.0	0.0	1.0	4.0	1/29/2018 13:40
42	Exterior	New Britain	Intersection 088-279	se	traffic signal		Metal	Green	Intact	0.1	0.0	1.6	7.3	1/29/2018 13:42
43			0.0 Calibration							0.0	0.0	1.0	2.0	1/29/2018 14:44
44			0.7 Calibration							0.8	0.1	1.1	12.1	1/29/2018 14:45
45			1.6 Calibration							1.5	0.1	1.1	4.8	1/29/2018 14:45
46	Exterior	Meriden	Intersection 079-210	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.3	1/29/2018 14:48
47	Exterior	Meriden	Intersection 079-210	ne	controller cabinet	VOID	Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/29/2018 14:48
49	Exterior	Meriden	Intersection 079-210	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	3.1	3.9	1/29/2018 14:49
50	Exterior	Meriden	Intersection 079-210	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	2.8	20.9	1/29/2018 14:52
51	Exterior	Rocky Hill	Intersection 118-209	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	2.3	8.7	1/29/2018 15:32
52	Exterior	Rocky Hill	Intersection 118-209	ne	signal hood		Metal	Yellow	Intact	0.6	0.2	1.0	2.0	1/29/2018 15:33
53	Exterior	Rocky Hill	Intersection 118-209	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.3	1/29/2018 15:44
54	Exterior	Rocky Hill	Intersection 118-209	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.1	2.8	1/29/2018 15:44
55			0.0 Calibration							0.0	0.0	1.0	2.0	1/29/2018 15:48
56			0.7 Calibration							0.7	0.2	1.1	3.1	1/29/2018 15:48
57			1.6 Calibration							1.6	0.1	1.2	6.5	1/29/2018 15:48
58			Self Calibration										78.3	1/30/2018 11:11
59			0.0 Calibration							0.0	0.0	1.8	2.5	1/30/2018 11:13
60			0.7 Calibration							0.6	0.2	1.0	1.7	1/30/2018 11:14
61			0.3 Calibration							0.3	0.1	1.0	4.3	1/30/2018 11:14
62	Exterior	Wethersfield	int 159-230		light pole		Metal	Grey	Defective	0.0	0.0	1.0	2.3	1/30/2018 11:17
63	Exterior	Wethersfield	int 159-230		light pole		Metal	Grey	Defective	0.0	0.0	1.2	2.5	1/30/2018 11:18
64	Exterior	Wethersfield	int 159-230		ctrl box		Metal	Grey	Defective	0.0	0.0	1.0	3.1	1/30/2018 11:19
65	Exterior	Wethersfield	int 159-230		ctrl box		Metal	Grey	Defective	0.0	0.0	1.0	3.4	1/30/2018 11:19
66	Exterior	East Hartford	int 42-251		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	3.1	1/30/2018 11:59
67	Exterior	East Hartford	int 42-251		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	4.5	1/30/2018 12:01
68	Exterior	East Hartford	int 42-251		light pole		Metal	Grey W Re	Intact	0.0	0.0	2.2	8.5	1/30/2018 12:02
69	Exterior	East Hartford	int 42-251		light pole		Metal	Grey W Re	Intact	0.0	0.0	1.0	1.4	1/30/2018 12:02
70	Exterior	East Hartford	int 42-251		light		Metal	Yellow	Intact	1.1	0.1	1.2	3.9	1/30/2018 12:22
71	Exterior	East Hartford	int 42-251		light		Metal	Yellow	Intact	1.1	0.1	1.2	7.9	1/30/2018 12:23
72	Exterior	East Hartford	int 42-251		light		Metal	Yellow	Intact	1.1	0.1	1.0	6.5	1/30/2018 12:23
73	Exterior	Bloomfield	011-209		span poles		Metal	Grey W Re	Intact	0.1	0.0	1.9	8.2	1/30/2018 13:07
74	Exterior	Bloomfield	011-209		span poles		Metal	Grey W Re	Intact	0.0	0.0	1.3	5.4	1/30/2018 13:07
75	Exterior	Windsor Locks	int 165-213		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/30/2018 13:42
76	Exterior	Windsor Locks	int 165-213		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	3.9	1/30/2018 13:43
77	Exterior	Windsor Locks	int 165-213		light hood	VOID	Metal	Yellow	Intact	0.0	0.0	1.3	3.9	1/30/2018 13:45

Lead paint includes paint found to contain **any detectable** amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise



Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer
 Site: ConnDOT - 1 Traffic Signal Intersection (79-210), Meriden, CT
 Project #: 222165.5706.0710
 Date(s): 1/29/2018
 Inspectors: Zac Smith

Number	Interior/ Exterior	Location	Int No.	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
79	Exterior	Windsor Locks	int 165-213		light hood		Metal	Yellow	Intact	0.0	0.1	1.0	0.3	1/30/2018 13:46
80	Exterior	Windsor Locks	int 165-213		light hood		Metal	Yellow	Intact	0.0	0.0	1.0	1.4	1/30/2018 13:46
81	Exterior	Windsor Locks	int 165-213		light hood		Metal	Black	Intact	0.0	0.0	3.4	10.4	1/30/2018 13:47
82	Exterior	Windsor Locks	int 165-213		light hood		Metal	Black	Intact	0.0	0.0	1.2	1.7	1/30/2018 13:47
83			0.0 Calibration							0.0	0.0	1.0	3.7	1/30/2018 14:11
84			0.7 Calibration							0.7	0.1	1.0	3.7	1/30/2018 14:12
85			0.3 Calibration							0.3	0.1	1.1	5.9	1/30/2018 14:12

Lead paint includes paint found to contain **any detectable** amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side, Sides B,C,D follow clockwise

80 Lupes Drive
Stratford, CT 06615



Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton
TRC Environmental Consultants
21 Griffin Rd., North
Windsor, CT 06095

Analytical Report

CET# 8010759



Report Date: February 02, 2018
Project: DOT, Intersections-Signals
Project Number: 222165.5706.0710

Connecticut Laboratory Certificate: PH 0116
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982
Rhode Island Certification: 199

CET # : 8010759

Project: DOT, Intersections-Signals

Project Number: 222165.5706.0710

SAMPLE SUMMARY

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 079-210 Traffic Signal	8010759-01	Paint Chip	1/29/2018 13:46	01/31/2018
03 Intersection 079-210 Controller Box	8010759-02	Paint Chip	1/29/2018 13:52	01/31/2018

Analyte: Total Lead [EPA 6010C]

Analyst: SS


Matrix: Paint Chip

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010759-01	01 Intersection 079-210 Traffic Signal	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:17	
8010759-02	03 Intersection 079-210 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:22	


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- *C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- *C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- *F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- *F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

.CET # : 8010759

Project: DOT, Intersections-Signals

Project Number: 222165.5706.0710

CERTIFICATIONS

Certified Analyses included in this Report

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018

Complete Environmental Testing, Inc.

80 Lupes Drive, Stratford, CT 06615 • Tel: 203-377-9984 • Fax: 203-377-9952 • www.cetlabs.com

21 GRIFFIN ROAD NORTH

WINDSOR, CONNECTICUT 06095

TELEPHONE (860) 298-9692

FAX (860) 298-6380

TCLP CHAIN OF CUSTODY

LAB ID#:

TURNAROUND TIME

PROJECT NUMBER
222165.5706.0716

PROJECT NAME
DOT Interactions - Signals

PARAMETERS

TURNAROUND TIME					
	24hr	48hr	X	3day	5day
	24hr	48hr	✓	3day	5day

INSPECTOR: (SIGNATURE)

(PRINTED)

(UNFILED)
Zachary Smith

[illegible]

Relinquished by: (Signature)

Date: _____

Received by: (Signature)

277

Relinquished by: (Signature)

1

Received by: (Signature)

(Printed)

Time;

Printed)

(Printed)

--	--

(Printed)

Edgar Smith

1200

01186 612081

GRAB GRADY

CONFIDENTIAL	DATE 05/26/2010
--------------	-----------------

If Total Pb is positive then analyze TELP
Send results to EPA/Region 9 TELC solutions team



SUBJECT ODT-Intersection imp's

SHEET NO. 6 OF 7


PROJECT NO. _____

DATE 1/29/18

BY RM, JS

CHK'D _____

Intersection #: 079-210, Meriden
U.S. Rt 5 @ Westfield Rd & Britannia St



* NO SUSP ACMT *

Project Title: Installation of Traffic Control Signals in District 1

Project Number:

- CN Project Number: 171-401
- PE Project Number: 171-401

Detailed Project Description: Installation of traffic control signals will require excavation of existing equipment as well as excavation for new foundations (span pole, mast arm, pedestal, controller cabinet, etc.) and trenching (i.e. conduit) as required. In addition to excavation for traffic signal equipment, excavation will be required for sidewalk ramps that will be installed or reconstructed to meet current ADA standards. In areas of an excavation where there is existing signal equipment, excavation will take place in areas that have undergone extensive ground disturbance in the past. In areas of an intersection where there is no existing signal equipment, excavation may be in areas where there may not have been extensive ground disturbance in the past. There is significantly less than one acre of disturbance for each location.

Purpose and Need Statement: This project will install new traffic signal equipment, which may include span poles, mast arms, signal heads, span wires, conduits, loops, pedestrian countdown heads, signing and pavement markings, to meet current department standards.

The intersection below consists of new signal equipment being installed at the existing signalized location:

1. Meriden – U.S. Route 5 at Westfield Road and Britannia Street (Int. No. 079-210).

MERIDEN

PROJECT 171-401

U.S. ROUTE 5 AT WESTFIELD ROAD
AND BRITANNIA STREET

INT. 079-210

