



May 4, 2018

Mr. Adam Fox, P.E.  
Principal Engineer  
Environmental Compliance Section  
Bureau of Engineering and Construction  
State of Connecticut Department of Transportation  
2800 Berlin Turnpike, P.O. Box 317546  
Newington, CT 06131-7546

Attention: Jason Coite, P.E. / Mandy Socolosky

Subject: On-Call Asbestos, Lead, Air Quality & Demolition Compliance  
Agreement No. 04.27-01(15)  
HazMat Inspection – Ten (10) District 1 Traffic Signal Intersections, Nine (9) Cities/Towns,  
CT  
ConnDOT Assignment No. 514-5709  
ConnDOT Project No. 171-402  
TRC Project No. 222165.5709.0710

Dear Mr. Fox:

TRC performed a limited survey for hazardous building materials associated with traffic signals and pedestrian control equipment at 10 Traffic Signal Intersection Sites in 9 cities/towns (Bloomfield, Cheshire, East Hartford, New Britain, Plainville, Rocky Hill, Southington, Wethersfield & Windsor Locks) in District 1, Connecticut. Results of the survey identified the following at the traffic signal span poles, mast arms, pedestals, crosswalk signal hoods/push buttons and controller cabinet replacements at the following Intersections:

Traffic Signal Int. No. 011-209, Route 218 at North Drive to CIGNA, Bloomfield

- One span pole was wood (unpainted). Detectable amounts of lead in paint were found on the second grey/red painted metal span pole. There were no pedestrian crosswalk pedestals/hoods. The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. Controller cabinet was unpainted.
- Projected paint waste debris associated with the grey/red painted span pole was characterized as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.

Traffic Signal Int. No. 025-225, Route 10 at Maplecroft Shopping Center, Cheshire

- One span pole was wood (unpainted). No detectable amounts of lead in paint were found on the second grey painted metal span pole. Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. Detectable amount of lead were identified on the yellow crosswalk hoods/push buttons. No detectable amounts of lead were identified on the painted metal controller cabinet.
- Projected paint waste debris associated with the yellow crosswalk hoods/push buttons was characterized as non-hazardous, non-RCRA waste.
- Since no detectable amounts of lead were present on painted metal surfaces of the grey painted

span pole and the controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.

- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.
- Tan brittle caulking at the base of the controller cabinet was sampled and found to be non-ACM.

Traffic Signal Int. No. 042-251, S.R. 502 at Rolling Meadow Drive, East Hartford

- One span pole was wood (unpainted). No detectable amounts of lead in paint were found on the second grey painted metal span pole. Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. Detectable amount of lead were identified on the yellow traffic light on pole. No detectable amounts of lead were identified on painted metal controller cabinet.
- Projected paint waste debris associated with the yellow traffic light on pole was characterized as non-hazardous, non-RCRA waste.
- Since no detectable amounts of lead were present on painted metal surfaces of the grey painted span pole and the controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.

Traffic Signal Int. No. 088-247, Route 71 at Paul J. Manafort Drive & Francis Street, New Britain

- All span poles were galvanized (unpainted). Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. Detectable amounts of lead were identified on the yellow painted crosswalk hoods/push buttons. No detectable amounts of lead in paint were identified on the painted metal controller cabinet.
- Since no detectable amounts of lead were present on the painted metal surfaces of the metal controller cabinet any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves and yellow painted crosswalk hoods/push buttons should be tested for TCLP lead to determine waste disposal.

Traffic Signal Int. No. 088-279, Route 71 at Firehouse Lane, New Britain

- One span pole was wood (unpainted). No detectable amounts of lead in paint were found on the second grey painted metal span pole. There were no pedestrian crosswalk pedestals/hoods. The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. Detectable amount of lead were identified on the black/yellow traffic light on span pole & yellow/green crosswalk push buttons. No detectable amounts of lead were identified on the painted metal controller cabinet.
- Projected paint waste debris associated with the black/yellow traffic light on span pole was characterized as non-hazardous, non-RCRA waste.
- Since no detectable amounts of lead were present on painted metal surfaces of the grey painted span pole and the controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.

- Any paint waste generated from the metal traffic lights themselves and yellow/green crosswalk push buttons should be tested for TCLP lead to determine waste disposal.
- Grey pliable caulking and black fibrous material near controller cabinet were sampled and found to be non-ACM.

Traffic Signal Int. No. 109-201, Route 10 at Whiting Street, Plainville

- All span poles were galvanized (unpainted). There were no pedestrian crosswalk pedestals/hoods. The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. No detectable amounts of lead in paint were identified on the painted metal controller cabinet.
- Since no detectable amounts of lead were present on the painted metal surfaces of the metal controller cabinet any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.

Traffic Signal Int. No. 118-209, Route 99 at Town Line Road, Rocky Hill

- One (1) span pole was galvanized (unpainted) and 1 span pole was wood (unpainted). Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. Detectable amounts of lead paint were found on yellow painted metal surfaces of the crosswalk hoods/push buttons. No detectable amounts of lead in paint were found on the painted metal controller cabinet.
- Since no detectable amounts of lead were present on the painted metal controller cabinet any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves and crosswalk hoods/push buttons should be tested for TCLP lead to determine waste disposal.

Traffic Signal Int. No. 131-233, Route 322 at Interstate 691 WB Off-Ramp, Southington

- No detectable amounts of lead in paint were found on the three (3) grey painted metal span poles. There were no pedestrian crosswalk pedestals/hoods. The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. No detectable amounts of lead were identified on the painted metal controller cabinet.
- Since no detectable amounts of lead were present on painted metal surfaces of the grey painted span poles and the controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.
- Black/grey flexible caulking at the base of the controller cabinet was sampled and found to be non-ACM.

Traffic Signal Int. No. 159-230, Route 175 at Goff Road, Wethersfield

- One span pole was wood (unpainted). No detectable amounts of lead in paint were found on the 2

grey painted metal span poles. Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves and yellow crosswalk push buttons are presently presumed to be lead containing. No detectable amounts of lead in paint was found on the grey painted metal controller cabinet.

- Since no detectable amounts of lead were present on painted metal surfaces of the grey painted span poles and the metal controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves and yellow crosswalk push buttons should be tested for TCLP lead to determine waste disposal.
- Hard white caulking at the base of the controller cabinet was sampled and found to be non-ACM.

Traffic Signal Int. No. 165-213, Route 140 at Route 159 – South Junction, Windsor Locks

- All span poles were galvanized (unpainted). Pedestrian crosswalk pedestals were galvanized (unpainted). The paint associated with the metal traffic lights themselves are presently presumed to be lead containing. No detectable amounts of lead in paint were identified on the yellow/black painted crosswalk hoods, yellow push buttons or painted metal controller cabinet.
- Since no detectable amounts of lead were present on the yellow/black painted crosswalk hoods, yellow push buttons or painted metal controller cabinet, any paint waste generated would be classified as non-hazardous, non-RCRA waste.
- Any paint waste generated from the metal traffic lights themselves should be tested for TCLP lead to determine waste disposal.
- Hard white caulking at the base of the controller cabinet was sampled and found to be non-ACM.

Potential universal waste (UW) and Connecticut Regulated Waste (CRW) items associated with the traffic lights themselves, crosswalk signal hoods/buttons and controller cabinets (i.e. Hg lamps/PCB ballasts and/or printed circuit boards) are also likely present at the Intersection sites.

Laboratory data, inspector notes & project description information are attached.

If you have any questions, please call TRC at (860) 298-9692.


Very Truly Yours,

TRC



Stephen R. Arienti, CHMM  
Senior Project Manager – Program Manager

Reviewed By:



Erik R. Plimpton, P.E., CHMM, CMC  
Vice President – Engineer in Charge



### Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer  
 Site: ConnDOT - 10 District 1 Traffic Signal Intersections, Statewide  
 Project #: 222165.5709.0710  
 Date(s): 1/29/2018 & 1/30/2018  
 Inspectors: Zac Smith & Eric Gitberg

Number	Interior/ Exterior	Location	Int No.	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm <sup>2</sup> )	Precision (mg/cm <sup>2</sup> )	Depth Index	Duration (sec)	Date/Time
1			Self Calibration										80.1	1/29/2018 10:13
2			0.0 Calibration							0.0	0.0	1.8	2.0	1/29/2018 10:15
3			0.7 Calibration							0.7	0.1	1.0	3.4	1/29/2018 10:15
4			1.6 Calibration							1.4	0.1	1.0	5.1	1/29/2018 10:15
5						VOID								
6						VOID								
7	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	0.1	0.2	5.0	2.0	1/29/2018 10:18
8	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	0.1	0.1	3.4	2.8	1/29/2018 10:18
9						VOID								
10						VOID								
11						VOID								
12						VOID								
13	Exterior	Cheshire	intersection 25-225	ne	signal hood		Metal	Yellow	Intact	0.9	0.1	1.1	4.2	1/29/2018 10:22
14	Exterior	Cheshire	intersection 25-225	ne	signal hood		Metal	Yellow	Intact	0.9	0.2	1.1	2.6	1/29/2018 10:22
15	Exterior	Cheshire	intersection 25-225	ne	signal hood		Metal	Yellow	Intact	0.9	0.1	1.1	4.2	1/29/2018 10:23
16	Exterior	Cheshire	intersection 25-225	ne	push to cross		Metal	Yellow	Intact	0.0	0.0	1.5	3.7	1/29/2018 10:24
17	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	0.1	0.0	3.1	22.3	1/29/2018 10:28
18	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Yellow	Intact	1.0	0.1	1.1	20.7	1/29/2018 10:29
19						VOID								
20	Exterior	Cheshire	intersection 25-225	nw	signal hood		Metal	Black	Intact	0.1	0.0	3.0	21.2	1/29/2018 10:31
21	Exterior	Cheshire	intersection 25-225	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/29/2018 10:35
22	Exterior	Cheshire	intersection 25-225	ne	span pole		Metal	Grey	Intact	0.0	0.0	1.0	7.6	1/29/2018 10:37
23						VOID								
24	Exterior	Southington	intersection 131-233	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.9	4.2	1/29/2018 11:14
25	Exterior	Southington	intersection 131-233	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	2.5	3.7	1/29/2018 11:14
26	Exterior	Southington	intersection 131-233	ne	span pole		Metal	Grey	Intact	0.0	0.0	2.0	4.2	1/29/2018 11:15
27	Exterior	Southington	intersection 131-233	nw	span pole		Metal	Grey	Intact	0.0	0.0	1.0	2.6	1/29/2018 11:16
28	Exterior	Southington	intersection 131-233	se	span pole		Metal	Grey	Intact	0.0	0.0	1.0	1.7	1/29/2018 11:17
29	Exterior	Plainville	intersection 109-201	e	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	3.4	1/29/2018 11:56
30	Exterior	Plainville	intersection 109-201	e	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.5	1/29/2018 11:56
31	Exterior	New Britain	intersection 088-247	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.5	1/29/2018 12:23
32	Exterior	New Britain	intersection 088-247	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	3.1	1/29/2018 12:23
33	Exterior	New Britain	intersection 088-247	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	1.9	6.8	1/29/2018 12:27
34	Exterior	New Britain	intersection 088-247	ne	signal hood		Metal	Yellow	Intact	1.2	0.1	1.1	5.4	1/29/2018 12:27
35	Exterior	New Britain	intersection 088-247	se	signal hood		Metal	Yellow	Intact	0.0	0.0	2.3	4.8	1/29/2018 12:28
36	Exterior	New Britain	intersection 088-279	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.1	2.5	1/29/2018 13:29
37	Exterior	New Britain	intersection 088-279	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	3.7	1/29/2018 13:29
38	Exterior	New Britain	intersection 088-279	se	span pole		Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/29/2018 13:32
39	Exterior	New Britain	intersection 088-279	se	span pole		Metal	Grey	Intact	0.0	0.0	1.3	4.5	1/29/2018 13:32
40	Exterior	New Britain	intersection 088-279	se	push to cross sign		Metal	Green	Intact	0.1	0.2	4.8	2.5	1/29/2018 13:39

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise



### Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer  
 Site: ConnDOT - 10 District 1 Traffic Signal Intersections, Statewide  
 Project #: 22165.5709.0710  
 Date(s): 1/29/2018 & 1/30/2018  
 Inspectors: Zac Smith & Eric Gitberg

Number	Interior/ Exterior	Location	Int No.	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm <sup>2</sup> )	Precision (mg/cm <sup>2</sup> )	Depth Index	Duration (sec)	Date/Time
41	Exterior	New Britain	intersection 088-279	se	push to cross sign		Metal	Green	Intact	0.0	0.0	1.0	4.0	1/29/2018 13:40
42	Exterior	New Britain	intersection 088-279	se	traffic signal		Metal	Green	Intact	0.1	0.0	1.6	7.3	1/29/2018 13:42
43			0.0 Calibration							0.0	0.0	1.0	2.0	1/29/2018 14:44
44			0.7 Calibration							0.8	0.1	1.1	12.1	1/29/2018 14:45
45			1.6 Calibration							1.5	0.1	1.1	4.8	1/29/2018 14:45
46	Exterior	Meriden	intersection 079-210	ne	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.3	1/29/2018 14:48
47	Exterior	Meriden	intersection 079-210	ne	controller cabinet	VOID	Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/29/2018 14:48
49	Exterior	Meriden	intersection 079-210	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	3.1	3.9	1/29/2018 14:49
50	Exterior	Meriden	intersection 079-210	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	2.8	20.9	1/29/2018 14:52
51	Exterior	Rocky Hill	intersection 118-209	ne	signal hood		Metal	Yellow	Intact	0.0	0.0	2.3	8.7	1/29/2018 15:32
52	Exterior	Rocky Hill	intersection 118-209	ne	signal hood		Metal	Yellow	Intact	0.6	0.2	1.0	2.0	1/29/2018 15:33
53	Exterior	Rocky Hill	intersection 118-209	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.0	2.3	1/29/2018 15:44
54	Exterior	Rocky Hill	intersection 118-209	sw	controller cabinet		Metal	Grey	Intact	0.0	0.0	1.1	2.8	1/29/2018 15:44
55			0.0 Calibration							0.0	0.0	1.0	2.0	1/29/2018 15:48
56			0.7 Calibration							0.7	0.2	1.1	3.1	1/29/2018 15:48
57			1.6 Calibration							1.6	0.1	1.2	6.5	1/29/2018 15:48
58			Self Calibration										78.3	1/30/2018 11:11
59			0.0 Calibration							0.0	0.0	1.8	2.5	1/30/2018 11:13
60			0.7 Calibration							0.6	0.2	1.0	1.7	1/30/2018 11:14
61			0.3 Calibration							0.3	0.1	1.0	4.3	1/30/2018 11:14
62	Exterior	Wethersfield	int 159-230		span pole		Metal	Grey	Defective	0.0	0.0	1.0	2.3	1/30/2018 11:17
63	Exterior	Wethersfield	int 159-230		span pole		Metal	Grey	Defective	0.0	0.0	1.2	2.5	1/30/2018 11:18
64	Exterior	Wethersfield	int 159-230		ctrl box		Metal	Grey	Defective	0.0	0.0	1.0	3.1	1/30/2018 11:19
65	Exterior	Wethersfield	int 159-230		ctrl box		Metal	Grey	Defective	0.0	0.0	1.0	3.4	1/30/2018 11:19
66	Exterior	East Hartford	int 42-251		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	3.1	1/30/2018 11:59
67	Exterior	East Hartford	int 42-251		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	4.5	1/30/2018 12:01
68	Exterior	East Hartford	int 42-251		span pole		Metal	Grey W Red	Intact	0.0	0.0	2.2	8.5	1/30/2018 12:02
69	Exterior	East Hartford	int 42-251		span pole		Metal	Grey W Red	Intact	0.0	0.0	1.0	1.4	1/30/2018 12:02
70	Exterior	East Hartford	int 42-251		light		Metal	Yellow	Intact	1.1	0.1	1.2	3.9	1/30/2018 12:22
71	Exterior	East Hartford	int 42-251		light		Metal	Yellow	Intact	1.1	0.1	1.2	7.9	1/30/2018 12:23
72	Exterior	East Hartford	int 42-251		light		Metal	Yellow	Intact	1.1	0.1	1.0	6.5	1/30/2018 12:23
73	Exterior	Bloomfield	011-209		span poles		Metal	Grey W Red	Intact	0.1	0.0	1.9	8.2	1/30/2018 13:07
74	Exterior	Bloomfield	011-209		span poles		Metal	Grey W Red	Intact	0.0	0.0	1.3	5.4	1/30/2018 13:07
75	Exterior	Windsor Locks	int 165-213		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	2.8	1/30/2018 13:42
76	Exterior	Windsor Locks	int 165-213		ctrl box		Metal	Grey	Intact	0.0	0.0	1.0	3.9	1/30/2018 13:43
77	Exterior	Windsor Locks	int 165-213		light hood	VOID	Metal	Yellow	Intact	0.0	0.0	1.3	3.9	1/30/2018 13:45
78														
79	Exterior	Windsor Locks	int 165-213		light hood		Metal	Yellow	Intact	0.0	0.1	1.0	0.3	1/30/2018 13:46
80	Exterior	Windsor Locks	int 165-213		light hood		Metal	Yellow	Intact	0.0	0.0	1.0	1.4	1/30/2018 13:46

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).



## Lead Based Paint Measurement Summary Table

**Device(s):** Niton XLP301-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer  
**Site:** ConnDOT - 10 District 1 Traffic Signal Intersections, Statewide  
**Project # :** 222165.5709.0710  
**Date(s):** 1/29/2018 & 1/30/2018  
**Inspectors:** Zac Smith & Eric Gitberg

Number	Interior/ Exterior	Location	Int No.	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm <sup>2</sup> )	Precision (mg/cm <sup>2</sup> )	Depth Index	Duration (sec)	Date/Time
81	Exterior	Windsor Locks	Int 165-213		light hood		Metal	Black	Intact	0.0	0.0	3.4	10.4	1/30/2018 13:47
82	Exterior	Windsor Locks	Int 165-213		light hood		Metal	Black	Intact	0.0	0.0	1.2	1.7	1/30/2018 13:47
83			0.0 Calibration							0.0	0.0	1.0	3.7	1/30/2018 14:11
84			0.7 Calibration							0.7	0.1	1.0	3.7	1/30/2018 14:12
85			0.3 Calibration							0.3	0.1	1.1	5.9	1/30/2018 14:12

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

## Analytical Report

### CET# 8010766



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199



CET # : 8010766  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 011-209 Span Pole	8010766-01	Paint Chip	1/30/2018 12:10	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010766-01	01 Intersection 011-209 Span Pole	<b>0.24</b>	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:58	

CET # : 8010766


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010766  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018



80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8020044



Report Date: February 07, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8020044

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
02 Intersection 011-209 Span Pole	8020044-01	Paint Chip	1/30/2018 12:12	01/31/2018

**Analyte: TCLP Lead [EPA 6020A]**

**Analyst: CED**

**Prep: EPA 3005A-1311**

**Matrix: Extract**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8020044-01	02 Intersection 011-209 Span Pole	<b>0.89</b>	0.013	mg/L	1	B8B0613	02/06/2018	02/06/2018 17:17	

CET # : 8020044


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8020044

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6020A in Water</i>	
Lead	NY,CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018
NY	New York Certification (NELAC)	11982	04/01/2018





80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010767



Report Date: February 05, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010767

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Interseccion 025-225 Controller Box	8010767-01	Paint Chip	1/29/2018 9:36	01/31/2018
03 Interseccion 025-225 Span Pole	8010767-02	Paint Chip	1/29/2018 9:41	01/31/2018
05 Interseccion 025-225 Traffic Signal	8010767-03	Paint Chip	1/29/2018 9:30	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010767-01	01 Interseccion 025-225 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:10	
8010767-02	03 Interseccion 025-225 Span Pole	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:15	

**Analyte: TCLP Lead [EPA 6020A]**

**Analyst: CED**

**Prep: EPA 3005A-1311**

**Matrix: Extract**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010767-03	05 Interseccion 025-225 Traffic Signal	<b>4.3</b>	0.013	mg/L	1	B8B0216	02/02/2018	02/02/2018 16:25	

CET # : 8010767


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Robert Blake



David Ditta  
Laboratory Director

Project Manager

Report Comments:

Sample Result Flags:

E- The result is estimated, above the calibration range.

H- The surrogate recovery is above the control limits.

L- The surrogate recovery is below the control limits.

B- The compound was detected in the laboratory blank.

P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.

D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.

+ - The Surrogate was diluted out.

\*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.

\*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.

\*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.

\*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.

I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010767

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT
<i>EPA 6020A in Water</i>	
Lead	NY,CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018
NY	New York Certification (NELAC)	11982	04/01/2018



21 GRIFFIN ROAD NORTH

WINDSOR, CONNECTICUT 06095

TELEPHONE (860) 298-9692

FAX (860) 298-6380

### TCLP CHAIN OF CUSTODY

025-225



8010767

Edition: November 2013  
Supersede Previous Edition

PROJECT NUMBER 222145.5709.0710	PROJECT NAME DOT Intersections - Signs	PARAMETERS	TURNAROUND TIME				
INSPECTOR: (SIGNATURE) <i>[Signature]</i>	(PRINTED) Zachary Smith		24hr	48hr	3day	5day	

FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	PARAMETERS					MATERIAL	
			COMP	GRAB		RCRA Pb	RCRA Pb, AS, CR, CD	8 RCRA Metals	TCLP Pb	SPLP Pb		Total Pb
01	1/29/18	0936	X		Intersection 025-225 Curbside box						X	Grey paint
02		0935	X		"						X	"
03		0944	X		Intersection 025-225 Sign Pole						X	Grey paint with red undercoat
04		0940	X		"						X	"
05		0930	X		Intersection 025-225 Traffic Signal						X	yellow paint

Relinquished by: (Signature) <i>[Signature]</i>	Date: 1/31/18	Received by: (Signature) <i>[Signature]</i>	Relinquished by: (Signature) <i>[Signature]</i>	Date: 1/31/18	Received by: (Signature) <i>[Signature]</i>
(Printed) Zachary Smith	Time: 1200	(Printed) CAROL GILMAN	(Printed) CAROL GILMAN	Time: 1525	(Printed) Catherine

IF Total Pb is positive then analyze TCLP and send results to EPI@otrc.com

80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010764



Report Date: February 05, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010764

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 042-251 Span Pole	8010764-01	Paint Chip	1/30/2018 11:41	01/31/2018
03 Intersection 042-251 Controller Box	8010764-02	Paint Chip	1/30/2018 11:31	01/31/2018
05 Intersection 042-251 Traffic Signal	8010764-03	Paint Chip	1/30/2018 11:30	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010764-01	01 Intersection 042-251 Span Pole	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:49	
8010764-02	03 Intersection 042-251 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:53	

**Analyte: TCLP Lead [EPA 6020A]**

**Analyst: CED**

**Prep: EPA 3005A-1311**

**Matrix: Extract**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010764-03	05 Intersection 042-251 Traffic Signal	4.4	0.013	mg/L	1	B8B0216	02/02/2018	02/02/2018 16:20	



CET # : 8010764


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Robert Blake



David Ditta  
Laboratory Director

Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010764

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

CERTIFICATIONS

Certified Analyses included in this Report

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT
<i>EPA 6020A in Water</i>	
Lead	NY,CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018
NY	New York Certification (NELAC)	11982	04/01/2018



21 GRIFFIN ROAD NORTH  
WINDSOR, CONNECTICUT 06095  
TELEPHONE (860) 298-9692  
FAX (860) 298-6380

### TCLP CHAIN OF CUSTODY

042-251



8010764

Edition: November 2013  
Supersede Previous Edition

LAB ID #

TURNAROUND TIME

24hr	48hr	3day	5day
		X	
24hr	48hr	3day	5day
		X	

PROJECT NAME

DOT Intersections - Signals

PARAMETERS

RCRA Pb	RCRA Pb, AS, CR, CD	8 RCRA Metals	TCLP Pb	SPLP Pb	Total Pb

INSPECTOR: (SIGNATURE)

*[Signature]*

(PRINTED)

Zachary Smith

MATERIAL

FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	RCRA Pb	RCRA Pb, AS, CR, CD	8 RCRA Metals	TCLP Pb	SPLP Pb	Total Pb	MATERIAL
			COMP	GRAB								
01	11/30/14	1141	X		Intersection 042-251 Spout pole				X		X	gray paint with rd undercoat
02		1140	X						X		X	"
03		1131	X		Intersection 042-251 Corralter Box				X		X	gray paint
04		1130	X						X		X	"
05		1130	X		Intersection 042-251 Traffic Signal				X		X	yellow paint
												"

Relinquished by: (Signature)

*[Signature]*

Date:

11/31/14

Received by: (Signature)

*[Signature]*

Date:

22

Relinquished by: (Signature)

*[Signature]*

Date:

11/31/14

Received by: (Signature)

*[Signature]*

(Printed)

Zachary Smith

Time:

1200

(Printed)

GNAC GUNDA

(Printed)

GNAC GUNDA

Time:

1525

(Printed)

COURNEY GUNDA

IF Total Pb is positive then analyze TCLP Send results to EPlumph@TRCSolutions.com

80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010769



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010769

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 088-247 Traffic Signal	8010769-01	Paint Chip	1/29/2018 11:25	01/31/2018
03 Intersection 088-247 Controller Box	8010769-02	Paint Chip	1/29/2018 11:30	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010769-01	01 Intersection 088-247 Traffic Signal	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:36	
8010769-02	03 Intersection 088-247 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:46	

CET # : 8010769


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

E- The result is estimated, above the calibration range.

H- The surrogate recovery is above the control limits.

L- The surrogate recovery is below the control limits.

B- The compound was detected in the laboratory blank.

P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.

D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.

+ - The Surrogate was diluted out.

\*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.

\*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.

\*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.

\*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.

I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010769

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

<b>Analyte</b>	<b>Certifications</b>
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

<b>Code</b>	<b>Description</b>	<b>Number</b>	<b>Expires</b>
CT	Connecticut Public Health	PH0116	09/30/2018





80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010768



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010768

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 088-279 Controller Box	8010768-01	Paint Chip	1/29/2018 13:15	01/31/2018
03 Intersection 088-279 Span Pole	8010768-02	Paint Chip	1/29/2018 13:10	01/31/2018
05 Intersection 088-279 Traffic Signal	8010768-03	Paint Chip	1/29/2018 13:05	01/31/2018
07 Intersection 088-279 Traffic Signal	8010768-04	Paint Chip	1/29/2018 13:01	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010768-01	01 Intersection 088-279 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:19	
8010768-02	03 Intersection 088-279 Span Pole	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:23	
8010768-03	05 Intersection 088-279 Traffic Signal	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:27	
8010768-04	07 Intersection 088-279 Traffic Signal	<b>0.11</b>	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:32	

CET #: 8010768


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

E- The result is estimated, above the calibration range.

H- The surrogate recovery is above the control limits.

L- The surrogate recovery is below the control limits.

B- The compound was detected in the laboratory blank.

P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.

D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.

+ - The Surrogate was diluted out.

\*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.

\*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.

\*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.

\*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.

I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010768

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018



21 GREEN ROAD NORTH  
WINDSOR, CONNECTICUT 06095

TELEPHONE (860) 298-9692  
FAX (860) 298-6380

### TCLP CHAIN OF CUSTODY



8010768

Edition: November 2013  
Supersede Previous Edition

PROJECT NUMBER  
222165.5709.0710

PROJECT NAME  
DOT Intersections - Signals

INSPECTOR: (SIGNATURE)  
*Zedny Smith*

INSPECTOR: (PRINTED)  
Zedny Smith

PARAMETERS

LAB ID #

TURNAROUND TIME

24hr	48hr	72hr	96hr	120hr
	X	X	X	X

FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	RCRA Pb	RCRA Pb, AS, CR, CD	8 RCRA Metals	TCLP Pb	SPLP Pb	Total Pb	MATERIAL
			COMP	GRAB								
01	1/29/18	1315	X		Intersection 088-279 Corbiller box				X		X	Grey Paint
02	1/29/18	1316	X		"				X		X	"
03	1/29/18	1310	X		Intersection 088-279 Spinn Pole				X		X	Grey paint with red undercoat
04	1/29/18	1312	X		"				X		X	"
05	1/29/18	1305	X		Intersection 088-279 traffic signal				X		X	Yellow Paint
06	1/29/18	1303	X		"				X		X	"
07	1/29/18	1301	X		Intersection 088-279 traffic signal				X		X	Black Paint
08	1/29/18	1300	X		"				X		X	"

Relinquished by: (Signature) <i>Zedny Smith</i>	Date: 1/31/18	Received by: (Signature) <i>[Signature]</i>	Date: 2/20	Relinquished by: (Signature) <i>[Signature]</i>	Date: 1/31/18	Received by: (Signature) <i>[Signature]</i>
(Printed) Zedny Smith	Time: 1200	(Printed) GARC GILMAY		(Printed) GARC GILMAY	Time: 1525	(Printed) GARC GILMAY

If total Pb is positive then analyze TCLP

Send results to [Epiliphon@TRCSolutions.com](mailto:Epiliphon@TRCSolutions.com)

80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8020054



Report Date: February 07, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8020054

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
08 Intersection 088-279 Traffic Signal	8020054-01	Paint Chip	1/29/2018 13:00	01/31/2018

**Analyte: TCLP Lead [EPA 6020A]**

**Analyst: CED**

**Prep: EPA 3005A-1311**

**Matrix: Extract**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8020054-01	08 Intersection 088-279 Traffic Signal	0.78	0.013	mg/L	1	B8B0613	02/06/2018	02/06/2018 17:22	

CET # : 8020054


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.



CET # : 8020054

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6020A in Water</i>	
Lead	NY,CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018
NY	New York Certification (NELAC)	11982	04/01/2018



21 GREEN ROAD NORTH  
WINDSOR, CONNECTICUT 06095

TELEPHONE (860) 298-9692

FAX (860) 298-6380

### TCLP CHAIN OF CUSTODY



8020054

Edition: November 2013  
Supersede Previous Edition

LAB ID #

TURNAROUND TIME

24hr	48hr	72hr	96hr	120hr
		X		
24hr	48hr	X	3day	5day

PROJECT NAME

DOT Intersections - Signals

PROJECT NUMBER

222115.5709.0710

INSPECTOR: (SIGNATURE)

(PRINTED)

Zachary Smith

FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	PARAMETERS					MATERIAL		
			COMP	GRAB		RCRA Pb	RCRA Pb, AS, CR, CD	8 RCRA Metals	TCLP Pb	SPLP Pb		Total Pb	
01	1/29/18	1315	X		Intersection 088-279 Condolet box							X	Grey Paint
02	1/29/18	1316	X		"				X				"
03	1/29/18	1310	X		Intersection 088-279 Sporn Ave							X	Grey paint with red undercoat
04	1/29/18	1312	X		"				X				"
05	1/29/18	1305	X		Intersection 088-279 traffic signal							X	Yellow Paint
06	1/29/18	1303	X		"				X				"
07	1/29/18	1301	X		Intersection 088-279 traffic signal							X	Black Paint
08	1/29/18	1300	X		"				X				"

Relinquished by: (Signature)

Date: 1/31/18

Time: 1200

Received by: (Signature)

Date: 2/20

Time: 1200

Relinquished by: (Signature)

Date: 1/31/18

Time: 1515

Received by: (Signature)

If total Pb is positive then analyze TCLP Send results to [EMPH@CTRC-Solutions.com](mailto:EMPH@CTRC-Solutions.com)

80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010771



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET# : 8010771

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 109-201 Controller Box	8010771-01	Paint Chip	1/29/2018 10:40	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010771-01	01 Intersection 109-201 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 19:07	

CET #: 8010771


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET #: 8010771

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018



80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010762



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199



CET # : 8010762

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 118-209 Signal Hood	8010762-01	Paint Chip	1/29/2018 14:36	01/31/2018
03 Intersection 118-209 Controller Box	8010762-02	Paint Chip	1/29/2018 14:46	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010762-01	01 Intersection 118-209 Signal Hood	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:39	
8010762-02	03 Intersection 118-209 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:44	

CET # : 8010762


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

E- The result is estimated, above the calibration range.

H- The surrogate recovery is above the control limits.

L- The surrogate recovery is below the control limits.

B- The compound was detected in the laboratory blank.

P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.

D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.

+ - The Surrogate was diluted out.

\*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.

\*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.

\*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.

\*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.

I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010762  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018



80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010772



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010772

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 131-233 Span Pole	8010772-01	Paint Chip	1/29/2018 10:17	01/31/2018
03 Intersection 131-233 Controller Box	8010772-02	Paint Chip	1/29/2018 10:12	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010772-01	01 Intersection 131-233 Span Pole	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 19:11	
8010772-02	03 Intersection 131-233 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 19:16	

CET # : 8010772


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8016772  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018





80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010770



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010770

Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 159-230 Span Pole	8010770-01	Paint Chip	1/30/2018 10:30	01/31/2018
03 Intersection 159-230 Controller Cabinet	8010770-02	Paint Chip	1/30/2018 10:40	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010770-01	01 Intersection 159-230 Span Pole	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 18:50	
8010770-02	03 Intersection 159-230 Controller Cabinet	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 19:03	

CET #: 8010770


Project: DOT, Intersections-Signals

Project Number: 222165.5709.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- \*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- \*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- \*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- \*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8010770  
Project: DOT, Intersections-Signals  
Project Number: 222165.5709.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018



80 Lupes Drive  
Stratford, CT 06615



Tel: (203) 377-9984  
Fax: (203) 377-9952  
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton  
TRC Environmental Consultants  
21 Griffin Rd., North  
Windsor, CT 06095

# Analytical Report

## CET# 8010760



Report Date: February 02, 2018  
Project: DOT, Intersections-Signals  
Project Number: 222165.5706.0710

Connecticut Laboratory Certificate: PH 0116  
Massachusetts laboratory Certificate: M-CT903



New York NELAP Accreditation: 11982  
Rhode Island Certification: 199

CET # : 8010760

Project: DOT, Intersections-Signals

Project Number: 222165.5706.0710

**SAMPLE SUMMARY**

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Intersection 165-213 Controller Box	8010760-01	Paint Chip	1/30/2018 12:56	01/31/2018
03 Intersection 165-213 Traffic Signal	8010760-02	Paint Chip	1/30/2018 13:01	01/31/2018
05 Intersection 165-213 Traffic Signal	8010760-03	Paint Chip	1/30/2018 13:06	01/31/2018

**Analyte: Total Lead [EPA 6010C]**

**Analyst: SS**

**Matrix: Paint Chip**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8010760-01	01 Intersection 165-213 Controller Box	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:26	
8010760-02	03 Intersection 165-213 Traffic Signal	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:30	
8010760-03	05 Intersection 165-213 Traffic Signal	ND	0.10	%	1	B8B0130	02/01/2018	02/01/2018 17:35	



CET #: 8010760

Project: DOT, Intersections-Signals

Project Number: 222165.5706.0710


All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta  
Laboratory Director



Project Manager

Report Comments:

Sample Result Flags:

E- The result is estimated, above the calibration range.

H- The surrogate recovery is above the control limits.

L- The surrogate recovery is below the control limits.

B- The compound was detected in the laboratory blank.

P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.

D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.

+ - The Surrogate was diluted out.

\*C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.

\*C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.

\*F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.

\*F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.

I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET #: 8010760  
Project: DOT, Intersections-Signals  
Project Number: 222165.5706.0710

**CERTIFICATIONS**

**Certified Analyses included in this Report**

Analyte	Certifications
<i>EPA 6010C in Solid</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2018



21 GRIFFIN ROAD NORTH

WINDSOR, CONNECTICUT 06095

TELEPHONE (860) 298-9692

FAX (860) 298-6380

165-213



8010760

Edition: November 2013  
Supersede Previous Edition

# TCLP CHAIN OF CUSTODY

PROJECT NUMBER

222145-5709-0710

PROJECT NAME

DOT Intersections - Signals

PARAMETERS

RCRA Pb

RCRA Pb, AS, CR, CD

8 RCRA Metals

TCLP Pb

SPLP Pb

Total Pb

LAB ID #

TURNAROUND TIME

INSPECTOR: (SIGNATURE)

*[Signature]*

(PRINTED)

Zakary Smith

MATERIAL

FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	RCRA Pb	RCRA Pb, AS, CR, CD	8 RCRA Metals	TCLP Pb	SPLP Pb	Total Pb	MATERIAL
			COMP	GRAB								
01	1/30/18	1256	X		Intersection 165-213 Conductor Box						X	grey paint
02		1255	X		"						X	black paint
03		1301	X		Intersection 165-213 Traffic Signal				X		X	black paint
04		1300	X		"				X		X	"
05		1306	X		Intersection 165-213 Traffic Signal						X	yellow paint
06		1305	X		"				X		X	"

Relinquished by: (Signature)

*[Signature]*

Date:

1/31/18

Received by: (Signature)

*[Signature]*

Relinquished by: (Signature)

*[Signature]*

Date:

1/31/18

Received by: (Signature)

*[Signature]*

(Printed)

Zakary Smith

Time:

1200

(Printed)

GREG GILMAN

(Printed)

GREG GILMAN

Time:

1515

(Printed)

COURNEY CATHARON

If Total Pb is positive then analyze TLLP

Send results to EPI@trcinc.com

Page 1 of 1





**BULK ASBESTOS ANALYSIS REPORT**

CLIENT: CT Department of Transportation

Lab Log #: 0051888  
Project #: 222165.5709.0710  
Date Received: 01/30/2018  
Date Analyzed: 02/01/2018

Site: Intersection Inspection #025-225, Cheshire, CT

**POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116**

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
1	Tan/Colorless (caulk)	Yes	No	--	---	ND	None
2	Tan/Colorless (caulk)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%  
ND - asbestos was not detected  
Trace - asbestos was observed at level of less than 1%  
NA/PS - Not Analyzed / Positive Stop  
SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: K. Williamson Reviewed by: Cathryn Lemire Date Issued: 02/01/2018  
Kathleen Williamson, Laboratory Manager Cathryn Lemire, Approved Signatory

**TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS**

NVLAP Lab Code 101424-0 AIHA-LAP,LLC #100122 CT #PH-0426 ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV#LT000411  
RI #AAL-007 TX #300354 VT #AL014538 LA#05011 VA #3333 000283 AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907  
CO# AL-15020 PHIL# 461 PA#68-03387



# ProScience Analytical Services, Inc.

22 Cummings Park, Woburn, Massachusetts 01801  
 781-935-3212 ~ Fax: 781-932-4857 ~ E-Mail: general@proscience.net

# Laboratory Report

Client Project #: 222165.5709.0710  
 Client Reference: CT DOT - Intersection, Cheshire, CT  
 PO #: N/A  
 Client #: 297  
 Client Name: TRC Environmental Corp. (CT)

Batch: NT 17035  
 Method: NOB  
 Date Received: 2/2/2018  
 Date Analyzed: 2/6/2018  
 Date of Report: 2/6/2018

LAB ID	Field ID	Description:	Color	Initial Weight	% Asbestos Types				% Other Non-asb.	% Organic	% Carb.	Total % Asbestos	Analyzed / Charged	Preped / Charged
					CHR	AMO	ACT	CRO						
NT128594	2	Tan Brittle Control Box Caulk		.0681	.00	.00	.00	.00	.44	99.56	.00	ND	Yes	No

**Comments:**

Key: CHR = Chrysotile AMO = Amosite CRO = Crocidolite ACT = Actinolite TRE = Tremolite ANT = Anthophyllite TR = Trace = < 1% ND = None Detected

  
 Mark Derosier, Analyst





**BULK ASBESTOS ANALYSIS REPORT**

CLIENT: CT Department of Transportation

Lab Log #: 0051886  
 Project #: 222165.5709.0710  
 Date Received: 01/30/2018  
 Date Analyzed: 02/01/2018

Site: Intersection Inspection #088-279, New Britain, CT

**POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116**

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
1	Black/Grey (caulk)	Yes	No	--	10% cellulose	ND	None
2	Black/Grey (caulk)	Yes	No	--	10% cellulose	ND	None
3	Black (fibrous material)	Yes	No	--	60% cellulose	ND	None
4	Black (fibrous material)	Yes	No	--	60% cellulose	ND	None

Reporting limit- asbestos present at 1%  
 ND - asbestos was not detected  
 Trace - asbestos was observed at level of less than 1%  
 NA/PS - Not Analyzed / Positive Stop  
 SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: K. Williamson Reviewed by: Cathryn Lemire Date Issued: 02/01/2018  
 Kathleen Williamson, Laboratory Manager Cathryn Lemire, Approved Signatory

**TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS**

NVLAP Lab Code 101424-0 AIHA-LAP, LLC #100122 CT #PH-0426 ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV# LT000411  
 RI #AAL-007 TX #300354 VT #AL014538 LA#05011 VA #3333 000283 AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907  
 CO# AL-15020 PHIL# 461 PA#68-03387



# ProScience Analytical Services, Inc.

22 Cummings Park, Woburn, Massachusetts 01801  
 781-935-3212 ~ Fax: 781-932-4857 ~ E-Mail: general@proscience.net

## Laboratory Report

Client Project #: 222165.5709.0710  
 Client Reference: CT DOT - Intersection, New Britain, CT  
 PO #: C222165  
 Client #: 297  
 Client Name: TRC Environmental Corp. (CT)

Batch: NT 17036  
 Method: NOB  
 Date Received: 2/2/2018  
 Date Analyzed: 2/6/2018  
 Date of Report: 2/6/2018

LAB ID	Field ID	Description:	Color	Initial Weight	% Asbestos Types					% Other Non-asp.	% Organic	% Carb.	Total % Asbestos	Analyzed / Charged	Preped / Charged
					CHR	AMO	ACT	CRO	ANT						
NT128595	2	Black/Grey Flexible Caulk		.2661	.00	.00	.00	.00	.00	.00	21.27	41.45	ND	Yes	No

**Comments:**

Key: CHR = Chrysotile AMO = Amosite CRO = Crocidolite ACT = Actinolite TRE = Tremolite ANT = Anthophyllite TR = Trace = < 1% ND = None Detected

  
 Mark Derosier, Analyst



21 GRIFFIN ROAD NORTH  
 WINDSOR, CONNECTICUT 06095  
 TELEPHONE (860) 298-9692  
 FAX (860) 298-6380

## ASBESTOS BULK SAMPLING CHAIN OF CUSTODY

Edition: October 2009  
 Supersedes Previous Edition

LAB ID #: 51887

PROJECT NUMBER 222165-5709-0710		PROJECT NAME CTDOT - Intersection Inspection Southington, CT		PARAMETERS					TURNAROUND TIME								
				PLM EPA 600/R93/116 (POSITIVE STOP)	PLM EPA 600/R93/116 (w/ gravimetric reduction) (POSITIVE STOP)	ANALYZE BY LAYER	POINT COUNT (IF >1% & <10%)	TEM NY NOB 1984 (IF PLM SERIES NEG)	PLM:	8hr	24hr	48hr	3day	TEM:	24hr	48hr	3day
SIGNATURE <i>Tom Martin</i>		INSPECTOR Tom Martin		MATERIAL													
FIELD SAMPLE NUMBER	DATE	TIME	TYPE		SAMPLE LOCATION	PLM EPA 600/R93/116 (POSITIVE STOP)	PLM EPA 600/R93/116 (w/ gravimetric reduction) (POSITIVE STOP)	ANALYZE BY LAYER	POINT COUNT (IF >1% & <10%)	TEM NY NOB 1984 (IF PLM SERIES NEG)							
			COMP	GRAB							8hr	24hr	48hr	3day	5day		
1	1/29/18	1020			Southington, Intersection #:131-233	X											
2	1/29/18	1021			Southington, Intersection #:131-233	X			X								

Relinquished by: (Signature) <i>Tom Martin</i> (Printed) Tom Martin	Date: 1/30/18 Time: 0933	Received by: (Signature) <i>Cathryn Lemire</i> (Printed) Cathryn Lemire	Date: 1/30/18 Time: 1030	Relinquished by: (Signature) (Printed)	Date: Time:	Received by: (Signature) (Printed)
Remarks:				Condition of Samples: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		
				Comments:		



**BULK ASBESTOS ANALYSIS REPORT**

CLIENT: CT Department of Transportation

Lab Log #: 0051887  
 Project #: 222165.5709.0710  
 Date Received: 01/30/2018  
 Date Analyzed: 02/01/2018

Site: Intersection Inspection #131-233, Southington, CT

**POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116**

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
1	Black/Grey (caulk)	Yes	No	--	---	ND	None
2	Black/Grey (caulk)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%  
 ND - asbestos was not detected  
 Trace - asbestos was observed at level of less than 1%  
 NA/PS - Not Analyzed / Positive Stop  
 SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: K. Williamson Reviewed by: Cathryn Lemire Date Issued: 02/01/2018  
 Kathleen Williamson, Laboratory Manager Cathryn Lemire, Approved Signatory

**TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS**

NVLAP Lab Code 101424-0 AIHA-LAP,LLC #100122 CT #PH-0426 ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV# LT000411  
 RI #AAL-007 TX #300354 VT #AL014538 LA#05011 VA #3333 000283 AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907  
 CO# AL-15020 PHIL# 461 PA#68-03387



# ProScience Analytical Services, Inc.

22 Cummings Park, Woburn, Massachusetts 01801  
 781-935-3212 ~ Fax: 781-932-4857 ~ E-Mail general@proscience.net

# Laboratory Report

Client Project #: 222165.5709.0710  
 Client Reference: CT DOT - Intersection, Southington, CT  
 PO #: C222165  
 Client #: 297  
 Client Name: TRC Environmental Corp. (CT)

Batch: NT 17037  
 Method: NOB  
 Date Received: 2/2/2018  
 Date Analyzed: 2/6/2018  
 Date of Report: 2/6/2018

LAB ID	Field ID	Description:	Color	Initial Weight	% Asbestos Types					% Carb.	% Organic	% Other Non-asb.	Total % Asbestos		Preped / Charged	
					CHR	AMO	ACT	CRO	ANT				TRE	Asbestos		Charged
NT128596	2	Black/Grey Flexible Control Box Caulk		2741	.00	.00	.00	.00	.00	.00	6.97	90.40	2.63	ND	Yes	No

**Comments:**

Key: CHR = Chrysotile AMO = Amosite CRO = Crocidolite ACT = Actinolite TRE = Tremolite ANT = Anthophyllite TR = Trace = < 1% ND = None Detected

  
 Mark Derosier, Analyst







**BULK ASBESTOS ANALYSIS REPORT**

CLIENT: CT Department of Transportation

Lab Log #: 0051890  
 Project #: 222165.5709.0710  
 Date Received: 01/30/2018  
 Date Analyzed: 02/01/2018

Site: Intersection Inspection #159-230, Wethersfield, CT

**POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116**

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
01	White (caulk)	Yes	No	--	---	ND	None
02	White (caulk)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%

ND - asbestos was not detected

Trace - asbestos was observed at level of less than 1%

NA/PS - Not Analyzed / Positive Stop

SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: K. Williamson Reviewed by: Cathryn Lemire Date Issued: 02/01/2018  
 Kathleen Williamson, Laboratory Manager Cathryn Lemire, Approved Signatory

**TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS**

NVLAP Lab Code 101424-0 AIHA-LAP, LLC #100122 CT #PH-0426 ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV# LT000411  
 RI #AAL-007 TX #300354 VT #AL014538 LA#05011 VA #3333 000283 AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907  
 CO# AL-15020 PHIL# 461 PA#68-03387



# ProScience Analytical Services, Inc.

22 Cummings Park, Woburn, Massachusetts 01801  
 781-935-3212 ~ Fax: 781-932-4857 ~ E-Mail: general@proscience.net

# Laboratory Report

Client Project #: 222165.5709.0710  
 Client Reference: CT DOT - Intersection Signals, 159-230 Controller  
 PO #: C222165  
 Client #: 297  
 Client Name: TRC Environmental Corp. (CT)

Batch: NT 17033  
 Method: NOB  
 Date Received: 2/2/2018  
 Date Analyzed: 2/6/2018  
 Date of Report: 2/6/2018

LAB ID	Field ID	Description:	Color	Initial Weight	% Asbestos Types					% Other Non-asb.	% Organic	% Carb.	Total % Asbestos	Analyzed / Charged	Preped / Charged
					CHR	AMO	ACT	CRO	ANT						
NT128592	02	Hard White Caulk		.1297	.00	.00	.00	.00	.00	.00	22.13	75.56	ND	Yes	No

**Comments:**

Key: CHR = Chrysotile AMO = Amosite CRO = Crocidolite ACT = Actinolite TRE = Tremolite ANT = Anthophyllite TR = Trace = < 1% ND = None Detected

  
 Mark Derosier, Analyst





**BULK ASBESTOS ANALYSIS REPORT**

CLIENT: CT Department of Transportation

Lab Log #: 0051889  
 Project #: 222165.5709.0710  
 Date Received: 01/30/2018  
 Date Analyzed: 02/01/2018

Site: Intersection Inspection 165-213, Windsor Locks, CT

**POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116**

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
01	White (caulk)	Yes	No	--	---	ND	None
02	White (caulk)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%  
 ND - asbestos was not detected  
 Trace - asbestos was observed at level of less than 1%  
 NA/PS - Not Analyzed / Positive Stop  
 SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized-light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: K. Williamson Reviewed by: Cathryn Lemire Date Issued: 02/02/2018  
 Kathleen Williamson, Laboratory Manager Cathryn Lemire, Approved Signatory

**TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS**

NVLAP Lab Code 101424-0 AIHA-LAP, LLC #100122 CT #PH-0426 ME LA-0075, LB-0071 MA #AA000052 NY #10980 WV# LT000411  
 RI #AAL-007 TX #300354 VT #AL014538 LA#05011 VA #3333 000283 AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907  
 CO# AL-15020 PHIL# 461 PA#68-03387



# ProScience Analytical Services, Inc.

22 Cummings Park, Woburn, Massachusetts 01801  
 781-935-3212 ~ Fax: 781-932-4857 ~ E-Mail: general@proscience.net

# Laboratory Report

Client Project #: 222165.5709.0710  
 Client Reference: CT DOT - Intersection Signals, 165-233 Controller  
 PO #: C222165  
 Client #: 297  
 Client Name: TRC Environmental Corp. (CT)

Batch: NT 17034  
 Method: NOB  
 Date Received: 2/2/2018  
 Date Analyzed: 2/6/2018  
 Date of Report: 2/6/2018

LAB ID	Field ID	Description:	Color	Initial Weight	% Asbestos Types				% Other Non-asb.	% Organic	% Carb.	Total % Asbestos	Analyzed / Charged	Preped / Charged			
					CHR	AMO	ACT	CRO							ANT	TRE	
NT128593	02	Hard White Caulk		.5000	.00	.00	.00	.00	.00	.00	.00	.00	21.96	75.42	ND	Yes	No

**Comments:**

Key: CHR = Chrysotile AMO = Amosite CRO = Crocidolite ACT = Actinolite TRE = Tremolite ANT = Anthophyllite TR = Trace = < 1% ND = None Detected

  
 Mark Derosier, Analyst



SUBJECT Intersection 011-209


SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_

DATE 1/30/18

BY 25 EG

CHK'D \_\_\_\_\_



Span poles - 2 painted metal poles

Controller Cabinet is not painted, silicone around base


No Crosswalk





SUBJECT DOT- Intersectioning's

Cheshire, int# : 025-225  
RT 10 @ Maplecroft Shopping Center



C1- tan, brittle control box caulk



SUBJECT Intersection 042-251 East Hartford


SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_

DATE 1/30/18

BY 25 EG

CHK'D \_\_\_\_\_




Spar poles - 1 painted metal, 1 wood

Controller Cabinet has silicone around base



SUBJECT DOT-Intersection insp's

# 088-247, New Britain  
RT 71 @ Paul Manafort Dr & Francis St




\* NO susp ACM on any structure \*

CCSU



SUBJECT DOT-Intersection insp's

#: 088-279, New Britain  
RT 71 @ Firehouse La.





CI - grey, pliable caulk on light arm (< 1 SF)  
 FI - black, fibrous material (FI)



SUBJECT DDT-Intersection insp's

# 109-201, Plainville  
RT 10 @ Whiting St




galvanized span pole 

\* silicone @ base of both span poles + control box (non-susp)  
\* No scarp ACM \*



SUBJECT DOT-Intersection insp's


Intersection # 118-209, Rocky Hill  
RT 99 @ Town Line Rd





SUBJECT DOT - Intersection insp's

# 131-233, Southington  
RT 322 @ 691 westbound off-ramp



C1 - black/grey, flexible control box caulk



SUBJECT Intersection 159-230 Wethersfield


SHEET NO. \_\_\_\_\_ OF \_\_\_\_\_

PROJECT NO. \_\_\_\_\_

DATE 1/30/18

BY ZS EG

CHK'D \_\_\_\_\_




Controller Cabinet - Only thin, powder coat on door - Only enough for Total Pb  
Spin poles - 2 painted, 1 wood

C1 - hard white caulk on Controller Cabinet base





SUBJECT Intersection 165-213



Span poles and push to cross signal posts are not printed

Controller Cabinet has castle ground base

< - Hard white castle ground base of Controller Cabinet ~ 10 linear feet

**Project Title:** Installation of Traffic Control Signals in District 1

**Project Number:**

- CN Project Number: 171-402
- PE Project Number: 171-402

**Detailed Project Description:** Installation of traffic control signals will require excavation of existing equipment as well as excavation for new foundations (span pole, mast arm, pedestal, controller cabinet, etc.) and trenching (i.e. conduit) as required. In addition to excavation for traffic signal equipment, excavation will be required for sidewalk ramps that will be installed or reconstructed to meet current ADA standards. In areas of an excavation where there is existing signal equipment, excavation will take place in areas that have undergone extensive ground disturbance in the past. In areas of an intersection where there is no existing signal equipment, excavation may be in areas where there may not have been extensive ground disturbance in the past. There is significantly less than one acre of disturbance for each location.

**Purpose and Need Statement:** This project will install new traffic signal equipment, which may include span poles, mast arms, signal heads, span wires, conduits, loops, pedestrian countdown heads, signing and pavement markings, to meet current department standards.

**All intersections below consist of new signal equipment being installed at existing signalized locations:**

1. Bloomfield – Route 218 at North Drive to CIGNA (Int. No. 011-209)
2. Cheshire – Route 10 at Maplecroft Shopping Center (Int. No. 025-225)
3. East Hartford – S.R. 502 at Rolling Meadow Drive (Int. No. 042-251)
4. New Britain – Route 71 at Paul J. Manafort Drive and Francis Street (Int. No. 088-247)
5. New Britain – Route 71 at Firehouse Lane (Int. No. 088-279)
6. Plainville – Route 10 at Whiting Street (Int. No. 109-201)
7. Rocky Hill – Route 99 at Town Line Road (Int. No. 118-209)
8. Southington – Route 322 at Interstate 691 Westbound Off-Ramp (Int. No. 131-233)
9. Wethersfield – Route 175 at Goff Road (Int. No. 159-230)
10. Windsor Locks – Route 140 at Route 159 - South Junction (Int. No. 165-213)


**The intersection below consists of new signal equipment being installed at the existing unsignalized location:**

1. Bloomfield – Route 178 at Crestview Drive (Int. No. 011-252)


**The intersection below consists of a revision to existing signal equipment at the existing signalized location. The revision is for new pedestrian amenities and detection; existing span poles and span pole foundations will remain:**

1. New Britain – Route 372 at Stanwood Drive and Wooster Street (Int. No. 088-221)

**BLOOMFIELD**  
PROJECT 171-402  
ROUTE 218 AT NORTH DRIVE TO  
CIGNA  
INT. 011-209



**CHESHIRE**  
PROJECT 171-402  
ROUTE 10 AT MAPLECROFT  
SHOPPING CENTER  
INT. 025-225




**EAST HARTFORD**


**PROJECT 171-402**

**S.R. 502 AT ROLLING MEADOW DRIVE**

**INT. 042-251**



**NEW BRITAIN**  
**PROJECT 171-402**  
**ROUTE 71 AT PAUL J. MANAFORT DRIVE AND FRANCIS STREET**  
**INT. 088-247**





**PLAINVILLE**  
PROJECT 171-402  
ROUTE 10 AT WHITING STREET  
INT. 109-201



INT. # 109-201

Plainville

372

177

177

10

84



R

E


H

**ROCKY HILL**  
**PROJECT 171-402**  
**ROUTE 99 AT TOWN LINE ROAD**  
**INT. 118-209**

INT. # 118-209




**SOUTHINGTON**  
PROJECT 171-402  
ROUTE 322 AT I-691 WB OFF-RAMP  
INT. 131-233



INT. # 131-233

N  
W  
O  
T

**WETHERSFIELD**  
**PROJECT 171-402**  
**ROUTE 175 AT GOFF ROAD**  
**INT. 159-230**




INT. # 159-230

**WINDSOR LOCKS**

**PROJECT 171-402**

**ROUTE 140 AT ROUTE 159 SOUTH  
JUNCTION**

**INT. 165-213**



**INT. # 165-213**

INTE  
IMPROV  
LOCAL