

**TOWN OF GLASTONBURY  
REQUEST FOR QUALIFICATIONS  
RPGL-2019-25  
ROOFING STUDY OF GLASTONBURY SCHOOLS  
ADDENDUM NO. 1  
January 25, 2019**

The attention of respondents submitting proposals for the above-referenced project is called to the following Addendum to the specifications. The items set forth herein, whether of omission, addition, substitution or other change, are all to be included in and form a part of the proposed Contract Documents for the work. Respondents shall acknowledge this Addendum on the Proposal Response Page (Attachment A).

<b>Question 1.</b>	<b><i>Please define the funding source for the Roofing Study and if funds are currently available.</i></b>
<b>Answer</b>	Funding is available for roofing study in the Town Capital Improvement Program.
<b>Question 2.</b>	<b><i>Please define the intended funding source for future Design and Construction phases, should the project proceed to those phases. Clarify the selected Consultants involvement with CT reimbursement process during this evaluation phase.</i></b>
<b>Answer</b>	Future projects might be funded from a variety of sources. Respondent shall have demonstrated experience with the State of Connecticut reimbursement process to assist the Town with necessary requirements.
<b>Question 3.</b>	<b><i>Please confirm that April 15 – April 19, 2019 is available for the selected consultant to complete the field evaluation (including roof cores) portion of the project.</i></b>
<b>Answer</b>	April 15-19, 2019 is the Spring recess for the District. Buildings will be generally available during that time.
<b>Question 4.</b>	<b><i>Please confirm and state the due date for questions as the RFQ states that questions must be received, “at least five (5) business days prior to the advertised response deadline.” This would mean that questions are due on Friday, February 1, 2019 at 11:00AM. There was some ambiguity as to question due date (Feb. 4?) at the pre-proposal meeting.</i></b>
<b>Answer</b>	All questions shall be submitted by noon on February 4, 2019.
<b>Question 5.</b>	<b><i>Please clarify when the Hourly Rates (on a per square foot basis) are to be submitted. Item 9. On page 7 appears to indicate that an “actual fee proposal is not required”. However the next sentence states, “Respondents shall include the following...in actual fee proposal upon request.” Please clarify if these costs are to be included in the RFQ response or not. We understand the Consultant’s Schedule of Fees is required.</i></b>
<b>Answer</b>	General description (square foot, hourly, etc.) of professional fee structure is required, actual fee proposal is not required. Respondents shall include the following hourly rates in their proposal response: <ul style="list-style-type: none"> <li>• IR roof scan per square foot</li> <li>• Aerial Photography per square foot</li> <li>• Roof Inspection per square foot</li> <li>• % mark up on Materials</li> <li>• % mark up on Sub Consultants</li> </ul>

	<ul style="list-style-type: none"> <li>• Cost per core sample</li> <li>• Cost per report</li> </ul>
<b>Question 6.</b>	<b><i>Please confirm the due dates for preliminary information are due by April 30, 2019 and the study/cost estimates complete by June 1, 2019. If due dates are maintained as noted, will the selected Consultant be granted access to the roof after school hours or on weekends?</i></b>
<b>Answer</b>	All efforts will be made to meet prescribed dates. Town reserves the right to extend dates if necessary.
<b>Question 7.</b>	<b><i>Would the Town be willing to share the existing Structural Report or Hazardous Material Report with consultants as part of the pre-proposal due diligence process?</i></b>
<b>Answer</b>	<p><u>Hazmat:</u> All of the existing school roofs had a complete replacement after 1990. In July 1989, the EPA issued the Asbestos Ban and Phase-Out Rule (ABPR), which planned to impose a full ban on the manufacturing, importation, processing and sale of asbestos-containing products. However, the ban did not include other uses of asbestos such roofing products. Although, it is unlikely that the district school roofs contain asbestos, the EPA - NESHAPS regulation requires pre-construction survey/sampling of any building materials scheduled for removal. This report will be completed during the design phase by the Town's Environmental Consultant and would be inserted in the Roof Consultants design package. Hazmat determination is not part of the Roof Consultants scope.</p> <p><u>Structural:</u> All existing roofs installed between 1990-2011 were designed to meet the energy code at the time of design. All have tapered roof insulation under the roof membrane. The district does not possess structural reports; however the district will provide any available drawings, including roof details to the successful Roof Consultant.</p>
<b>Question 8.</b>	<b><i>Can you provide the 2009 roof reports?</i></b>
<b>Answer</b>	See roof reports attached.

**END OF ADDENDUM NO. 1 TEXT**

GLASTONBURY PUBLIC  
SCHOOLS

SEP 22 2009

FACILITIES AND  
FOOD SERVICE DEPT.



*100% Submittal*  
**Roof Management/ Consulting  
Services for 2009 at  
Glastonbury Public Schools**

*September 11, 2009*



PREPARED BY:



**PROFESSIONAL ROOF  
CONSULTANTS**

608 Chadds Ford Drive  
Dilworth Suite #200  
Chadds Ford West  
Chadds Ford, PA 19317  
Tel: 610-558-4000  
Fax: 610-388-9415  
WEBSITE: [www.teamrri.com](http://www.teamrri.com)



**A WOMAN OWNED SMALL BUSINESS**

11-11-11  
11-11-11

## Table of Contents

Cover letter	Pages 1 thru 2
Visual Roof Evaluation Report	Pages 3 thru 10
Buttonball Lane ES	Pages 11 thru 23
Eastbury ES	Pages 24 thru 31
Gideon Welles JHS	Pages 32 thru 51
Glastonbury HS & Gymnasium	Pages 52 thru 90
Hebron ES	Pages 91 thru 93
Hopewell ES	Pages 94 thru 109
Naubuc ES	Pages 110 thru 127
Smith MS	Pages 128 thru 144
Solar Survey Study	Pages 145 thru 152
Appendix A — Estimated Size & Output	Pages 153 thru 156
Appendix B—Design Layout	Page 157
Drawings	SKE-1.0 SKE-2.0 SKE-3.0

September 11, 2009

Mr. Bradley Devlin  
Director of Facilities  
Glastonbury School District  
320 Hubbard Street  
Glastonbury, CT 06033-0191

RE: Roof Management / Consulting Services 2009 – Glastonbury School District

Dear Mr. Devlin:

Roofing Resources, Inc. recently conducted a visual roof evaluation to provide current conditions, provide incidental remedial repairs, provide opinion of repairs to deficient areas and provide roofing options for budgeting in FY2010. Included in this report are Three (3) options:

Option 1 – Visual Evaluation with Minor Repairs:

- The scope of work includes all buildings and roof areas in the Glastonbury School District.
- Onsite school management interviews will be conducted to determine problem areas as a priority.
- Roof systems will be walked to visually identify all field, perimeter, and termination conditions.
- Notes will be made on drawings if available. If drawings are not available notes will be catalogued for reporting.
- Digital photographs will be taken of identified system issues along with repairs if completed.
- Minor, typical, bi-annual maintenance repairs and patching will be completed using in-kind materials during the evaluations. All conditions identified and determined to require more extensive repair will be detailed and completed at a time and material basis only after the School Districts review and approval.
- Out of scope work can be considered with intensive investigation including coring, measurements, infrared survey, AutoCAD drawings, specification writing, quality assurance, and other services to fully determine the source of issues and/or the requirements for repair or maintenance.
- The appropriate client representative will receive a report of all work completed along with recommendations.

Option 2 – Hebron Avenue School Replacement Options, Solar Survey, and Respective Budget Estimates:

- The scope of work includes all roof areas scheduled to be replaced on the Hebron Avenue Elementary School.
- All previous roof system documentation will be verified for accuracy.
- School management will be interviewed to understand current energy, mandates including cool roof listing, LEED best practices, VOC compliance, and any other pertinent State or Local Government requirements.

- A general solar survey will be included. The solar evaluation will include a summarized findings and recommendations report for steps to be completed to fully integrate a solar installation with a future roof system replacement.
- A comprehensive summary report including roof system options for consideration and corresponding budgets projected to 2010 costs.
- Out of Scope work includes a full building structural evaluation, development of full roof system replacement specification and construction documents, detailed AutoCAD Drawings corresponding to specification documents, project bid and project quality management.

**Option 3 – Naubuc School Metal and Masonry Repairs:**

- Secure metal cap flashings and seal as needed.

We trust our roof services and report meet with your requirements for this facility. Please contact our office if you have any questions or if we may be of service in any other way.

Regards,  
Roofing Resources, Inc.



Kenneth Areskog  
Regional Manager

C: Gregory Rose – SR Products, Inc.  
Erich Poch - RRI

**VISUAL ROOF EVALUATION REPORT - 2009**

**CLEINT:** Glastonbury School District  
320 Hubbard Street  
Glastonbury, CT 06033-0191

**CONTACT:** Mr. Bradley Devlin  
Director of Facilities  
(860) 652-7950

**PROJECT:** Roof Management and Consulting Services for 2009  
Glastonbury School District consisting of:  
Buttonball Lane ES  
Eastbury ES  
Gideon Welles JHS  
Glastonbury HS & Gymnasium  
Hebron ES  
Hopewell ES  
Naubuc ES  
Smith MS

**DATE OF SITE VISITS:** June 23<sup>rd</sup> - June 25<sup>th</sup> and July 1<sup>st</sup>, 2009

**SURVEY CONDUCTED BY:** Kenneth Areskog  
Roofing Resources, Inc. (RRI)  
(770) 558-2219

---

As part of the roof system leak investigation, Roofing Resources, Inc. (RRI) performed a visual assessment on the referenced schools located in Glastonbury, CT. This assessment included a visual walk-over of existing buildings, interview of on-site personnel to assist in determining locations and history of existing leaks, visual verification of existing components and inspection of the existing conditions along with minor repairs and cleaning of debris around roof drains and other isolated locations. RRI will provide opinions and options for remediation along with opinion of costs.

**OBSERVATION, FINDINGS & RECOMMENDATIONS**

**Buttonball Lane ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 11 through 23)**

Approximate Roof Area: 62,500 square feet

This school is a single-storied building with multi-level roof areas. The façade is comprised of brick with multi-paned aluminum framed windows. The roof system is comprised of a reinforced EPDM fully adhered membrane over what appears to be a mechanically attached tapered polyisocyanurate insulation board. Core samples were not taken and warranty information was not available. The physical appearance of the membrane appears to be in good condition; however this roof is beginning to show signs of aging with the advent of de-lamination of splice seams at patches and field seams.



Anomalies and repair recommendations with quantities include:

- Approximately 400 de-laminated perimeter patches shall be repaired by applying a new surface splice over the existing patch.
- Approximately 475 de-laminated field patches shall be repaired by applying a new surface splice over the existing patch.
- Approximately 250 linear feet of deteriorated sealant to existing surface mounted counter flashing shall be repaired with removal of the old sealant and the replacement of new sealant.
- Approximately 250 linear feet of de-laminated field seams around six (6) roof drain targets shall be overlaid with new strip-ins.
- Approximately 160 linear feet of de-laminated field seams at one (1) expansion joint location shall be overlaid with new strip-ins.
- Strip-in flashings at six (6) existing scupper locations shall be overlaid with new strip-ins.
- Trim two (2) trees with branches extending unto the roof.

All roof drains and roof areas were cleaned of debris. Surface splices, open seams, pourable sealer pockets with voids were topically treated as needed.

Eastbury ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 24 through 31)

Approximate Roof Area: 44,300 square feet

This school is a single-storied building with multi-level roof areas. The façade is comprised of brick with multi-paned aluminum framed windows. The roof system is comprised of a non-reinforced EPDM fully adhered membrane over what appears to be a mechanically attached tapered polyisocyanurate insulation board. Core samples were not taken; however, provided warranty information indicates a 20-year Firestone warranty is in place with an expiration date of 2015. The physical appearance of the membrane appears to be in good condition; however this roof is beginning to show signs of aging with the advent of de-lamination of splice seams at patches and field seams.

Anomalies and repair with quantities include:

- Missing roof drain strainers at two (2) drain locations shall be replaced.
- Poor roof drainage was observed between drains at Area 2 and at roof scuppers on Area 2 and 6. No action required until roof is renovated.
- Three (3) oxidized curb caps shall be primed and re-coated.
- Unused gas piping shall be removed and discarded.
- Open flashing laps were observed at two (2) scuppers shall be repaired applying new strip-ins.
- Missing downspout shall be replaced with approximately 10' linear feet of 3"x4" new leader with splash block.
- Possible wet insulation observed by A/C unit on Area 2. Approximately 200 square feet appear soft to foot traffic.
- Approximately 50 de-laminated perimeter patches shall be repaired by applying a new surface splice over the existing patch.
- Approximately 100 de-laminated field patches shall be repaired by applying a new surface splice over the existing patch.

- Approximately 700 linear feet of de-laminated field seams around six (16) roof drain targets shall be overlaid with new strip-ins.
- Approximately 1,500 linear feet of de-laminated field seams shall be overlaid with new strip-ins.
- Trim tree with branches extending unto the roof.

All roof drains and roof areas were cleaned of debris. Surface splices, open seams, pourable sealer pockets with voids were topically treated as needed.

Gideon Welles JHS: (See photographic Journal Showing Aerial and Roof Areas on Pages 32 through 51)

Approximate Roof Area: 82,600 square feet

This school is a two-storied building with multi-level roof areas. The façade is comprised of brick with multi-paned aluminum framed windows. The roof system is comprised of a gravel surface asphalt built-up roof system. Core samples were not taken, therefore, no additional information was obtained on concealed components. It was indicated a 20-year warranty was issued in 1991. The physical appearance of the membrane appears to be in fair/poor condition; however this roof is beginning to show signs of aging with the advent of de-lamination of gravel surfacing and the deterioration of flashing components. Generic asphalt built-up roofs have limited service-life after 20 years due to thermal changes over an extended period of time.

Anomalies and repair with quantities include:

- Approximately sixty (60) areas are exhibiting signs of gravel migration causing the asphalt membrane to be exposed to the sunlight which may deteriorate the membrane prematurely. These areas shall be swept back to the gravel adhesion point, new asphalt adhesive applied and the gravel re-applied.
- Approximately 400' linear feet of base flashings are showing signs of deterioration. These areas shall have the existing base flashings removed and replace with new modified bitumen flashings.
- Roof Areas 1 and 16 have trees extending onto the roof area. These trees shall be trimmed back from the roof.

All roof drains, gutters and roof areas were cleaned of debris. Voids in the strip-ins around the roof's perimeters were re-sealed as needed. In addition, pitch pockets with voids were topically treated in affected areas.

Glastonbury HS & Gymnasium: (See photographic Journal Showing Aerial and Roof Areas on Pages 52 through 90)

Approximate Roof Area: 137,550 and 51,250 square feet, respectively

This school is a single to two-storied building with multi-level roof areas. The façade is comprised of brick with multi-paned aluminum framed windows. The roof systems on the main school areas are comprised of a mostly gravel surfaced built-up roof systems with new additions added with white granular surfaced modified bitumen roof systems. The gymnasium roofs are comprised predominantly of fully adhered non-reinforced EPDM membrane with out-sections of gravel surfaced built-up and newer white granular surfaced modified bitumen roof systems. Core samples were not taken and

warranty information was not available. The physical appearances of the predominant gravel-surfaced roofs are marginal with some areas in poor condition and some areas in fair condition. The newer granular surfaced modified bitumen roofs are in good condition with some incidental installation anomalies. The EPDM membrane roof systems are in good condition; however, a moderate amount of repairs are needed to extend the service life of this roof system.

Anomalies and repair with quantities include:

**Main School Roof:**

- Approximately fifteen (30) areas of exposed felts were observed around roof drains and perimeter edges shall have new adhesive applied with the gravel replaced.
- Approximately 200' linear feet of exposed membrane was observed around the perimeter shall have new adhesive applied with the gravel replaced.
- Rotor clean two (2) roof drains.
- Approximately 100' linear feet of neoprene expansion joint is split and shall be repaired with new EPDM adhesive tape.
- Approximately 300' linear feet of loose base flashings are in need of repair/replacement.
- Replace approximately 100 linear feet of deteriorated sealant to existing reglet-mounted counter flashing.
- Approximately twenty (20) pitch pockets are constructed in a clustered manner. This correction should be considered with a roof replacement.
- Approximately fifty (50) areas at expansion joint and/or base flashing terminations shall be re-enforced with mastic and mesh.

**Gymnasium Roof:**

- Approximately 200 square feet of soft (probably wet) insulation was observed by a large roof-top unit shall be removed and replaced with new components.
- Approximately 50 de-laminated field patches shall be repaired by applying a new surface splice over the existing patch.
- Approximately three (3) areas of exposed felts were observed around roof drains shall have new adhesive applied with the gravel replaced.

All roof drains and roof areas were cleaned of debris. Surface splices, open seams, pourable sealer pockets with voids were topically treated as needed.

**Hebron ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 91 through 93)**

Approximate Roof Area: 56,750 square feet

This school is a single-storied building with some raised roof areas. The façade is comprised of brick with multi-paned aluminum framed windows. The roof systems are comprised of fully adhered EPDM membrane roof systems on the raised roof areas and ballasted EPDM roof systems on the lower roof areas. The raised roof areas appear to have mechanically attached insulation systems. The lower roof area insulation was not obtained. Core samples were not taken and warranty information was not

available. The physical appearance of the membrane appears to be in fair condition on the raised roof areas and poor condition on the lower roof areas.

Anomalies and repair with quantities include:

**Raised Roof Areas:**

- Approximately 100 de-laminated field patches shall be repaired by applying a new surface splice over the existing patch.

**Lower Roof Areas:**

- Membrane is pulling loose from terminations in many areas. Due to the condition of these roof areas, temporary repairs shall be used to prevent water from damaging the interior space.

All roof drains and roof areas were cleaned of debris.

Hopewell ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 94 through 109)

**Approximate Roof Area: 59,650 square feet**

This school is a single-storied building with multi-level roof areas. The façade is comprised of brick with multi-paned aluminum framed windows. The roof system is comprised of a reinforced EPDM fully adhered membrane over what appears to be a mechanically attached tapered polyisocyanurate insulation board. Core samples were not taken and warranty information was not available. The physical appearance of the membrane appears to be in good condition; however this roof is beginning to show signs of aging with the advent of de-lamination of splice seams at patches and field seams.

Anomalies and repair with quantities include:

- Approximately 200 de-laminated perimeter patches shall be repaired by applying a new surface splice over the existing patch.
- Approximately 600 de-laminated field patches shall be repaired by applying a new surface splice over the existing patch.
- Overlay approximately 1,500 linear feet of de-laminated field seams around thirty-five (35) roof drain targets with new strip-ins.
- Approximately 50 linear feet of repair requires strip-in at building removal area indicated at Roof Area 2 & 10.
- Trim tree branches extending unto the roof.

All roof drains and roof areas were cleaned of debris. Surface splices, open seams, pourable sealer pockets with voids were topically treated as needed.

**Naubuc ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 110 through 127)**

Approximate Roof Area: 43,500 square feet

This school was constructed with a single-storied brick façade building with additions added over the years. The additions are single and two-storied structures. The roof systems comprise of gravel-surfaced built-up roofs on the four (4) main wings with fully adhered EPDM roofs on the connecting roof areas. Asphalt shingles are installed on the original building at the mansard and a shingle roof was incorporated into the EPDM connecting roof areas. The façade is comprised of brick with punch opening windows and multi-paned aluminum framed windows. The insulation below the EPDM roof systems appears to be mechanically attached tapered polyisocyanurate insulation; however the insulation below the gravel-surfaced built-up roofs was not available. Core samples were not taken and warranty information on the gravel-surfaced roofs was not available, however the EPDM roof systems are currently under warranty. The physical appearance of the gravel-surfaced built-up roofs appears to be in fair condition with some areas appearing in poor condition. The EPDM roof system and asphalt shingles appear to be in satisfactory condition.

**Option 3 – Naubuc School Metal and Masonry Repairs:**

- All loose metal caps were securely fastened to the brick masonry substrates at the 1<sup>st</sup> floor perimeter columns.

Anomalies and repair with quantities include:

- Apply approximately 300 square feet of liquid membrane to wall panels on clerestory.
- Re-saturate approximately 300 square feet of exposed membrane on gravel-surfaced built-up roof areas.
- Seal laps on approximately 8- linear feet of expansion joint.
- Overlay approximately ten (10) de-laminated field patches at one (1) expansion joint location.
- Replacement four (4) roof strainers and check all drain ring clamps.
- Trim tree branches extending unto the roof.
- Tuck-point mortar beds on chimney.
- Replace broken roof-top turbine.

All roof drains and roof areas were cleaned of debris. Surface splices, open seams, pourable sealer pockets with voids were topically treated as needed.

**Smith MS: (See photographic Journal Showing Aerial and Roof Areas on Pages 128 through 144)**

Approximate Roof Area: 71,000 square feet

This school is a multi-level building of single to two-storied floors. The façade is comprised of brick with ribbons of decorative cut-faced masonry block with punch opening and multi-paned aluminum framed windows. The roof system is comprised of a pea-gravel aggregate built-up roof system. Core samples were not taken; therefore no insulation information was available. The built-up roof areas currently have a 20-year warranty. Sloped roof areas have asphalt shingles. The physical appearance of the membrane appears to be in good condition.

Anomalies and repair with quantities include:

- Gravel stop strip-ins, expansion joint terminations and base flashings are showing early signs of distress. Approximately 4,000 linear feet of strip-in, expansion joint and base flashings shall require protection from ultraviolet sunlight.
- Replacement two (2) roof strainers and check all drain ring clamps.

All roof drains and roof areas were cleaned of debris. Surface splices, open seams, pourable sealer pockets with voids were topically treated as needed.

#### **OPINION OF COSTS & REPAIR/REPLACEMENT RECOMMENDATIONS**

**Buttonball Lane ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 11 through 23)**

It is our professional opinion the current roof system condition to be in **GOOD** condition; therefore we recommend the following Repair Budget to be: \$0.25 per sf @ 62,500 sf

**Eastbury ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 24 through 31)**

It is our professional opinion the current roof system condition to be in **GOOD** condition; therefore we recommend the following Repair Budget to be: \$0.25 per sf @ 44,300 sf

**Gideon Welles JHS: (See photographic Journal Showing Aerial and Roof Areas on Pages 32 through 51)**

It is our professional opinion the current roof system condition to be in **POOR-FAIR** condition; therefore we recommend the following Replacement and Repair Budget to be: \$25.00 per sf (replacement) and \$0.75 per sf (repairs) @ 44,300 sf

**Glastonbury HS & Gymnasium: (See photographic Journal Showing Aerial and Roof Areas on Pages 52 through 90)**

It is our professional opinion the current roof system condition to be in **POOR-FAIR-GOOD** condition; therefore we recommend the following Replacement and Repair Budget to be: \$25.00 per sf (replacement) and \$0.75 per sf (repairs) @ 137,550 and 51,250 square feet NOTE: Good areas are designated as newer modified bitumen roof systems. General maintenance can be considered at \$0.05 per sf.

**Hebron ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 91 through 93)**

It is our professional opinion the current roof system condition to be in **POOR-FAIR** condition; therefore we recommend the following Replacement and Repair Budget to be: \$25.00 per sf (replacement) and \$0.75 per sf (repairs) @ 46,750 and 10,000 square feet

**Hopewell ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 94 through 109)**

It is our professional opinion the current roof system condition to be in **GOOD** condition; therefore we recommend the following Repair Budget to be: \$0.25 per sf @ 59,650 sf

Naubuc ES: (See photographic Journal Showing Aerial and Roof Areas on Pages 110 through 127)

It is our professional opinion the current roof system condition to be in POOR-FAIR-GOOD condition; therefore we recommend the following Replacement and Repair Budget to be: \$25.00 per sf (replacement) and \$0.75 per sf (repairs) @ 43,500 square feet NOTE: Good areas are designated as newer EPDM and asphalt shingle roof systems. General maintenance can be considered at \$0.05 per sf.


Smith MS: (See photographic Journal Showing Aerial and Roof Areas on Pages 128 through 144)

It is our professional opinion the current roof system condition to be in GOOD condition; therefore we recommend the following Repair Budget to be: \$0.25 per sf 71,000 square feet

NOTE: Cost estimates on areas where replacement and/or repairs are recommended can be provided upon request. The budget estimates are to provide guidelines for budgeting only.

**ADDITIONAL CAPABILITIES**

With design/build capabilities, RRI is prepared to provide all materials and labor to perform the outlined scope of work. We are also available to provide any additional assistance which may include technical assistance, quality assurance, project management, forensic assistance and engineering services.



Buttonball Lane ES

Buttonball Lane, Glastonbury, CT





Glastonbury School District - Buttonball Lane ES | 2009



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Anamoly  
Open voids at cover strip transitions



Area 1—Anamoly  
Deteriorated sealants at top edge of surfaced mounted counter-flashings with open sheet metal miters



Area 1—Anamoly  
Splice laps are delaminating at some roof drain targets



Area 1—Anamoly  
Cover strips at edge metal transitions are lifting. Remedial repairs were conducted where moisture wasn't present



Area 1—Anamoly  
Splice patches throughout roof area are delaminating around the edges. NOTE: This condition is typical at all roof locations



Area 1—Observation  
Terminations appear to be in satisfactory condition



Area 2—Overview



Area 2—Overview



Area 2—Overview



Area 2—Overview



Area 2—Overview



Area 2—Anomaly  
Splice lap is delaminating along the edge at most locations.



Area 2—Anomaly  
Splice laps are delaminating at some roof drain targets  
NOTE: Splice patches about area are delaminating around the edges.



Area 2—Observation  
Terminations appear to be in satisfactory condition



Area 3 —Overview



Area 3 —Overview



Area 3 —Overview



Area 3 —Overview



Area 3 —Overview



Area 3 —Anomalies  
Open laps at all scuppers, splice patches at edge metal transitions are delaminating and splice patches in the field of the roof are delaminating



Area 4—Overview



Area 4—Overview



Area 4—Anomalies

Splice patches at edge metal transitions are delaminating, splice patches in the field of the roof are delaminating and counter-flashing sealants are deteriorating



Area 5 — Overview



Area 5 — Overview



Area 5 — Overview



Area 5 — Overview



Area 5 — Overview



Area 5 — Anomalies  
Splice laps are delaminating at some roof drain targets  
NOTE: Splice patches about area are delaminating around the edges.



Area 5 — Anomalies  
Splice patches at wall transitions around the perimeter are delaminating



Area 6 — Overview



Area 6 — Overview





Area 6—Anomalies  
Splice patches in the field of the roof are delaminating and counter-flashing sealants are deteriorating



Area 7—Overview



Area 6—Anomalies  
Splice patches in the field of the roof are delaminating



Area 7 — Observations  
Terminations appear satisfactory



Area 8 — Overview



Area 8 — Overview



Area 8—Overview



Area 8—Overview



Area 8— Overview



Area 8 — Overview



Area 8 — Anomalies  
Splice patches at edge metal transitions are delaminating, splice patches in the field of the roof are delaminating and counter-flashing sealants are deteriorating



Area 8—Observations  
Terminations appear to be in satisfactory condition



Area 9 —Overview



Area 9 —Overview



Area 9 —Overview



Area 9 — Anomalies  
Splice patches at edge metal transitions are delaminating, splice patches in the field of the roof are delaminating



Area 9 — Anomaly  
Open splices on roof drain targets



Area 10 —Overview



Area 10—Overview



Area 10—Observations  
Terminations appear to be satisfactory



Area 11—Overview



Area 11 — Overview  
NOTE: Excessive ponding was observed



Area 11 — Overview



Area 11 — Anomalies  
Splice patches at edge metal transitions are delaminating and splice patches in the field of the roof are delaminating



Area 12—Overview



Area 12—Overview



Area 12—Observations  
Terminations appear to be in satisfactory condition.  
Gutters were cleared of debris



Area 13— Overview



Area 13— Overview and Observations  
Terminations appear to be in satisfactory condition.  
Some delamination of splice seams/patches were observed.



Area 14— Overview and Observations  
Terminations appear to be in satisfactory condition.  
Some delamination of splice seams/patches were observed.



Eastbury ES  
Neipsic Rd., Glastonbury, CT



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Anomaly  
Galvanized steel curb caps oxidizing



Area 1—Observation  
Unused utility pipe—Recommend removal



Area 1—Anomaly  
Metal edge strip-in delaminating from gravel guard



**Area 1—Anomalies**  
Cover plate strip-ins are splitting at seam, many splice patches about roof area delaminating and roof drain target splices are delaminating around the edges



**Area 2—Overview**



**Area 2—Overview**



**Area 2—Overview**  
NOTE: Small raised roof area ponds water and has failed edge metal strip-in flashings around perimeter



**Area 2—Overview**



**Area 2— Overview**





Area 2— Overview



Area 2—Anomaly

Water ponds between roof drains, splice laps are delaminating at some roof drain targets, many splice patches are delaminating and edge metal cover strips are splitting or delaminating



Area 2—Anomaly

Open splice seams at scupper outlet



Area 2— Anomaly

Field seams are delaminating in some areas



Area 2 —Overview

NOTE: Recommend removal of tree branches from roof area



Area 2 —Anomaly

Missing downspout



Area 3—Overview



Area 3—Overview



Area 3 — Anomalies

Splice laps are delaminating at some roof drain targets, many splice patches are delaminating and edge metal cover strips are splitting or delaminating



Area 4 — Overview



Area 4— Overview



Area 4 — Overview



Area 4 —Overview



Area 4 —Anomalies

Cover plate strip-ins are splitting at seam, many splice patches about roof area delaminating and roof drain target splices are delaminating around the edges  
NOTE: Excessive blisters along cover strip on batten



Area 5 —Overview



Area 5 —Overview



Area 5 —Overview



Area 5 —Anomalies

Splice patches at edge metal transitions are delaminating and splice patches in the field of the roof are delaminating



Area 6—Overview



Area 6—Overview



Area 6— Overview



Area 6 — Anomaly  
Strip-in flashings a open around scupper flashing



Area 6 — Anomaly  
Missing roof drain strainers, splice laps are delaminating at some roof drain targets, many splice patches are delaminating and edge metal cover strips are splitting or delaminating




Area 6 — Anomaly  
Brick tuck-pointing recommended



Area 7—Overview



Area 7—Anomalies  
Edge metal cover strips are splitting or delaminating



Hopewell ES  
1068 Chestnut Hill Rd., Glastonbury, CT



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1— Anomaly  
Splice patches are delaminating at their perimeters



Area 1— Anomaly  
Target splices are delaminating at their perimeters



Area 1—Observation  
View of roof termination at wall



Area 1—Observation  
View of expansion joint termination at the wall



Area 1— Observation  
View of perimeter edge metal



Area 1—Observation  
View of expansion joint termination at the outside roof edge



Area 1—Anomaly  
Open splice along outside edge was sealed



Area 1—Anomaly  
Openings in splice patches. Remedial repairs were conducted in these areas.



Area 2—Overview





Area 2—Overview



Area 2—Overview



Area 2—Overview



Area 2—Overview



Area 2—Anomaly  
Splice patches delaminating at their perimeters



Area 2—Observation  
View of expansion joint at wall transition



Area 2—Overview  
View of expansion joint at roof transition at roof edge  
Debris was removed from the roof's surface



Area 2— Anomaly  
View of roof repair where building was modified.  
Splice patch appears open at termination points



Area 2—Anomaly  
Repair patch was not flashed into the expansion joint



Area 2—Observation  
View of roof repair at roof modification



Area 2—Observation  
View of expansion joint at wall transition



Area 2—Anomaly  
Metal counter flashing in poor condition



Area 2—Anomaly  
Splice patches repaired where applicable



Area 3—Overview



Area 3—Overview



Area 3—Overview



Area 3—Anomaly  
Splice patches delaminating in many areas



Area 4—Overview



Area 4—Overview



Area 4—Overview



Area 4—Overview



Area 4—Overview



Area 4—Anomaly  
Splice patches delaminating in many areas



Area 4—Overview



Area 4— Anomaly  
Debris was removed from the roof area



Area 4— Anomaly  
Many splice patches are delaminating at the transitions



Area 4— Anomaly  
Splice targets are delaminating around the edges



Area 4— Anomaly  
Splice patches are delaminating in many areas



Area 4— Anomaly  
Splice patches at roof perimeters are open at metal junctions. These areas received remedial repairs where applicable.



Area 4— Anomaly  
Target patches at roof projections are delaminating at many areas.



Area 5—Overview



Area 5—Overview



Area 5—Overview



Area 5—Overview



Area 5— Anomaly  
Splice patches delaminating at edges



Area 5— Anomaly  
Target patches delaminating at edges



Area 5— Observation  
View of expansion joint at wall transition



Area 5— Observation  
View of expansion joint at wall transition



Area 5— Anomaly  
Splice patches at roof perimeters are open at metal junctions. These areas received remedial repairs where applicable.



Area 6— Overview



Area 6— Overview



Area 6— Overview



Area 6—Overview



Area 6—Overview



Area 6—Overview



Area 6—Overview



Area 6—Anomaly  
Sealant deterioration at termination bar



Area 6—Anomaly  
Surface splice open at roof to vertical transition





Area 7—Overview and Observation  
Note: Ponding water



Area 7—Overview and Observation  
Note: Ponding water



Area 8—Overview



Area 8—Overview



Area 8—Observation  
Fasteners appear to be protruding beneath membrane



Area 8—Overview  
Sealants appear to be deteriorating at gutter laps.



Area 9—Overview



Area 9—Overview



Area 9—Overview



Area 9—Observation  
Outside view of roof scupper



Area 9—Anomaly  
Surface splices delaminating at edges



Area 9—Anomaly  
Surface splices delaminating at edges



Area 10—Overview



Area 10—Overview



Area 10— Anomaly  
Conduits clustered through roof penetration pocket



Area 10—Anomaly  
Vegetation should be trimmed back from roof area



Area 10— Observation  
Wall crack was typically repaired in the past. Current sealants are deteriorating.



Area 10—Anomaly  
Expansion joint cover strip is delaminating in areas



Area 11—Overview



Area 11—Overview



Area 11—Anomaly  
Splice patches along perimeter are delaminating from edge metal



Area 11—Anomaly  
Surface splices are delaminating in many areas



Area 11—Observation  
View of termination at wall



Area 12—Overview



Area 12—Overview



Area 12—Overview



Area 12—Anomaly  
Splice patches are delaminating in areas



Area 12—Anomaly  
Target patches are delaminating in areas



Gideon Welles MS  
1029 Neipsic Road, Glastonbury, CT



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Anomaly

Exposed membrane around drain areas  
NOTE: Exposed areas where typically identified at roof ridges, roof perimeter corners and roof drains



Area 1— Anomaly  
Non-waterproofed pipe insulation appears to extending into pourable sealer pocket



Area 1— Anomaly  
Strip-in flashings were un-adhered to the edge metal in many location. Where identified, remedial repairs were conducted to these locations



Area 2— Overview



Area 2— Overview  
No apparent anomalies were observed at this roof area



Area 3— Overview



Area 3— Overview





Area 3 — Anomaly  
Termination securement missing at this location



Area 3 — Anomaly  
Deteriorated sealant joints were observed



Area 3 — Observation  
Termination appears satisfactory



Area 3 — Observation  
Suggest applying counter flashing metal over area shown



Area 4 — Overview



Area 4 — Overview



Area 4 — Anomaly  
Base flashing does not extend beyond roof edge metal



Area 4 — Anomaly  
Deteriorated joint sealant



Area 5 — Overview



Area 5 — Overview



Area 5 — Overview



Area 5 — Anomaly  
Strip-in membrane delaminating from edge metal



Area 6 — Overview



Area 6 — Overview



Area 6 — Overview



Area 6 — Anomaly  
Missing termination on base flashing



Area 6 — Anomaly  
Expansion joint does not extend past metal edge



Area 6 — Observation  
Expansion joint termination appears to be satisfactory



Area 7—Overview



Area 7—Overview



Area 7 — Overview



Area 7 — Overview



Area 7 — Anomaly  
Poor edge metal termination



Area 7 — Anomaly  
Poor edge metal termination



Area 7 — Anomaly  
Loose base flashings around ventilators



Area 7 — Anomaly  
Poor base flashing installation at roof hatch



Area 7 — Observation  
View of base flashing



Area 7 — Anomalies  
Open termination at base flashings  
NOTE: Base flashings appear to be in poor condition



Area 7 — Anomaly  
Mortar beds for brick in poor condition



Area 8 — Overview



Area 8 — Overview



Area 8 — Overview



Area 8 — Anomalies  
Some exposed membrane areas



Area 8 — Anomaly  
Strip-in delaminating from edge metal  
Remedial repairs conducted to these areas



Area 9 — Overview



Area 9 — Overview



Area 9—Overview  
No apparent anomalies were observed



Area 10—Overview



Area 10— Anomaly  
Gutters were cleared of debris



Area 11 — Overview



Area 11 — Overview



Area 11 — Anomaly  
Poor tie-in between expansion joint and edge metal



Area 11 — Anomaly  
Expansion joint material is deteriorated



Area 11 — Anomaly  
Broken roof drain strainer



Area 11 — Anomaly  
Remedial repairs were conducted to the strip-in at locations delaminated from edge metal



Area 11 — Anomalies  
Debris was removed from the roof surface



Area 11 — Anomaly  
Apparent opening below window



Area 11 — Observation  
Base flashings appear to be in satisfactory condition





Area 12 — Overview  
NOTE: Exposed membrane along perimeter edge



Area 12 — Overview



Area 12 — Overview



Area 12 — Overview  
NOTE: Exposed membrane along perimeter edge



Area 12 — Overview  
NOTE: Exposed membrane along perimeter edge



Area 12 — Anomalies  
Poor roof tie-in at roof transitions



Area 13 —Overview



Area 13 —Overview



Area 13 —Observations  
Terminations appear to be in satisfactory condition.  
Gutters were cleared of debris



Area 13 — Overview



Area 13 — Overview and Observations  
Terminations appear to be in satisfactory condition.  
Some delamination of splice seams/patches were observed.



Area 13 — Anomaly  
Poor expansion joint tie-in



Area 13 — Anomaly  
Expansion joint does not extend to the outside edge



Area 13 — Anomaly  
Base flashing is not terminated at edge metal



Area 13 — Observation  
Base flashings are showing signs of distress



Area 13 — Anomaly  
Base flashing laps are not fully adhered



Area 14 — Overview



Area 14 — Overview



Area 14 — Anomaly  
NOTE: Exposed membrane in isolated areas



Area 14 — Overview



Area 14 — Anomaly  
Exposed membrane and broken roof drain strainer



Area 14 — Anomaly  
Strip-in membrane along perimeter is not adhered to edge metal. Remedial repairs were conducted at these locations



Area 15 — Overview



Area 15 — Overview



Area 15 — Overview



Area 15 — Overview



Area 15 — Anomaly  
Poor installation of refrigerant pipes



Area 16 — Anomaly  
Expansion joint does not extend to the roof's perimeter



Area 16 — Overview



Area 16 — Overview



Area 16 — Observation  
Plastic coated conduits require a gooseneck chase



Area 16 — Observation  
Plastic coated conduits require a gooseneck chase



Area 16 — Overview  
View of edge metal detail



Area 17 — Overview



Area 17 — Overview



Area 17 — Overview



Area 17 — Observation  
Base flashings appear satisfactory



Area 17 — Observation  
Base flashings appear satisfactory



Area 17 — Anomaly  
Base flashing missing termination securement



Area 17 — Anomaly  
Conduits are not sealed at through wall locations



Area 18 — Overview



Area 18 — Overview



Area 18 — Overview



Area 18 — Overview



Area 18 — Observations  
Some minor strip-in flashings are un-adhered to the edge metal. Remedial repairs were conducted at these locations.



Area 19 — Overview  
Gravel was removed from the membrane surface



Area 19 — Overview



Area 19 — Anomaly  
Expansion joint does not extend to the roof's perimeter edge






Area 20 — Overview



Area 20 — Anomaly  
Gutter appears to be back-pitched




Hebron ES  
Hebron Avenue, Glastonbury, CT



# Glastonbury School District - Hebron Avenue ES | 2009



Area 1—Overview



Areas 1, 2 & 3—Overview



Area 3—Overview



Area 3—Overview




Area 2—Overview




Area 2—Observation  
Mortar joints on brick work failing


# Glastonbury School District - Hebron Avenue ES | 2009



Areas 3 & 4 —Overview



Areas 3 & 4 —Overview




Areas 2, 5 & 7 —Overview




Area 6—Overview



Area 6—Overview



Areas 1 & 2 — Anomaly  
Membrane shrinkage at expansion joint



Glastonbury HS & Gymnasium  
Hubbard Rd., Glastonbury, CT



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1— Anomalies  
Exposed membrane felts at roof drain. Similar exposed felt conditions appear around perimeter edges



Area 1— Anomaly  
Apparent loose base flashings



Area 1— Anomalies  
Additional areas of exposed membrane. Circle indicates a restricted roof drain leader



Area 2 — Overview



Area 2 — Overview



Area 2 -- Overview



Area 2 — Anomaly  
Missing termination bar beneath window support sill



Area 2—Anomaly  
Apparent loose base flashings



Area 2—Anomaly  
Missing sealant at counter flashing reglet






Area 3— Overview  
Splice laps are delaminating at some roof drain targets



Area 3— Overview  
Cover strips at edge metal transitions are lifting. Remedial repairs were conducted where moisture wasn't present



Area 3— Overview  
Splice patches throughout roof area are delaminating around the edges. NOTE: This condition is typical at all roof locations



Area 3— Anomaly  
Apparent exposed membrane at roof drains



Area 3— Anomaly  
Damaged strip-in at edge metal



Area 3— Anomaly  
Open sealant at expansion joint termination



Area 3a—Overview



Area 3a —Overview




Area 3a —Overview




Area 3a —Anomaly  
Splice lap is delaminating along the edge at most locations.



Area 3a —Anomaly  
Refrigerant pipe insulation extends into pourable sealer



Area 3a —Anomaly  
Open membrane laps around roof drain flashings



Area 3b —Overview



Area 3b —Overview



Area 3b —Overview  
Some areas indicate membrane sheet was overheated when installed.



Area 4 —Overview



Area 4 —Overview



Area 4 — Overview



Area 4—Overview



Area 4—Overview



Area 4— Overview



Area 4 — Overview



Area 4 — Overview



Area 4 — Anomaly  
Expansion joint is deteriorated



Area 4 — Anomaly  
Pipe penetrations are clustered



Area 4 — Anomaly  
Base flashings are damaged around curb unit



Area 4 — Anomaly  
Apparent restricted roof drain with missing drain strainer



Area 5 — Overview



Area 5 — Overview



Area 5 — Overview



Area 5— Overview



Area 5—Anomaly  
Apparent exposed membrane areas



Area 5—Anomaly  
Excessive gravel buildup at roof's perimeter



Area 5 — Anomaly  
Open metal work at wall transitions



Area 5 — Anomaly  
Loose base flashings along wall



Area 5a — Overview



Area 5a—Overview



Area 5a—Anomaly  
Some areas of membrane were installed with excessive wrinkles in the sheet



Area 5b — Overview



Area 5b — Overview



Area 5b — Anomaly  
Open expansion joint corner (sealant)



Area 5b—Anomaly  
Open expansion joint corner (sealant) and some areas of membrane were installed with excessive wrinkles in the sheet



Area 5b — Anomaly  
View of wrinkle in sheet between roof drains



Area 5c — Overview



Area 5c — Overview  
NOTE: Roof area appears to be in satisfactory condition



Area 6a — Overview



Area 6a — Overview



Area 6a — Anomaly  
Pipe penetration pockets are clustered with deteriorated fillers (typical)





Area 6a — Observation  
Brick work deteriorating from moisture intrusion



Area 6b — Overview



Area 6b — Overview



Area 6b — Anomaly  
Some voids in the flashing laps were identified



Area 7 — Overview



Area 7 — Anomaly  
Some exposed membrane was observed around roof drains



Area 7 — Anomaly  
Some splits in the strip-in flashings were observed around the perimeter



Area 7 — Anomaly  
Some exposed membrane was observed around roof drains



Area 8 — Overview



Area 8 — Overview



Area 8 — Anomaly  
Open terminations were observed along with open inside corners on sheet metal work



Area 8 — Observation  
Wall joints sealants are deteriorated



Area 9 — Overview



Area 9 — Overview



Area 9 — Anomaly  
Base flashings are in poor/deteriorated condition



Area 9 — Anomaly  
Base flashings are in poor/deteriorated condition



Area 9 — Observation  
Brick work damage at coping termination



Area 9 — Anomaly  
Physical damage was observed at the metal coping



Area 9a — Overview



Area 9a — Overview / Observation  
Membrane has many wrinkles in the sheet



Area 9b — Overview



Area 9b — Overview



Area 9b — Overview



Area 9b — Overview



Area 9b — Overview



Area 9b — Overview



Area 9b — Anomaly  
Appears cricket was not installed during the installation



Area 9b — Anomaly  
Plastic conduits are not recommended to penetrate a penetration pocket



Area 9b — Overview  
Gutter detail on penthouse roof



Area 9b — Overview  
Solar panels



Area 9c & d — Overview



Area 9c & d — Overview



Area 9c & d — Overview



Area 10 — Overview



Area 10 — Overview



Area 10 — Overview



Area 10 — Overview



Area 10 — Overview



Area 10 — Anomalies  
Sealants deteriorating at expansion joint transitions



Area 10 — Anomalies  
Sealants deteriorating at expansion joint transitions



Area 10 — Anomaly  
Penetration pipes mastic deteriorating are clustered along with



Area 11 — Overview



Area 11 — Overview



Area 11 — Overview



Area 11 — Anomaly  
Several areas of exposed membrane



Area 11 — Overview of wall transitions



Area 12 — Overview



Area 12 — Overview





Area 12—Overview



Area 12 — Anomaly  
Damaged base flashing



Area 12 — Anomaly  
Expansion joint damage



Area 13— Overview



Area 13 — Overview



Area 13 — Overview



Area 13 — Anomaly  
Base flashings loose at inside corner



Area 13 — Observation  
Ponding water at base of A/C unit



Area 13 — Anomaly  
Wall joint open at edge metal to expansion joint transition



Area 14 — Overview



Area 14 — Overview



Area 14 — Overview



Area 14 — Overview



Area 14 — Anomaly  
Exposed membrane was observed in many areas around the perimeter edge metal



Area 15 — Overview



Area 15 — Overview



Area 15 — Anomaly  
Expansion joint did not extend to roof edge causing split in membrane



Area 15 — Observations  
Major repair was conducted around large A/C unit



Area 16 — Overview



Area 16 — Overview



Area 16 — Anomaly  
Expansion joint did not adequately extend to roof edge




Area 16 — Anomaly  
Expansion joint open at the roof edge



Area 16 — Anomaly  
Expansion joint did not extend to roof edge



Area 16 — Anomaly  
Exposed membrane at some areas around the perimeter



Area 17 — Overview



Area 17 — Overview



Area 17 — Anomaly  
Expansion joint did not extend to roof edge causing split in membrane



Area — anomaly  
Exposed membrane was observed around roof drain areas



Area 17 — Overview



Area 17 — Overview



Area 18—Overview



Area — Anomaly  
Expansion joint did not extend correctly to roof edge causing splits in membrane



Area — Anomaly  
Expansion joint did not extend to roof edge causing split in membrane



Area 18 — Anomaly  
Expansion joint did not extend correctly to roof edge causing split in membrane



Area 18 — Anomaly  
Expansion joint did not extend correctly to roof edge causing split in membrane



Area 18 — Anomaly  
Exposed membrane was observed around roof drain areas



Area 19 — Overview



Area 19 — Overview



Area 19 — Overview



Area 19 — Anomaly  
Open end on expansion joint termination



Area 19 — Anomaly  
Expansion joint cover is deteriorated



Area 20 — Overview



Area 20 — Overview



Area 20 — Anomaly  
Expansion joint cover strips are loose



Area 20 — Anomaly  
Drain flashings membrane is exposed



Area 20 — Anomaly  
Expansion joint does not correctly terminate to the perimeter edge



Area 20 — Anomaly  
Expansion joint transitions are in poor condition



Area 21 — Overview





Area 21— Overview



Area 21— Overview



Area 21— Anomaly  
Poor termination design at expansion joint transition



Area 21— Anomaly  
Base flashings are on poor condition




Area 21— Anomaly  
Several open cover strips at window area



Area 21— Anomaly  
Some areas of exposed membrane at roof drains



Area 21— Anomaly  
Poor expansion joint tie-in at wall



Area 21— Observation  
Sealant at wall joints are deyeriorated



Area 22 — Overview



Area 22 — Overview



Area 22 — Overview



Area 22 — Overview



Area 22 — Anomaly  
Repairs are in poor condition at penetration removal area



Area 22—anomaly  
Insulated pipe installed into penetration pocket



Area 23— Overview



Area 23— Overview



Area 23— Anomaly  
Expansion joint cover strips are delaminating



Area 23—Anomaly  
Expansion joint does not terminate to the perimeter edge



Area 24 — Overview



Area 24 — Overview



Area 24 — Overview



Area 24 — Overview



Area 24—Anomaly  
Expansion joint does not terminate to the perimeter edge



Area 24—Anomaly  
Some areas of exposed membrane at roof drains



**Area 24—Anomaly**  
Several open cover strips at window area



**Area 24—Observation**  
Base flashing terminations appear to be in satisfactory condition



**Area 25—Overview**



**Area 25—Overview**



**Area 25—Anomaly**  
Base flashings are loose at perimeter wall



**Area 25—Anomaly**  
Base flashings are loose at perimeter wall



Area 26—Overview



Area 26—Overview

GYMNASIUM ROOF AREAS



Gymnasium Area 1—Overview



Gymnasium Area 1—Overview



Gymnasium Area 1—Overview



Gymnasium Area 1—Overview



Gymnasium Area I—Overview



Gymnasium Area I—Overview



Gymnasium Area I—Overview



Gymnasium Area I—Overview



Gymnasium Area I—Overview



Gymnasium Area I—Anomaly  
Some pipe boots are deteriorated with delaminating splices



Gymnasium Area 1—Anomaly  
Plastic coated conduits are not recommended for penetration pockets



Gymnasium Area 1—Anomaly  
Many splice patches are delaminating



Gymnasium Area 1—Overview  
Lower roof area



Gymnasium Area 1—Overview  
Scupper detail appears in satisfactory condition



Gymnasium Area 2—Overview



Gymnasium Area 2—Overview





Gymnasium Area 2—Overview



Gymnasium Area 2—Overview



Gymnasium Area 2—Overview



Gymnasium Area 2—Overview



Gymnasium Area 2—Overview



Gymnasium Area 2—Anomaly  
Many splice are delaminating



Gymnasium Area 2— Anomaly  
Termination splices at perimeter edges are delaminating at their edges



Gymnasium Area 3— Overview



Gymnasium Area 3— Overview



Gymnasium Area 3— Anomaly  
Exposed membrane was observed around roof drain



Gymnasium Area 4— Overview



Gymnasium Area 4— Overview



Gymnasium Area 4— Observation  
View of base flashings under cantilever



Gymnasium Area 4— Anomaly  
View of open base flashing along outside wall



Gymnasium Area 5 — Overview



Gymnasium Area 5 — Overview



Gymnasium Area 5 — Anomaly  
Exposed membrane was observed at roof drain



Gymnasium Area 5 — Observation  
Expansion joint detail does not extend to outside edge



Gymnasium Area 6 — Overview



Gymnasium Area 6 — Overview



Gymnasium Area 6 — Overview



Gymnasium Area 6 — Observation  
Expansion joint does not extend to the outside edge



Gymnasium Area 5 — Observation  
View of expansion joint termination



Gymnasium Area 5 — Anomaly  
Exposed membrane observed at roof drain





Smith MS  
Addison Rd., Glastonbury, CT

**Glastonbury School District - Smith Middle School | 2009**



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Anomaly  
Low flashing height with topical repairs



Area 1—Observation  
View of expansion joint at wall transition

# Glastonbury School District - Smith Middle School | 2009



Area 2—Overview



Area 2—Overview



Area 2—Observation  
View of roof tie-in transition



Area 3—Overview



Area 3—Observation  
Built-up roof to shingle roof transition



Area 3—Observation  
Built-up roof to shingle roof transition



# Glastonbury School District - Smith Middle School | 2009



Area 4—Overview



Area 4—Overview



Area 4—Overview



Area 5 – Overview



Area 5 – Overview



Area 5 – Overview

# Glastonbury School District - Smith Middle School | 2009



Area 5 - Overview



Area 5 - Overview



Area 5 - Overview



Area 5 - Overview



Area 5 - Overview



Area 5 - Observation  
Built-up roof to shingle roof transition

# Glastonbury School District - Smith Middle School | 2009



Area 5 —Observation  
Built-up roof to shingle roof transition



Area 5 —Observation  
Built-up roof to shingle roof transition



Area 5 —Observation  
Built-up roof to shingle roof transition



Area 6 —Overview



Area 6 —Overview



Area 6 —Overview

# Glastonbury School District - Smith Middle School | 2009



Area 6—Overview



Area 6—Observation  
Built-up roof gravel edge detail



Area 6—Observation  
Poor base flashing detail



Area 6—Observation  
Poor base flashing detail (close-up)



Area 7—Overview



Area 7—Overview

# Glastonbury School District - Smith Middle School | 2009




Area 7—Overview



Area 7—Overview



Area 7—Overview



Area 7—Overview



Area 7—Overview



Area 7—Overview

# Glastonbury School District - Smith Middle School | 2009



Area 7—Overview



Area 7—Overview



Area 7—Overview



Area 7—Overview



Area 7—Overview



Area 7—Observation  
Built-up roof gravel edge to expansion joint detail

Glastonbury School District - Smith Middle School | 2009



Area 8—Overview



Area 8—Overview



Area 8—Overview



Area 8—Overview



Area 8—Overview



Area 8—Overview

# Glastonbury School District - Smith Middle School | 2009



Area 8—Overview



Area 8—Overview



Area 8—Overview



Area 8—Overview



Area 8—Overview



Area 8—Overview





Area 8—Observation  
Built-up roof gravel edge and expansion joint detail



Area 8— Observation  
View of typical base flashing detail



Area 8—Observation  
Built-up roof gravel edge detail



Area 8—Observation  
Built-up roof to asphalt shingle transition



Area 8—Observation  
View of pitch pocket detail



Area 9—Overview

# Glastonbury School District - Smith Middle School | 2009



Area 9—Overview



Area 9—Overview



Area 9—Anomaly  
Missing drain strainers



Area 9—Anomaly  
Poor tie-in detail at built-up to shingle transition



Area 9—Anomaly  
Poor tie-in detail at built-up to shingle transition



Area 10—Overview

# Glastonbury School District - Smith Middle School | 2009



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview

# Glastonbury School District - Smith Middle School | 2009



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview

Glastonbury School District - Smith Middle School | 2009



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Overview

Glastonbury School District - Smith Middle School | 2009



Area 10—Overview



Area 10—Overview



Area 10—Overview



Area 10—Anomaly  
Clustered pipe conduits




Area 10—Anomaly  
Poor base flashing detail at transition



Area 10—Anomaly  
Poor base flashing detail at transition





Naubus ES  
Griswold St., Glastonbury, CT





Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Overview



Area 1—Observation  
Perimeter edge metal



Area 1—Anomaly  
Broken drain strainer along with exposed membrane felts



Area 1—Observation  
Outside perimeter edge repaired



Area 1— Observation  
Repair patch installed beneath unit



Area 1— Anomaly  
Tie-in on repair beginning to deteriorate



Area 1— Anomaly  
Tie-in on repair beginning to deteriorate



Area 1—Anomaly  
Exposed membrane felts around roof drains



Area 2— Overview



Area 2— Overview



Area 2— Overview



Area 2— Anomaly  
Scupper metal damaged



Area 2— Anomaly  
Scupper metal damaged



Area 2— Observation  
Limited flashing access



Area 2— Anomaly  
Poor termination at Area 2 to Area 3 roof areas



Area 3—Overview



Area 3—Overview



Area 3—Overview



Area 3—Overview



Area 3—Anomaly  
Poor expansion joint detail with open laps



Area 3—Anomaly  
Poor expansion joint detail with open laps



Area 3—Anomaly  
Low counter flashing trim



Area 3—Anomaly  
Broken drain strainer



Area 3—Anomaly  
Open expansion joint laps



Area 4—Overview



Area 4—Overview



Area 4—Overview



Area 4—Overview



Area 4—Anomaly  
Cracked cementitious board on skylight



Area 4—Anomaly  
Cracked cementitious board on skylight



Area 4— Observation  
View of transition flashing



Area 4—Anomaly  
Damaged curb flashing a support stand



Area 4—Anomaly  
Support screwed into roof system



Area 5—Overview



Area 5—Overview



Area 5—Overview  
NOTE: Roof gravel was cleaned from roof surface



Area 5—Anomaly  
Splice patches delaminating from membrane



Area 5—Observation  
Roof termination



Area 5—Observation  
Roof termination



Area 6—Overview



Area 6—Overview



Area 6—Overview



Area 6—Overview



Area 6—Anomaly  
Splice patches over expansion joints are delaminating



Area 6—Observation  
View of roof termination at wall





Area 6—Overview



Area 6—Overview



Area 6—Overview



Area 6—Overview



Area 6—Anomaly  
Hip to ridge shingle was resealed at both locations



Area 6—Anomaly  
Ridge vent was resecured



Area 8—Overview



Area 8—Overview



Area 9—Overview



Area 9—Overview



Area 10—Overview



Area 10—Observation  
View of roof termination at drip edge



Area 10—Observation  
View of roof termination at wall flashing



Area 10—Observation  
View of roof termination at wall flashing



Area 11—Overview



Area 11—Overview



Area 11—Overview



Area 11—Overview



Area 11—Overview



Area 11—Observation  
View of roof termination at wall



Area 11—Overview



Area 11—Overview



Area 11—Anomaly  
Missing drain strainer



Area 11—Anomaly  
Missing curb flashing



Area 11—Anomaly  
Roof repair is showing indications of deterioration




Area 12—Overview




Area 12—Overview



Area 12—Anomaly  
Turbine vent is broken



Area 12—Anomaly  
Strip-in repair indicating signs of deterioration



Area 12—Anomaly  
Chimney mortar joints in need to repair



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview



Area 13—Overview

NOTE: Ridge to hip transition shingle were sealed

WALL ELEVATION PHOTOGRAPHS



View of unsecured metal caps (typical)  
NOTE: Contractor secured all metal caps



Mortar joints appear to be deteriorating



Some damaged brick was observed



Window perimeter sealants in poor condition





Damaged brick observed



Wall joints in need of repair



Option No. 3—Metal cap repairs (typ.)



Option No. 3—Metal cap repairs (typ.) NOTE: Metal caps secured around perimeter of building.