

REVISED SURVEY REPORT

**PRE-RENOVATION
INVESTIGATIVE SURVEY FOR
HAZARDOUS BUILDING MATERIALS**

**BROOKFIELD MAINTENANCE FACILITY
MAIN BUILDING
BROOKFIELD, CONNECTICUT
Project No. 34-350**

Prepared for

**State of Connecticut
Department of Transportation**
Newington, Connecticut

Prepared by

TRC
Windsor, Connecticut

REVISED
January 2019

**PRE-RENOVATION
INVESTIGATIVE SURVEY FOR
HAZARDOUS BUILDING MATERIALS**

**BROOKFIELD MAINTENANCE FACILITY
MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Project No. 34-350

Prepared for
State of Connecticut
Department of Transportation
Newington, Connecticut

Prepared by
TRC
Windsor, Connecticut

Erik R. Plimpton, P.E., CHMM, CMC
Vice President – Program Manager

Edmund J. Burke, P.E.
Engineer in Charge

TRC Project No. 222165.5616.0710
REVISED – January 2019

TRC
21 Griffin Road North
Windsor, Connecticut 06095
Telephone (860) 298-9692
Facsimile (860) 298-6380

TABLE OF CONTENTS

PROJECT OUTLINE

TABLES

- 1 BULK SAMPLE SUMMARY OF SUSPECT ASBESTOS CONTAINING MATERIALS
- 2 IDENTIFIED ASBESTOS CONTAINING MATERIALS
- 3 CONFIRMED NON-ASBESTOS CONTAINING MATERIALS
- 4 SUMMARY OF LEAD PAINT XRF MEASUREMENTS
- 5 SUMMARY OF COMPOSITE BUILDING MATERIAL WASTE CHARACTERIZATION
- 6 INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED MATERIALS,
WASTES AND ITEMS IDENTIFIED
- 7 BULK SAMPLE SUMMARY OF SUSPECT PCB CONTAINING CAULK
MATERIALS
- 8 IDENTIFIED PCB CONTAINING CAULK MATERIALS

APPENDICES

- A SITE PHOTOS WITH DOT ASSIGNMENT AND MAP
- B SITE SKETCHES
- C TRC INSPECTORS LICENSES/CERTIFICATIONS
- D LABORATORY ACCREDITATIONS
- E TRC ASBESTOS BULK SAMPLE CHAIN OF CUSTODY FORMS
- F TRC ASBESTOS PLM LABORATORY ANALYSIS DATA
- G TRC ASBESTOS TEM LABORATORY ANALYSIS DATA
- H TRC LEAD PAINT XRF MEASUREMENT TABLE
- I COMPOSITE BUILDING MATERIAL WASTE CHARACTERIZATION DATA
- J PCB CAULK/GLAZE LABORATORY ANALYSIS DATA
- K ITEMIZED COST ESTIMATE FOR ASBESTOS ABATEMENT
- L HAZARDOUS/REGULATED MATERIALS, WASTES AND ITEMS REMOVAL
COST ESTIMATE
- M PRIOR HAZMAT INSPECTION DATA
- N RELATED CORRESPONDENCE

PROJECT OUTLINE

DOT Project No.: 34-350
Assignment No.: 514-5616
DOT Project Manager: Michael F. Bedson, EIT

Site Address: Brookfield Maintenance Facility – Main Building
1050 Federal Road, Brookfield, CT

TRC Project No.: 222165.5616.0710
Asbestos Inspector: Thomas Martin (LIC #000014)
Kelly Grey (LIC #000320)
Lead Inspector: Kelly Grey (LIC #002267)
Environmental Technical Assistant: Zachary Smith/Carmen Jacko
Date(s) of Inspection: 7/3/17-7/6/17 & 11/29/18

Asbestos Identified: Yes
Lead Paint Identified: Yes
Gen. Bldg. Mat. Haz Waste: No
Add'l Haz./Reg. Mat./Waste/Items: Yes (See Table 6)
EPA PCB Bulk Product Waste
Caulk: No
CTDEEP State Regulated PCB
Caulk: Yes

Asbestos Removal Cost Estimate: \$ 2,270
Haz/Reg Materials/Wastes/Items Removal Cost Estimate: \$ 6,620

Additional Notes:

The property consists of a one-story brick garage maintenance building currently subject to future renovation. Associated motor fuel island and various fuel/waste oil underground storage tanks (USTs) are to be removed during a prior renovation project. Oil-water separator and tank monitoring system are to remain onsite. The building was still occupied at the time of the inspection; therefore utilities were not shut-off prior to arrival, including electric, gas, telephone, and municipal water source. Municipal sanitary system services the building. Hydraulic lifts/floor drains are located in various bays and groundwater monitoring wells (GWMW) can be found on the exterior A and D-sides of the building.

TABLES

**TABLE 1
BULK SAMPLE SUMMARY OF SUSPECT ASBESTOS CONTAINING MATERIALS
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Sample No.	Sample Location	Type of Homogeneous Material	% and Type Asbestos
2001 EnviroMed Bulk Sampling Data			
1	Ground floor Boiler Room/Chimney	Breeching cement (<i>no longer present at 2017 TRC inspection</i>)	5%
2	Ground floor Boiler Room/Chimney	Breeching cement (<i>no longer present at 2017 TRC inspection</i>)	50%
3	Ground floor Boiler Room/Chimney	Breeching cement (<i>no longer present at 2017 TRC inspection</i>)	5%
4	Ground floor – Generator Room	Mudded pipe joint insulation (<i>no longer present at 2017 TRC inspection</i>)	50%
5	Ground floor – Generator Room	Mudded pipe joint insulation (<i>no longer present at 2017 TRC inspection</i>)	50%
6	Ground floor – Generator Room	Mudded pipe joint insulation (<i>no longer present at 2017 TRC inspection</i>)	50%
7	Ground floor – Office 1	FT1 – 12x12 tan vinyl floor tile (<i>no longer present at 2017 TRC inspection</i>)	4%
8	Ground floor – Office 2	FT1 – 12x12 tan vinyl floor tile (<i>no longer present at 2017 TRC inspection</i>)	5%
9	Ground floor – Office 1	FT1 – mastic under 12x12 tan vinyl floor tile (<i>no longer present at 2017 TRC inspection</i>)	NAD
10	Ground floor – Office 2	FT1 – mastic under 12x12 tan vinyl floor tile (<i>no longer present at 2017 TRC inspection</i>)	<1%
11	Ground floor – Office 1	CB1 – 4" brown cove molding (<i>no longer present at 2017 TRC inspection</i>)	NAD
12	Ground floor – Office 2	CB1 – 4" brown cove molding (<i>no longer present at 2017 TRC inspection</i>)	NAD
13	Ground floor – Office 1	CB1 – glue behind 4" brown cove molding	NAD
14	Ground floor – Office 2	CB1 – glue behind 4" brown cove molding	NAD
15	Ground floor – Office 1	CT1 – 2x4 suspended ceiling tile (with worms & holes)	NAD
16	Ground floor – Office 2	CT1 – 2x4 suspended ceiling tile (with worms & holes)	NAD
17	Ground floor – Bays 12 & 13 window	RW – window glazing (type I) (<i>no longer present at 2017 TRC inspection</i>)	NAD

NA/PVA Not analyzed/positive via inseparable association with a confirmed positive ACM

NA/PS Not analyzed/positive stop, homogeneous to sample proven to contain asbestos

ND<1% Non-detected, less than 1%

NAD No asbestos detected

+ Although found to be negative by analysis, material is homogeneous to a determined ACM and therefore must be considered positive

1 Result confirmed by TEM analyses

* Quantified by PLM Point Counting techniques

**TABLE 1 (continued)
BULK SAMPLE SUMMARY OF SUSPECT ASBESTOS CONTAINING MATERIALS
BROOKFIELD MAINTENANCE FACILITY - MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Sample No.	Sample Location	Type of Homogeneous Material	% and Type Asbestos
18	Ground floor - Bay 9 window	RW - window glazing (type I) <i>(no longer present at 2017 TRC inspection)</i>	NAD
19	Ground floor- Bay 1 window	RW - window glazing (type I) <i>(no longer present at 2017 TRC inspection)</i>	NAD
20	Ground floor - Bays 12 & 13 window	RW - window glazing (type II) <i>(no longer present at 2017 TRC inspection)</i>	NAD
21	Ground floor - Bay 9 window	RW - window glazing (type II) <i>(no longer present at 2017 TRC inspection)</i>	NAD
22	Ground floor- Bay 3 window	RW - window glazing (type II) <i>(no longer present at 2017 TRC inspection)</i>	NAD
23	Ground floor - Office 1 window	WG1 - window glazing (type III)	NAD
24	Ground floor - Office 1 window	WG1 - window glazing (type III)	NAD
25	Ground floor - Office 1 window	WG1 - window glazing (type III)	NAD
26	Ground floor- Women's Room window	Window glazing (type IV) <i>(no longer present at 2017 TRC inspection)</i>	NAD
27	Ground floor - Men's Room window	Window glazing (type IV) <i>(no longer present at 2017 TRC inspection)</i>	NAD
28	Ground floor - Office 1 window	Window glazing (type IV) <i>(no longer present at 2017 TRC inspection)</i>	NAD
29	<i>Void</i>	<i>Void</i>	<i>Void</i>
30	<i>Void</i>	<i>Void</i>	<i>Void</i>
31	Ground floor - Office 1	C1 - door frame caulking	NAD
32	Ground floor - Hall	C1 - door frame caulking	NAD
33	Roof 2	Patching cement <i>(gone as of 2017)</i>	10%
34	Roof 1	Patching cement <i>(gone as of 2017)</i>	12%
35	Roof 2 wall	Flashing cement	45%
36	Roof 3 wall	Flashing cement	40%
37	Roof 2 edge	Flashing cement	45%
38	Roof 1 edge	Flashing cement	30%
39	Roof 2 counter flashing	Brown caulking <i>(gone as of 2017)</i>	NAD
40	Roof 1 parapet cap	Brown caulking <i>(gone as of 2017)</i>	NAD

NA/PVA Not analyzed/positive via inseparable association with a confirmed positive ACM

NA/PS Not analyzed/positive stop, homogeneous to sample proven to contain asbestos

ND<1% Non-detected, less than 1%

NAD No asbestos detected

+ Although found to be negative by analysis, material is homogeneous to a determined ACM and therefore must be considered positive

† Result confirmed by TEM analyses

* Quantified by PLM Point Counting techniques

**TABLE 1 (continued)
BULK SAMPLE SUMMARY OF SUSPECT ASBESTOS CONTAINING MATERIALS
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Sample No.	Sample Location	Type of Homogeneous Material	% and Type Asbestos
41	Roof 2	Built-up roofing material – top layer <i>(gone as of 2017)</i>	NAD
42	Roof 2	Built-up roofing material – second layer <i>(gone as of 2017)</i>	NAD
43	Roof 2	Built-up roofing material – third layer <i>(gone as of 2017)</i>	NAD
44	Roof 2	Built-up roofing material – fourth layer <i>(gone as of 2017)</i>	NAD
45	Roof 2	Built-up roofing material – fifth layer <i>(gone as of 2017)</i>	NAD
46	Roof 2	Built-up roofing material – sixth layer <i>(gone as of 2017)</i>	NAD
47	Roof 2	Built-up roofing material – seventh layer <i>(gone as of 2017)</i>	NAD
48	Roof 2	Built-up roofing material – bottom layer <i>(gone as of 2017)</i>	NAD
49	Roof 1	Built-up roofing material – top layer <i>(gone as of 2017)</i>	NAD
50	Roof 1	Built-up roofing material – second layer <i>(gone as of 2017)</i>	NAD
51	Roof 1	Built-up roofing material – third layer <i>(gone as of 2017)</i>	NAD
52	Roof 1	Built-up roofing material – fourth layer <i>(gone as of 2017)</i>	NAD
53	Roof 1	Built-up roofing material – fifth layer <i>(gone as of 2017)</i>	NAD
54	Roof 1	Built-up roofing material – sixth layer <i>(gone as of 2017)</i>	NAD
55	Roof 1	Built-up roofing material – seventh layer <i>(gone as of 2017)</i>	NAD
56	Roof 1	Built-up roofing material – eighth layer <i>(gone as of 2017)</i>	NAD
57	Roof 1	Built-up roofing material – bottom layer <i>(gone as of 2017)</i>	NAD
58	Ground floor – Locker Room	SHR 1 – wallboard/sheetrock	NAD
59	Ground floor – Locker Room	SHR 1 – wallboard/sheetrock	NAD

NA/PVA Not analyzed/positive via inseparable association with a confirmed positive ACM

NA/PS Not analyzed/positive stop, homogeneous to sample proven to contain asbestos

ND<1% Non-detected, less than 1%

NAD No asbestos detected

+ Although found to be negative by analysis, material is homogeneous to a determined ACM and therefore must be considered positive

1 Result confirmed by TEM analyses

* Quantified by PLM Point Counting techniques

**TABLE 1 (continued)
BULK SAMPLE SUMMARY OF SUSPECT ASBESTOS CONTAINING MATERIALS
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Sample No.	Sample Location	Type of Homogeneous Material	% and Type Asbestos
60	Ground floor – Locker Room	SHR1 – wallboard/joint compound	NAD
61	Ground floor – Locker Room	SHR1 – wallboard/joint compound	NAD
62	Ground floor – Locker Room	SHR1 – wallboard/joint compound	NAD
2017 TRC Confirmation/Supplemental Bulk Sampling Data			
1	Bay 4 loft	CP11 – white fiberglass end sealant	ND
2	Women's room	CP11 – white fiberglass end sealant	ND
3	Office 2	PI1 – paper/foil/tar pipe insulation wrap on fiberglass 1" line	ND
4	Bay 4 loft	PI1 – paper/foil/tar pipe insulation wrap on fiberglass 1" line	ND
5	Bay 9	PI1 – paper/foil/tar pipe insulation wrap on fiberglass 1" line	ND
6	Generator room	DWG1 – sticky, grey door window glaze	ND
7	Generator room	DWG1 – sticky, grey door window glaze	ND ¹
8	Bay 5	DWG2 – black, soft door window glaze	ND
9	Bay 5	DWG2 – black, soft door window glaze	ND ¹
10	Bay 4	DWG3 – black, pliable door window glaze	ND
11	Bay 4	DWG3 – black, pliable door window glaze	ND ¹
12	Library	FJ1 – black, tar-like floor expansion joint material	ND
13	Bay 13	EJ1 – black, tar-like floor expansion joint material	Trace chrysotile ¹
14	Bay 13	EJ2 – brown, fibrous floor expansion joint material	ND
15	Bay 11	EJ2 – brown, fibrous floor expansion joint material	ND
16	Office 1	C1 – white, flexible door caulk	Trace chrysotile ¹
17	Exterior – D side o/s Generator Room	C2 – exterior, beige brittle vent caulk	3% chrysotile
18	Exterior – D side o/s Generator Room	C2 – exterior, beige brittle vent caulk	NAPS

NA/PVA Not analyzed/positive via inseparable association with a confirmed positive ACM

NA/PS Not analyzed/positive stop, homogeneous to sample proven to contain asbestos

ND<1% Non-detected, less than 1%

NAD No asbestos detected

+ Although found to be negative by analysis, material is homogeneous to a determined ACM and therefore must be considered positive

¹ Result confirmed by TEM analyses

* Quantified by PLM Point Counting techniques

**TABLE 1 (continued)
 BULK SAMPLE SUMMARY OF SUSPECT ASBESTOS CONTAINING MATERIALS
 BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
 BROOKFIELD, CONNECTICUT**

Sample No.	Sample Location	Type of Homogeneous Material	% and Type Asbestos
19	Office 1	WG1 – interior, brittle grey window glazing on 9 pane metal sash windows	Trace chrysotile ¹
20	Office 1	G1 – tan glue associated with former covebase in Offices 1 & 2	ND ¹

NA/PVA Not analyzed/positive via inseparable association with a confirmed positive ACM

NA/PS Not analyzed/positive stop, homogeneous to sample proven to contain asbestos

ND<1% Non-detected, less than 1%

NAD No asbestos detected

+ Although found to be negative by analysis, material is homogeneous to a determined ACM and therefore must be considered positive

¹ Result confirmed by TEM analyses

* Quantified by PLM Point Counting techniques

**TABLE 2
 IDENTIFIED ASBESTOS CONTAINING MATERIALS (>1%)
 BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
 BROOKFIELD, CONNECTICUT**

Material	Sampled/ Assumed (mo/yr)	General Location	NESHAP Category	AHERA Category	Estimated Quantity
Flashing cement	3/01 EnviroMed	Remnants remaining on Roof 1 HVAC	Category I Non-friable	Miscellaneous	4 SF
C2 – exterior, beige brittle vent caulk	7/17 TRC	Exterior – D side o/s Generator Room	Category II Non-friable	Miscellaneous	8 LF (1 vent)

AHERA Categories = thermal system insulation (TSI), surfacing material or miscellaneous
 NESHAP Categories = friable, category I non-friable or category II non-friable
 Friable = crumbled, pulverized or reduced to powder by hand pressure when dry
 Category I Non-friable = packings, gaskets, resilient floor covering and asphalt roofing
 Category II Non-friable = all non-friable that is not Category I

**TABLE 3
 CONFIRMED NON-ASBESTOS CONTAINING MATERIALS (<1%)
 BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
 BROOKFIELD, CONNECTICUT**

Material	General Location
CT1 – 2x4 suspended ceiling tile (with worms & holes)	Ground floor – Offices 1 & 2
WG1 – window glazing (type III)	Ground floor – Office 1 windows
C1 – door frame caulking	Ground floor – Hall, Office 1, Office 2, Boiler Room, Bay 4 interior of door, Bay 9 door to exterior, exterior Bay 1 around electrical outlet, exterior Boiler Room above upper vent, exterior Bay 9, exterior Bay 10 around conduit
SHR1 – wallboard/sheetrock & joint compound	Ground floor – Locker Room, Library
CP11 – white fiberglass end sealant	Men's Room, Women's Room, Bay 1, Bay 4 loft, Bay 10
PI1 – paper/foil/tar pipe insulation wrap on fiberglass 1" line	Office 2, Bay 4 loft, running length of Bay 4 through Bay 9, Bay 10, Bay 1, Bay 2, Bay 3, Men's Room, Women's Room, Hallway
DWG1 – sticky, gray door window glaze	Generator Room exterior door, Bay 1 door to exterior, Bay 9 door to exterior
DWG2 – black, soft door window glaze	Bay 5 door to Bay 10, Bay 13 door to exterior
DWG3 – black, pliable door window glaze	Bay 4
EJ1 – black, tar-like floor expansion joint material	Bay 1, Bay 3, Bay 10, Bay 13, Library
EJ2 – brown, fibrous floor expansion joint material	Bays 1-13
CB1/G1 – tan glue associated with former cove base in Offices 1 & 2	Office 1, Office 2 (remnants)

* However, associated layers are positive.

**TABLE 4
SUMMARY OF LEAD PAINT XRF MEASUREMENTS
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Structure	No. of Measurements	Calibrations	Void	Lead Detected	No Lead Detected
2011 EnviroMed XRF Measurements Maintenance Facility Main Building	186	5	0	95	86
2017 TRC Confirmation/Verification XRF Measurements Maintenance Facility Main Building	214	9	0	80	125

See Lead Paint XRF Measurement Table in Appendix H.

TABLE 5
SUMMARY OF COMPOSITE BUILDING MATERIAL WASTE CHARACTERIZATION
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT

Waste Stream	Metal	mg/L Leachate	Hazardous/Non-Hazardous
Bays 10, 11, 12 Bldg. Material Composite (Excluding metal substrates)	Arsenic	---	Analyte not tested
	Barium	---	Analyte not tested
	Cadmium	---	Analyte not tested
	Chromium	---	Analyte not tested
	Lead	1.9	Non-Hazardous
	Mercury	---	Analyte not tested
	Selenium	---	Analyte not tested
	Silver	---	Analyte not tested

The sample was analyzed following the Toxicity Characteristic Leaching Procedure (TCLP) for the Resource Conservation Recovery Act (RCRA) Metals most likely to be present in this type of structure. The sample was a composite of wood, wallboard, brick, flooring, roofing and other building materials and was collected per CTDEEP sampling guidelines in approximate percent by weight proportions to represent the building as a whole. The sample did not include any metal components, as metal items should be recycled to promote waste minimization efforts, rather than disposed of, and the recycling operation is exempt from the USEPA RCRA and CTDEEP Hazardous Waste regulations. In most instances, the sample will not include foundation materials (concrete/stone/etc.), as these materials are used as clean fill during the demolition process and are therefore not part of the waste disposal stream.

See Appendix I for results.

BDL - Below Detection Limit

ND - Not Detected

**TABLE 6
INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED
MATERIALS, WASTES AND ITEMS IDENTIFIED
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Quantity	Size	Material/Item	General Location	Potential Hazard
Eight (8)		Halogen lights	Bay 1	UW – Hg lamps
Three (3)		HID lights	Bay 1	UW – Hg lamps
One (1)		Illuminated exit sign	Bay 1	UW – used electronics (printed circuit boards) UW – Hg lamp
One (1)		Fire extinguisher	Bay 1	CRW – waste chemical solid
Four (4)		Halogen lights	Bay 2	UW – Hg lamps
Three (3)		Fluorescent lights	Bay 2	UW – Hg lamps
Three (3)		HID lights	Bay 2	UW – Hg lamps
One (1)		Fire extinguisher	Bay 2	CRW – waste chemical solid
Four (4)		Halogen lights	Bay 3	UW – Hg lamps
Six (6)		HID lights	Bay 3	UW – Hg lamps
One (1)		Illuminated exit sign	Bay 3	UW – used electronics (printed circuit boards) UW – Hg lamp
One (1)		Fire extinguisher	Bay 3	CRW – waste chemical solid
One (1)		Thermostat	Bay 3	UW – Hg ampoule
One (1)		Refrigerator	Bay 4	CFCs/Freon
One (1)		Alarm control panel	Bay 4	UW – used electronics (printed circuit boards)
One (1)		Emergency light	Bay 4	UW – Hg lamps UW – used electronics (printed circuit boards) UW – batteries (Ni-Cd battery or Pb-acid battery)
One (1)		Thermostat	Bay 4	UW – Hg ampoule
One (1)		Exit sign	Bay 4	UW – used electronics (printed circuit boards) UW – Hg lamp

- CRW- Connecticut Regulated Waste – PCBs (CR01), Oils (CR02/CR03), waste chemical liquids - antifreeze, latex & solvent paints, sludges, etc. (CR04), waste chemical solids (CR05)
- UW- Universal Waste (batteries, thermostat ampoules, fluorescent lamps, used electronics)
- IH- Inhalation hazard (silicas, etc.)
- I- Ignitable - may contain ingredients which are ignitable (materials which have a flashpoint <140°F) (D001)
- C- Corrosive - may contain ingredients which are alkaline or acidic (materials with a PH<2 or >12.5) (D002)
- T- Toxic - may contain ingredients which are harmful if swallowed or which release vapors that can cause irritation
- R- Reactive – may contain ingredients which are unstable, react violently with water or are explosive (D003)

**TABLE 6 (continued)
INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED
MATERIALS, WASTES AND ITEMS IDENTIFIED
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Quantity	Size	Material/Item	General Location	Potential Hazard
Four (4)		4' fluorescent bulbs/ballast	Bay 4	UW – Hg lamps CRW – PCB ballasts
Two (2)		HID lights	Bay 4	UW – Hg lamps
Eight (8)		HID lights	Bays 5-9	UW – Hg lamps
Five (5)		Fluorescent lights	Bays 5-9	UW – Hg lamps
Thirty two (32)		4' fluorescent bulbs/ballast	Bays 5-9	UW – Hg lamps CRW – PCB ballasts
Two (2)		Halogen lights	Bays 5-9	UW – Hg lamps
One (1)		Hydraulic lift	Bay 8	CRW – hydraulic oil
One (1)		Hydraulic tank	Bay 8	CRW – hydraulic oil
One (1)		Exit sign	Bay 9	UW – used electronics (printed circuit boards) UW – Hg lamp
One (1)		GPS Remote Station	Bay 9	UW – used electronics (printed circuit boards)
One (1)		Hydraulic lift	Bay 9	CRW – hydraulic oil
One (1)		Hydraulic tank	Bay 9	CRW – hydraulic oil
Various		Floor drains	Bays 1, 2, 3, 4, 6, 7, 12	CRW – waste chemical liquid/sludge, RCRA sludge, PCB
Four (4)		4' fluorescent bulbs/ballast	Tool Room	UW – Hg lamps CRW – PCB ballasts
Eight (8)		4' fluorescent bulbs/ballast	Hallway	UW – Hg lamps CRW – PCB ballasts
One (1)		Fire extinguisher	Hallway	CRW – waste chemical solid
One (1)		Emergency light	Hallway	UW – Hg lamps UW – used electronics (printed circuit boards) UW – batteries (Ni-Cd battery or Pb-acid battery)

- CRW- Connecticut Regulated Waste – PCBs (CR01), Oils (CR02/CR03), waste chemical liquids - antifreeze, latex & solvent paints, sludges, etc. (CR04), waste chemical solids (CR05)
- UW- Universal Waste (batteries, thermostat ampoules, fluorescent lamps, used electronics)
- IH- Inhalation hazard (silicas, etc.)
- I- Ignitable - may contain ingredients which are ignitable (materials which have a flashpoint <140°F) (D001)
- C- Corrosive - may contain ingredients which are alkaline or acidic (materials with a PH<2 or >12.5) (D002)
- T- Toxic - may contain ingredients which are harmful if swallowed or which release vapors that can cause irritation
- R- Reactive – may contain ingredients which are unstable, react violently with water or are explosive (D003)

**TABLE 6 (a, continued)
INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED
MATERIALS, WASTES AND ITEMS IDENTIFIED
BROOKFIELD MAINTENANCE FACILITY - MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Quantity	Size	Material/Item	General Location	Potential Hazard
Four (4)		4' fluorescent bulbs/ballast	Men's Room	UW - Hg lamps CRW - PCB ballasts
Four (4)		4' fluorescent bulbs/ballast	Locker Room	UW - Hg lamps CRW - PCB ballasts
Two (2)		4' fluorescent bulbs/ballast	Library	UW - Hg lamps CRW - PCB ballasts
One (1)		Hand sanitizer	Library	CRW - waste chemical liquid
Two (2)		4' fluorescent bulbs/ballast	Women's Room	UW - Hg lamps CRW - PCB ballasts
One (1)		Exit sign	Bays 12 & 13	UW - used electronics (printed circuit boards) UW - Hg lamp
One (1)		Fire extinguisher	Bays 12 & 13	CRW - waste chemical solid
Three (3)		HID lights	Bays 12 & 13	UW - Hg lamps
One (1)		Emergency light	Bays 12 & 13	UW - Hg lamps UW - used electronics (printed circuit boards) UW - batteries (Ni-Cd battery or Pb-acid battery)
Fourteen (14)		4' fluorescent bulbs/ballast	Bays 12 & 13	UW - Hg lamps CRW - PCB ballasts
One (1)		Hydraulic tank	Bay 12	CRW - hydraulic oil
One (1)		Hydraulic lift	Bay 13	CRW - hydraulic oil
One (1)		Mercury thermostat	Office 1	UW - Hg ampoule
Four (4)		U-shaped fluorescent bulbs/ballasts	Office 1	UW - Hg lamps CRW - PCB ballasts
Four (4)		4' fluorescent bulbs/ballast	Office 1	UW - Hg lamps CRW - PCB ballasts
One (1)		Smoke detector	Office 1	UW - used electronics (printed circuit boards) Low-level radioactive waste

CRW- Connecticut Regulated Waste - PCBs (CR01), Oils (CR02/CR03), waste chemical liquids - antifreeze, latex & solvent paints, sludges, etc. (CR04), waste chemical solids (CR05)

UW- Universal Waste (batteries, thermostat ampoules, fluorescent lamps, used electronics)

IH- Inhalation hazard (silicas, etc.)

I- Ignitable - may contain ingredients which are ignitable (materials which have a flashpoint <140°F) (D001)

C- Corrosive - may contain ingredients which are alkaline or acidic (materials with a PH<2 or >12.5) (D002)

T- Toxic - may contain ingredients which are harmful if swallowed or which release vapors that can cause irritation

R- Reactive - may contain ingredients which are unstable, react violently with water or are explosive (D003)

**TABLE 6 (...continued)
INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED
MATERIALS, WASTES AND ITEMS IDENTIFIED
BROOKFIELD MAINTENANCE FACILITY - MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Quantity	Size	Material/Item	General Location	Potential Hazard
One (1)		Ceiling-mounted A/C	Office 1	CFCs/Freon
One (1)		Mercury thermostat	Office 2	UW - Hg ampoule
Four (4)		U-shaped fluorescent bulbs/ballasts	Office 2	UW - Hg lamps CRW - PCB ballasts
Four (4)		4' fluorescent bulbs/ballast	Office 2	UW - Hg lamps CRW - PCB ballasts
One (1)		Smoke detector	Office 2	UW - used electronics (printed circuit boards) Low-level radioactive source
One (1)		Ceiling-mounted A/C	Office 2	CFCs/Freon
One (1)		Emergency light	"Stores"/Bay 10	UW - Hg lamps UW - used electronics (printed circuit boards) UW - batteries (Ni-Cd battery or Pb-acid battery)
One (1)		Exit sign	"Stores"/Bay 10	UW - used electronics (printed circuit boards) UW - Hg lamp
One (1)		UST mgmt system	"Stores"/Bay 10	UW - used electronics (printed circuit boards)
Sixty (60)		4' fluorescent bulbs/ballast	"Stores"/Bay 10	UW - Hg lamps CRW - PCB ballasts
One (1)		Fire extinguisher	"Stores"/Bay 10	CRW - waste chemical solid
One (1)		Small refrigerator	"Stores"/Bay 10	CFCs/Freon
Four (4)		4' fluorescent bulbs/ballast	Bay 11	UW - Hg lamps CRW - PCB ballasts
One (1)		Fire extinguisher	Bay 11	CRW - waste chemical solid
One (1)		Smoke detector	Bay 11 (loft)	UW - used electronics (printed circuit boards) Low-level radioactive source
One (1)		HID light (overhead 2' diameter round)	Bay 11 (loft)	UW - Hg lamps

CRW- Connecticut Regulated Waste - PCBs (CR01), Oils (CR02/CR03), waste chemical liquids - antifreeze, latex & solvent paints, sludges, etc. (CR04), waste chemical solids (CR05)

UW- Universal Waste (batteries, thermostat ampoules, fluorescent lamps, used electronics)

IH- Inhalation hazard (silicas, etc.)

I- Ignitable - may contain ingredients which are ignitable (materials which have a flashpoint <140°F) (D001)

C- Corrosive - may contain ingredients which are alkaline or acidic (materials with a PH<2 or >12.5) (D002)

T- Toxic - may contain ingredients which are harmful if swallowed or which release vapors that can cause irritation

R- Reactive - may contain ingredients which are unstable, react violently with water or are explosive (D003)

**TABLE 6 (...continued)
INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED
MATERIALS, WASTES AND ITEMS IDENTIFIED
BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Quantity	Size	Material/Item	General Location	Potential Hazard
Ten (10)		Spare 4' fluorescent bulbs (no ballast)	Bay 11 (loft)	UW – Hg lamps
Four (4)		4' fluorescent bulbs/ballast	Boiler Room	UW – Hg lamps CRW – PCB ballasts
One (1)		Fire extinguisher	Mezzanine above Storage Room	CRW – waste chemical solid
Twenty six (26)		4' fluorescent bulbs/ballast	Mezzanine above Storage Room	UW – Hg lamps CRW – PCB ballasts
One (1)		HID light	Mezzanine above Storage Room	UW – Hg lamps
Two (2)		HVAC units	Roof 1	CFCs/Freon
One (1)		Exterior light	Bay 1 exterior	UW – Hg lamps
One (1)		Exterior light	Bay 3 exterior	UW – Hg lamps
One (1)		Red exterior light	Bay 5 exterior	UW – Hg lamps
One (1)		Exterior light	Bay 6/7 exterior	UW – Hg lamps
Two (2)		Exterior lights	Bay 9 exterior	UW – Hg lamps
One (1)		Oil/water separator	Bay 9 exterior	CRW – oil/sludge
One (1)		Exterior light	Bay 10 exterior	UW – Hg lamps
Two (2)		Exterior lights	Bay 13 exterior	UW – Hg lamps
One (1)		Exterior light	Generator Room exterior	UW – Hg lamps
Two (2)		A/C units	Office 1/Office 2 exterior	CFCs/Freon
One (1)		Electrical meter	Exterior A-side	UW – used electronics (printed circuit boards)
Two (2)	4,000 gal	UST – gasoline	Exterior A-side	I – gasoline
One (1)		Gasoline pump	Exterior A-side	I
One (1)		Diesel pump	Exterior A-side	CRW – oil
One (1)		AST (propane)	Exterior D-side near Generator Room	I – propane

- CRW- Connecticut Regulated Waste – PCBs (CR01), Oils (CR02/CR03), waste chemical liquids - antifreeze, latex & solvent paints, sludges, etc. (CR04), waste chemical solids (CR05)
- UW- Universal Waste (batteries, thermostat ampoules, fluorescent lamps, used electronics)
- IH- Inhalation hazard (silicas, etc.)
- I- Ignitable - may contain ingredients which are ignitable (materials which have a flashpoint <140°F) (D001)
- C- Corrosive - may contain ingredients which are alkaline or acidic (materials with a PH<2 or >12.5) (D002)
- T- Toxic - may contain ingredients which are harmful if swallowed or which release vapors that can cause irritation
- R- Reactive – may contain ingredients which are unstable, react violently with water or are explosive (D003)

**TABLE 6 (...continued)
 INVENTORY OF ADDITIONAL HAZARDOUS/REGULATED
 MATERIALS, WASTES AND ITEMS IDENTIFIED
 BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
 BROOKFIELD, CONNECTICUT**

Quantity	Size	Material/Item	General Location	Potential Hazard
One (1)	2,000 gal	UST – fuel oil	Exterior D-side near Generator Room	CRW – oil
One (1)	4,000 gal	UST – diesel	Exterior A-side	CRW – diesel oil
One (1)	5,000 gal	UST – waste water/oil	Exterior A-side	CRW – waste chemical liquid/oil

- CRW- Connecticut Regulated Waste – PCBs (CR01), Oils (CR02/CR03), waste chemical liquids - antifreeze, latex & solvent paints, sludges, etc. (CR04), waste chemical solids (CR05)
- UW- Universal Waste (batteries, thermostat ampoules, fluorescent lamps, used electronics)
- IH- Inhalation hazard (silicas, etc.)
- I- Ignitable - may contain ingredients which are ignitable (materials which have a flashpoint <140°F) (D001)
- C- Corrosive - may contain ingredients which are alkaline or acidic (materials with a PH<2 or >12.5) (D002)
- T- Toxic - may contain ingredients which are harmful if swallowed or which release vapors that can cause irritation
- R- Reactive – may contain ingredients which are unstable, react violently with water or are explosive (D003)

**TABLE 7
BULK SAMPLE SUMMARY OF SUSPECT PCB CONTAINING MATERIALS
BROOKFIELD MAINTENANCE FACILITY - MAIN BUILDING
BROOKFIELD, CONNECTICUT**

Sample No.	Homogenous Material Type	Sample Location	Total PCB (ppm)	EPA/CTDEEP Regulated
C2-A	Exterior beige brittle vent caulk	Exterior Generator Room Vent	1.7	CTDEEP
WG1-A	Interior grey brittle window glaze	Office 1/Bay 4	0.49	Unregulated
DWG1-A	Grey sticky door window glaze	Bay 1 exterior D-side door	ND<0.8	Unregulated
DWG2-A	Black soft door window glaze	Bay 13 exterior D-side door	ND<0.74	Unregulated
DWG3-A	Black pliable door window glaze	Bay 4 exterior B-side door	ND<0.32	Unregulated
1	White pliable door frame caulk (C1)	Office 1 & 2 door frames	ND<0.40	Unregulated
2	White/grey soft caulk (C1)	Exterior Bay 10 around conduit	ND<0.40	
3	White/grey soft caulk (C1)	Exterior Boiler door	ND<0.40	

*BRL< = Below Reportable Detection Limit
PCB ≥ 50 ppm = EPA PCB Bulk Product Waste
PCB >1 ppm but <50 ppm = CTDEEP regulated*

◆ Asbestos containing material (>1%)

*Additional samples were collected due to elevated detection limits that were >1 PPM

**TABLE 8
 IDENTIFIED PCB CONTAINING MATERIALS
 BROOKFIELD MAINTENANCE FACILITY – MAIN BUILDING
 BROOKFIELD, CONNECTICUT**

Material	Sample Date (mo/yr)	General Location	Adjacent Substrates	Estimated Quantity
CTDEEP REGULATED PCB CONTAINING MATERIALS (> 1 ppm, < 50 ppm)				
C2 – exterior beige brittle vent caulk*	Sampled 9/17	Exterior Generator Room – D-side vent*	Metal/Brick	8 LF (1 vent)*
EPA REGULATED PCB BULK PRODUCT WASTE (≥ 50 ppm)				
NO EPA REGULATED PCB BULK PRODUCT WASTES WERE POSITIVELY IDENTIFIED IN THE SUBJECT AREA				

◆ Asbestos containing material (>1%)

APPENDIX A

SITE PHOTOS WITH DOT ASSIGNMENT AND MAP



PHOTO 1. A/B sides.




PHOTO 2. A/D sides.

BROOKFIELD MAINTENANCE FACILITY, BROOKFIELD, CONNECTICUT



NOTES:
 1. THIS DRAWING IS THE PROPERTY OF THE STATE OF CONNECTICUT. IT IS TO BE USED ONLY FOR THE PROJECT AND SITE SPECIFICALLY IDENTIFIED HEREON.
 2. NO PART OF THIS DRAWING IS TO BE REPRODUCED OR TRANSMITTED IN ANY FORM OR BY ANY MEANS, ELECTRONIC OR MECHANICAL, INCLUDING PHOTOCOPYING, RECORDING, OR BY ANY INFORMATION STORAGE AND RETRIEVAL SYSTEM, WITHOUT THE WRITTEN PERMISSION OF THE STATE OF CONNECTICUT.



PROJECT NO.	63-389
DATE	SS-001
PROJECT NAME	BROOKFIELD
PROJECT LOCATION	RENOVATION OF BROOKFIELD REPAIR GARAGE
PROJECT NUMBER	DEMOLITION PLAN
SCALE	AS SHOWN
DATE	11-1-87
PROJECT ENGINEER	OFFICE OF ENGINEERING
PROJECT NO.	63-389
PROJECT NAME	RENOVATION OF BROOKFIELD REPAIR GARAGE
PROJECT LOCATION	BROOKFIELD
PROJECT NUMBER	DEMOLITION PLAN
SCALE	AS SHOWN
DATE	11-1-87
PROJECT ENGINEER	OFFICE OF ENGINEERING
PROJECT NO.	63-389
PROJECT NAME	RENOVATION OF BROOKFIELD REPAIR GARAGE
PROJECT LOCATION	BROOKFIELD
PROJECT NUMBER	DEMOLITION PLAN
SCALE	AS SHOWN
DATE	11-1-87
PROJECT ENGINEER	OFFICE OF ENGINEERING

STATE OF CONNECTICUT
DEPARTMENT OF TRANSPORTATION



memorandum

subject: Lead, Asbestos, and Soil Investigations
Danbury Repair Facility
Project No.: 34-350

date: June 6, 2017

to: Mr. Adam G. Fox
Transportation Principal Engineer
Bureau of Engineering and Construction

from: Mr. Christopher J. Bonsignore *CA*
Transportation Principal Engineer
Bureau of Engineering and Construction

Christopher J.
Bonsignore,
P.E.
2017.06.07
17:50:31-04:00

The following documents are attached for your use in preparing reports, plans, special provisions, and estimates for lead, asbestos, hazardous materials, soil, and groundwater for the subject project.

- 1. Danbury Site Plan depicting design elements, demolition, and excavation
- 2. Danbury Floor Plan
- 3. Brookfield Aerial Site Plan
- 4. Scope of Work

ONLY NEW CONSTRUCTION

memo/Rev 0

Although the main building in Brookfield will remain under this project, a full lead and asbestos investigation shall be completed under this project for the proposed demolition of this building in the future.

For your information, ~~EnviroMed-Services-Asbestos and Lead Inspection Reports~~ exist in Property and Facilities Services files.

The FDP for the project is March 2018, although it would be desirable to receive the reports in August 2017 when the Design Development submission is due.

PE efforts for this project will be under the above-noted project number.

*TRC 11/06/17
JAN*
8071

Should you have any questions or need any additional information, please contact the Project Engineer, Mr. Joseph S. Bordonaro, at Extension 3310.

Attachments

Joseph S. Bordonaro/jsb/sk

cc: James A. Fallon
David A. Hartley
Christopher J. Bonsignore – Michael J. Strong – Joseph S. Bordonaro
Matthew Easdon

Michael J. Strong, P.E.
2017.06.07
17:50:31-04:00

Joseph Bordonaro
2017.06.07
17:50:31-04:00

8. Install block heaters, tied into the BAS System (2 along vehicle spots near road).
9. Install flagpole.
10. Install generator with diesel base tank. No sound attenuating enclosure.
11. Install 1000 gallon oil-water separator.
12. Install 500 gallon aboveground waste oil and waste antifreeze storage tanks.
13. Utilities:
 - a. Natural Gas: New.
 - b. Public Water Supply: New.
 - c. Public Sewer System: New.
 - d. Power: New.
 - e. Communications: New.
 - f. Cable TV: New.

The material storage area (bins, catch basin tops, pipe, etc.) will need to be relocated by Maintenance elsewhere on site. Areas around the existing salt shed and on the upper site will be investigated during the design phase. This project will provide the base work necessary if existing paved area is not available.

Staff Maintenance may pursue a slip ramp to I-84 from a future highway project rather than this project.



BUILDING AND SITE IMPROVEMENTS - BROOKFIELD:

The facility contains a National Geodetic Survey (NGS) Continuously Operating Reference Station (CORS) Global Positioning System (GPS) that must remain operational at all times from its existing location in the building. The building will remain for usage by Maintenance personnel during a potential renovation project at the New Milford site. The building has a newer roof and envelope. The following renovations will be made:

1. Remove the motor fuel island, unleaded, diesel, fuel oil, and waste oil tanks. Oil-water separator and tank monitoring system to remain. The Brookfield tank replacement programmed for 2019 construction in advance of the 2020 expiration date will not be performed.
2. Remove the cold storage building.
3. Install 2000 gallon fuel oil aboveground storage tank and associated piping.
4. Remove and relocate equipment for Repair & Stores operations (TBD).

ENVIRONMENTAL - DANBURY & BROOKFIELD:

Environmental Compliance investigations for soil and groundwater, asbestos and lead, and other hazards will be performed.

X:\0034-0350\Facilities\all_other_data\Correspondence\1-Design 0-60%\Scope - Danbury Repair - Final 5-26-17.doc

BS 1.9 710

APPENDIX B
SITE SKETCHES




SUBJECT Brookfield Maint Facility

SHEET NO. 2 OF _____
PROJECT NO. 722/65-5616-0710
DATE 7/3
BY me, KG + ES
CHK'D _____

Ext

* All ext windows have silicone caulk & rubber glass sealant






SUBJECT Brookfield Maint Facility

SHEET NO. 2 OF _____
PROJECT NO. 222165-5616-0710
DATE 7/3
BY RM, KG + JS
CHK'D _____

PII sketch






SUBJECT Brookfield Maint FIC


SHEET NO. 1 OF 1
PROJECT NO. _____
DATE 7/5/17
BY [signature]
CHK'D _____

Roof



- * All 3 roofs are now membrane (no cuts as per EP)
- * metal flashing on entire parapet cap
- * silicone caulk throughout
- * no brown caulk present

ACR cement (flashing) remnants
(~ 4 SF)



Legend :

- ◆ = Sample Number & Location
- = Vent Tube
- = Mechanical Unit


REVISIONS			Drawing Title:	
			Asbestos Bulk Sample Location Diagram	
DATE	MARK	DESCRIPTION	Prepared by:	Date:
			EnviroMed Services, Inc. 25 Science Park, New Haven, CT 06511	MO9/01
			Project: Brookfield DOT - Maintenance Garage Roof Plan Brookfield, Connecticut	Scale: N.T.S.
			Prepared for: State of Connecticut Department of Transportation Newington, Connecticut	Drawn By: DER
				Approved By: J.F.
				Drawing No. 2 of 2
			EMS # 01-01-111	



SUBJECT Brookfield Maint Facility

SHEET NO. 2 of 4
PROJECT NO. _____
DATE 7/3, 5+6/17
BY ML, KG+ES
CHK'D _____

Haz waste - Hydraulic lifts / Floor drains (☒)






SUBJECT Brookfield Maint Facility

SHEET NO. 2 OF _____
PROJECT NO. _____
DATE 12/3, 1/6/11
BY M, RG 25
CHK'D _____

Ext Haz waste/UST's/AST's





SUBJECT CONN DOT BROOKFIELD MF

SHEET NO. 1 OF 2
PROJECT NO. 222165.5416.0710
DATE 11/29/18
BY CARMEN JACKO
CHK'D _____

OFFICES 1 & 2

ONLY PLACES WITH DROP CEILINGS
NO ROOFING DEBRIS ON DROP CEILINGS
TSI ABOVE CEILING TILE IN OFFICES

NORTH BAY AREA
NEW WINDOWS

INTERIOR INCLUDING BAY 10-12, SHOWER AND LOCKERS
CONCRETE DECK
I BEAMS WITH GREY PAINT
CMU WALLS PAINTED GREY AND WHITE
BATH HAS CERAMIC WALL TILE
CONCRETE FLOOR THROUGHOUT
GREY PAINT ON LOCKER AND SHOWER FLOORS
PAINT SPARSE ~~ON~~ IN BAYS



SUBJECT CONN DOT BROOKFIELD MF

SHEET NO. 2 OF 2

PROJECT NO. _____

DATE 11/29/18

BY _____

CHK'D _____

PCB SAMPLES (C1)

OFFICE 1+2 DOORS

WHITE PLYABLE DOOR FRAME CAULK 1

EXTERIOR BAY 10 AROUND CONDUIT

WHITE/GREY SOFT CAULK 2

EXTERIOR BOILER DOOR (EXTERIOR)

WHITE SOFT CAULK 3

CTDOT – Brookfield Maintenance Facility, Brookfield, CT

222165-5616-0710

7/3, 5, 6/17

PCB Summary

Cold Storage building

C1 – grey pliable building caulk between metal wall/ceiling panels; metal/metal junction;
Samples C1-A, C1-B, C1-C

Maintenance Facility

C1 – white flexible door/vent caulk;

Hall/Men's rm dr(metal/CMU), Hallway(metal/CMU), Offices 1 & 2(metal/CMU), Bay 1 ext around outlet(metal/brick), Bay 10 ext around conduit penetrations(metal/brick), Bay 9 side A dr(metal/CMU interior: metal/brick ext), Bay 4 side B dr(metal/CMU), Boiler rm dr(metal/CMU interior: metal/brick ext) Generator rm dr(metal/CMU interior: metal/brick ext), exterior side C o/s boiler rm top of metal vent(metal/brick). Found silicone caulking behind C1 only on A side around the conduit wall penetrations. No other C1 locations had caulks behind it.

Sample C1-A *extremely small bead of C1 throughout building + C1-B

~~NO SAMPLE ANALYSIS YET, Awaiting REMOVAL RE: IMPACT.~~

C2 – exterior, beige brittle vent caulk; exterior Generator room, (metal/brick); majority of C2 is gone due to weathering. Nothing behind C2. ALSO ACM

Sample C2-A

WG1 – interior, grey brittle window glaze; Office 1/Bay 4(metal/glass), 2 windows, both have very limited access.

Sample WG1-A

DWG1 – sticky grey door window glaze; Bays 1 & 9(metal/glass), Generator room(metal/glass).

Sample DWG1-A

DWG2 – black soft door window glaze; interior Bay 10 “Stores” room(metal/glass), Bay 13 ext
dr side D(metal/glass)

Sample DWG2-A

NON-REG

DWG3 – black, pliable door window glaze, Bay 4 interior only(metal/glass) – exterior has
silicone.

Sample DWG3-A

NON-REG

APPENDIX C

TRC INSPECTORS LICENSES/CERTIFICATIONS

1001615-0011065-0000001 of 0000001-CST-3-1610001-0754-07022



KELLY M GREY
84 HOPYARD RD
STAFFORD SPRINGS CT 06076-4227



Dear KELLY M GREY,


Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health
P.O. Box 340308
M.S.#12MQA
Hartford, CT 06134-0308

(860) 609-7603
oplc.dph@ct.gov
www.ct.gov/dph/license



Sincerely,

RAUL PINO, MD, MPH, COMMISSIONER
DEPARTMENT OF PUBLIC HEALTH



INSTRUCTIONS:

1. Detach and file each of the cards in this form.
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
4. The employer's copy is for persons who must demonstrate current licensure certification in order to safely employ or utilize. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.



CERTIFICATE OF ACHIEVEMENT

This certifies that

Kelly Grey

has successfully completed the
4 Hour Asbestos Site Inspector Refresher Training
Asbestos Accreditation Under TSCA Title II
40 CFR Part 763

conducted by

ATC Group Services, LLC
73 William Fyarks Drive
West Springfield, MA 01089
(413) 761-0070


Principal Instructor: Marcus Sotara

November 17, 2016

Date of Course

November 17, 2017

Expiration Date


Regional Training Manager: Gregory March

SIAR-5591

Certificate Number

November 17, 2016

Examination Date

100036 DI A111401 **AUI11 17 0064 0609-427241 C013008101



KELLY M GREY
84 HOPYARD RD
STAFFORD SPRINGS CT 06076-4227



Dear KELLY M GREY,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health
P.O. Box 340308
M.S.#12MQA
Hartford, CT 08134-0308

(860) 509-7803
oplc.dph@ct.gov
www.ct.gov/dph/license

Sincerely,

RAUL PIND, MD, MPH, COMMISSIONER
DEPARTMENT OF PUBLIC HEALTH

100036-000041-000101 of 0000001-C01-31400101-0084-00000

EMPLOYER'S COPY
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

NAME
KELLY M GREY

VALIDATION NO. 03-594856

CERTIFICATE NO. 002267

CURRENT THROUGH 02/28/18

PROFESSION
LEAD INSPECTOR RISK ASSESSOR

Raul Pind
COMMISSIONER

INSTRUCTIONS:

1. Detach and sign each of the cards on this form.
2. Display the larger card in a prominent place in your office or place of business.
3. The wallet card is for you to carry so your person. If you should wish to carry the wallet card, place it in a secure place.
4. The employer's copies for persons who must demonstrate current licensure/certification in order to obtain employment or privileges. The employer's card is to be preserved to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A
LEAD INSPECTOR RISK ASSESSOR

KELLY M GREY

CERTIFICATE NO. 002267

CURRENT THROUGH 02/28/18

VALIDATION NO. 03-594856

Raul Pind
COMMISSIONER

WALLET CARD
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

NAME
KELLY M GREY

VALIDATION NO. 03-594856

CERTIFICATE NO. 002267

CURRENT THROUGH 02/28/18

PROFESSION
LEAD INSPECTOR RISK ASSESSOR

Raul Pind
COMMISSIONER

CERTIFICATE OF ACHIEVEMENT

This certifies that

Kelly Grey

84 Hopyard Rd., Stafford, CT 06076

has successfully completed the
EPA Model Lead Risk Assessor Refresher Training
745.225 (c) (8) (i)



Gregory Marsch

conducted by
ATC Group Services LLC
73 William Franks Drive
West Springfield, MA 01089
(415) 781-0070

Mark B. Finkel

Principal Inspector: Neal Rowden
April 21, 2017

Date of Course

April 21, 2017

Exam Date

Regional Training Director: Gregory Marsch
ELIAR-719
Certification Number

Dear THOMAS J. MARTIN,

Attached you will find your validated certificate for the coming year. Should you have any questions about your certificate renewal, please do not hesitate to write or call:

Department of Public Health
P.O. Box 340308
M.S.#12MQA
Hartford, CT 06134-0308

(860) 609-7603
oplc.dph@ct.gov
www.ct.gov/dph/license

Sincerely,



RAUL PINO, MD, MPH, COMMISSIONER
DEPARTMENT OF PUBLIC HEALTH

EMPLOYER'S COPY
STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
NAME
THOMAS J. MARTIN
VALIDATION NO. 03-573056
CURRENT THROUGH 02/28/18
PROFESSION ASBESTOS CONSULTANT-INSPECTOR
COMMISSIONER

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS
ASBESTOS CONSULTANT-INSPECTOR
THOMAS J. MARTIN
CERTIFICATE NO. 000014
CURRENT THROUGH 02/28/18
VALIDATION NO. 03-573056
COMMISSIONER

INSTRUCTIONS:

1. Detach and sign each of the cards on this form.
2. Display the large card in a prominent place for your office or place of business.
3. The smaller card is for you to carry on your person. If you do not wish to carry the smaller card, place it in a secure place.
4. The employer's copy is for persons who wish to demonstrate cases of licensed certification in order to obtain employment as privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.



Spectrum Environmental Associates, Inc.
Exceeding our Clients Expectations of Excellence

This is to certify that
Thomas J. Martin

Social Security #: XXX-XX-3014

Has Successfully Completed The:

Asbestos Building Inspector Refresher Course
Also satisfies the N.Y.S.D.O.H. Building Inspector Refresher Requirements

This course is EPA and New York State Department Of Health approved pursuant to Article 30, Section 905 of the New York State Labor Law as required under Title 10, Chapter 11, Subchapter H, Part 73 NYSCRR.

The DOH 2832 certificate issued is the official record of this training course.

Exam Score	88	Course Date(s)	12/8/2016
Exam Date	12/8/2016	Expiration Date	12/8/2017
DOH 2832 Certificate Number	769882		

A handwritten signature in black ink, appearing to read 'Donald Trisbett'.

Donald Trisbett, Instructor

A handwritten signature in black ink, appearing to read 'William Wissmann'.

William Wissmann
Director of Training

2589 Albany Street, Box 1024 - Schenectady, New York 12301-1024
Phone: (518) 346-6374 Fax: (518) 346-40621 www.4spectrum.com



This is to certify that

Zachary W Smith



has completed the requisite training, and has passed an examination for accreditation

as:

Asbestos Inspector

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Institute for Environmental Education, Inc.
16 Upton Drive Wilmington, MA 01887

June 19-21, 2017

Course Dates

17-0302-102-401150

Certificate Number

June 21, 2017

Examination Date

June 21, 2018

Expiration Date

Wentworth

Training Director

16 Upton Drive, Wilmington, MA 01887 Telephone: 978.633.5273 www.ievee.org

INSTITUTE FOR ENVIRONMENTAL EDUCATION

Certificate of Completion



360training

This Certifies That

Carmen Jacko

is awarded this certificate for

OSHA 10 Hour Outreach Training Program - Construction

Credit Hours: 10.00

Completion Date: 07/27/2014

Marie Athey

Marie Athey, Trainer C 0026383 and G 0034871

"As an OSHA authorized trainer, I verify that I have conducted this OSHA outreach training class in accordance with OSHA Outreach Training Program requirements. I will document this class to my authorizing OSHA training organization. Upon successful review of my documentation, I will provide each student their completion card within 90 days of the end of the class."

360training.com ♦ 13801 Burnet Rd., Suite 100 ♦ Austin, TX 78727 ♦ 888-360-TRNG ♦ www.360training.com

APPENDIX D

LABORATORY ACCREDITATIONS

State of Connecticut, Department of Public Health
Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH
PURSUANT TO REGULATORY PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT FOR MAKING THE
EXAMINATIONS OF WATER SAMPLES FOR TESTS DESCRIBED BELOW WHICH HAVE BEEN AUTHORIZED TO BE MADE BY THE DEPARTMENT

TRC ENVIRONMENTAL CORPORATION

Windsor CT 06095

LOCATED AT 21 Clinton Road North in
Middletown

AND RESPECTFULLY THE NAME OF
Kathleen Whitman WHO HAS BEEN DESIGNATED
BY THE REGISTRAR AS BEING IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE FOR
APPROVAL AS FOLLOWS:

BUILDING MATERIALS
ASBESTOS FIBERS - PCM
BULK IDENTIFICATION - PIM


SEE COMPUTER PRINT OUT FOR SPECIFIC TESTS APPROVED

THIS CERTIFICATE IS VALID FROM DECEMBER 31, 2017 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH
DATED AT HARTFORD, CONNECTICUT THIS 12 DAY OF December, 2015

Registration No. PH-0450

SEZANNIE B. AVONCHOR, MS.
CHIEF, ENVIRONMENTAL HEALTH SECTION

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 101424-0

TRC Environmental Corporation
Windsor, CT

*is accredited by the National Voluntary Laboratory Accreditation Program for specific services,
listed on the Scope of Accreditation, for:*

Asbestos Fiber Analysis

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-ILAC-IAF Communique dated January 2009).*

2016-07-01 through 2017-06-30
Effective Dates



A handwritten signature in black ink, appearing to read "John S. Dunham".

For the National Voluntary Laboratory Accreditation Program



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

TRC Environmental Corporation
21 Griffin Road North
Windsor, CT 06095
Ms. Kathleen Williamson
Phone: 860-298-6392 Fax: 860-298-6214
Email: kwilliamson@trcsolutions.com
<http://www.trcsolutions.com>

ASBESTOS FIBER ANALYSIS

NVLAP LAB CODE 101424-0

Bulk Asbestos Analysis

<u>Code</u>	<u>Description</u>
18/A01	EPA 600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples
18/A03	EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials

A handwritten signature in black ink, appearing to read "Kathleen Williamson".

For the National Voluntary Laboratory Accreditation Program

State of Connecticut, Department of Public Health
Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH PURSUANT TO APPLICABLE PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT, FOR MAKING THE EXAMINATIONS, DETERMINATIONS OR TESTS SPECIFIED BELOW WHICH HAVE BEEN AUTHORIZED IN WRITING BY THAT DEPARTMENT.

PROSCIENCE ANALYTICAL SERVICES, INC.

LOCATED AT 22 Cummings Park IN Wolcott, MA 01801
AND REGISTERED IN THE NAME OF Harvey Yee

THIS CERTIFICATE IS ISSUED IN THE NAME OF Aimee Cormier WHO HAS BEEN DESIGNATED BY THE REGISTERED OWNER/AUTHORIZED AGENT TO BE IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE OF APPROVAL AS FOLLOWS:

SOLID WASTE/SOIL
Examination for:
Total Metals

ASBESTOS
Bulk Identification (PEM + TEM)
Air-Fiber Counting (PCM + TEM)

ENVIRONMENTAL HEALTH & HOUSING
Lead in Paint
Lead (Paint) in Soil
Lead in Dust Wipes

SEE COMPUTER PRINT-OUT FOR SPECIFIC TESTS APPROVED


THIS CERTIFICATE EXPIRES December 31, 2018 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH DATED AT HARTFORD, CONNECTICUT, THIS 29th November 2016



Registration #
PB-0299

SUZANNE BLANCFLOR, MS
CHIEF, ENVIRONMENTAL HEALTH SECTION

United States Department of Commerce
National Institute of Standards and Technology



Certificate of Accreditation to ISO/IEC 17025:2005

NVLAP LAB CODE: 200099-0

ProScience Analytical Services, Inc.
Woburn, MA

is accredited by the *National Voluntary Laboratory Accreditation Program* for specific services,
listed on the *Scope of Accreditation*, for:

Asbestos Fiber Analysis

*This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005.
This accreditation demonstrates technical competence for a defined scope and the operation of a laboratory quality
management system (refer to joint ISO-IAC-IAF Communiqué dated January 2009).*

2017-01-01 through 2017-12-31
Effective Dates



A handwritten signature in black ink, which appears to read "David S. Lamm".

For the National Voluntary Laboratory Accreditation Program



SCOPE OF ACCREDITATION TO ISO/IEC 17025:2005

ProScience Analytical Services, Inc.
22 Cummings Park
Woburn, MA 01801-2122
Ms. Aimee Cormier
Phone: 781-935-3212 Fax: 781-932-4857
Email: aimee.cormier@proscience.net
<http://www.proscience.net>

ASBESTOS FIBER ANALYSIS

NVLAP LAB CODE 200090-0

Bulk Asbestos Analysis

<u>Code</u>	<u>Description</u>
18/A01	BPA 600/M4-82-020: Interim Method for the Determination of Asbestos in Bulk Insulation Samples
18/A03	BPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials

Airborne Asbestos Analysis

<u>Code</u>	<u>Description</u>
18/A02	U.S. EPA's "Interim Transmission Electron Microscopy Analytical Methods-Mandatory and Nonmandatory and Mandatory Section to Determine Completion of Response Actions" as found in 40 CFR, Part 763, Subpart B, Appendix A.

A handwritten signature in black ink, appearing to read "John S. Leman".

For the National Voluntary Laboratory Accreditation Program



STATE OF CONNECTICUT

DEPARTMENT OF PUBLIC HEALTH
ENVIRONMENTAL HEALTH SECTION



ENVIRONMENTAL LABORATORY CERTIFICATION PROGRAM CERTIFIED ANALYTES REPORT FOR ALL MATRICES

Phoenix Environmental Laboratories, Inc.

587 EAST MIDDLE TURNPIKE
MANCHESTER, CT 06040

CT REGISTRATION NUMBER :

REGISTERED OWNER / AUTHORIZED AGENT : Allan Caffyn

DIRECTOR : Phyllis Shiller

CO DIRECTOR(S) : Kathleen Cressla

PHONE : (860) 645-1102

LABORATORY REGISTRATION EFFECTIVE DATE :

LABORATORY REGISTRATION EXPIRATION DATE :

LABORATORY STATUS :

APPROVED BY

SUZANNE BLANCAFLOR, MS, MPH
CHIEF, ENVIRONMENTAL HEALTH SECTION

REVIEWED BY

6/18/2018 2:36:23 PM

DERMOT JONES

ANY QUESTIONS CONCERNING THIS DOCUMENT SHOULD BE ADDRESSED TO THE
ENVIRONMENTAL LABORATORY CERTIFICATION PROGRAM AT (860) 509-7389

DRINKING WATER (SDWA)

STATUS REPORTED ON 6/18/2018

ANALYTE NAME

MICROBIOLOGY/BACTERIA

E. COLI - COLILERT (SM9223 Enumeration & P/A)	
E. COLI - MF NUTRIENT AGAR + MUQ (SM9222G)	ENTEROCOCCUS - ENTEROLERT
ENTEROCOCCUS - MF mEI Agar (EPA1600)	FECAL COLIFORM - MF m-FC (SM9222D)
HPC - POUR PLATE (SM9215B)	TOT COLIFORM - COLILERT (SM9223 Enumeration & P/A)
TOT. COLIFORM - MF mENDO (SM9222B)	

PHYSICALS

COLOR	
CONDUCTIVITY	ODOR
pH	TEMPERATURE
TURBIDITY	

MINERALS

ACIDITY	
ALKALINITY	CHLORIDE
CHLORINE, TOTAL & FREE RESIDUAL	FLUORIDE
HARDNESS, CALCIUM	HARDNESS, TOTAL
SULFATE	

NUTRIENTS

AMMONIA	
NITRATE	NITRITE
O-PHOSPHATE	

METALS

ALUMINUM	
ANTIMONY	ARSENIC
BARIUM	BERYLLIUM
BORON	CADMIUM
CALCIUM	CHROMIUM
COBALT	COPPER
IRON	LEAD
MAGNESIUM	MANGANESE
MERCURY	MOLYBDENUM
NICKEL	POTASSIUM
SELENIUM	SILVER
SODIUM	THALLIUM

TIN
ZINC

VANADIUM

RESIDUE

TOTAL DISSOLVED SOLIDS

TOTAL RESIDUE (SOLIDS)

DEMANDS

TOTAL ORGANIC CARBON

MISCELLANEOUS

CYANIDE (TOTAL)

FOAMING AGENTS (MBAS)

ORGANIC DISINFECTION BY-PRODUCTS

BROMOACETIC ACID

BROMOCHLOROACETIC ACID

CHLOROACETIC ACID

DIBROMOACETIC ACID

DICHLOROACETIC ACID

TRICHLOROACETIC ACID

VOLATILE ORGANICS

1,2-DIBROMO-3-CHLOROPROPANE 504.1 (DBCP)
(SOC)

1,4-DIOXANE (522 SIM)

1,4-DIOXANE (Mod 8270)

ETHYLENE DIBROMIDE 504.1 (EDB) (SOC)

TOTAL TRIHALOMETHANES 524.2 (SOC)

VINYL CHLORIDE - 524.2

VOLATILE ORGANICS - 524.2 (SOCs)

PESTICIDES/ PCB'S

ALDRIN

CHLORDANE (TECHNICAL) (SOC)

DIELDRIN

ENDRIN (SOC)

HEPTACHLOR (SOC)

HEPTACHLOR EPOXIDE (SOC)

HEXACHLOROBENZENE (SOC)

HEXACHLOROCYCLOPENTADIENE (SOC)

LINDANE (BHC-GAMMA) (SOC)

METHOXYCHLOR (SOC)

METRIBUZIN

PCB's (Aroclors, Qualitative Only)

TOXAPHENE (SOC)

HERBICIDES

2,4,5-TP (SILVEX) (SOC)

2,4-D (SOC)

DALAPON (SOC)

DICAMBA

DINOSEB (SOC)

DIQUAT (SOC)

GLYPHOSATE (SOC)

PARAQUAT

PENTACHLOROPHENOL (SOC)

PICLORAM (SOC)

PHTHALATE ESTERS & ADIPATES

BIS (2 - ETHYLHEXYL) ADIPATE - 525.3 (SOC)

BIS (2 - ETHYLHEXYL) PHTHALATE - 525.3 (SOC)

PAHS

BENZO(a)PYRENE - 525.3 (SOC)

TRIAZINE PESTICIDES

ALACHLOR (SOC)	ATRAZINE (SOC)
BUTACHLOR	METOLACHLOR
PROPACHLOR	SIMAZINE (SOC)

CARBAMATE PESTICIDES

3 - HYDROXYCARBOFURAN	ALDICARB (SOC)
ALDICARB SULFONE (SOC)	ALDICARB SULFOXIDE (SOC)
CARBARYL	CARBOFURAN (SOC)
METHOMYL	OXAMYL (SOC)

RADIOCHEMICALS

URANIUM - EPA 200.8

NON-POTABLE WATER/ WASTEWATER (CWA)

STATUS REPORTED ON 8/18/2018

ANALYTE NAME

MICROBIOLOGY/BACTERIA

E. COLI - COLILERT (SM9223 Enumeration & P/A)	
E. COLI - MF NUTRIENT AGAR + MUG (SM9222G)	ENTEROCOCCUS - ENTEROLERT
ENTEROCOCCUS - MF mEI Agar (EPA1600)	FECAL COLIFORM - COLILERT-18 (Enumeration)
FECAL COLIFORM - MF m-FC (SM9222D)	FECAL STREPT - MF mEnterococcus Agar (SM9230C)
HPC - POUR PLATE (SM9215B)	TOT COLIFORM - COLILERT (SM9223 Enumeration & P/A)
TOT. COLIFORM - MF mENDO (SM9222B)	

PHYSICALS

COLOR	
CONDUCTIVITY	ODOR
pH	TEMPERATURE
TURBIDITY	

MINERALS

ACIDITY	
ALKALINITY	CHLORIDE
CHLORINE, TOTAL & FREE RESIDUAL	HARDNESS, CALCIUM
HARDNESS, TOTAL	SULFATE
SULFIDE	SULFITE

NUTRIENTS

AMMONIA	
KJELDAHL NITROGEN	NITRATE
NITRITE	O-PHOSPHATE
TOTAL PHOSPHOROUS	

METALS

ALUMINUM	ANTIMONY
ARSENIC	BARIUM
BERYLLIUM	BORON
CADMIUM	CALCIUM
CHROMIUM	CHROMIUM - Hexavalent
COBALT	COPPER
IRON	LEAD
MAGNESIUM	MANGANESE
MERCURY	MOLYBDENUM
NICKEL	POTASSIUM

SELENIUM
SODIUM
THALLIUM
TITANIUM
ZINC

SILVER
STRONTIUM
TIN
VANADIUM

RESIDUE

TOTAL DISSOLVED SOLIDS	TOTAL RESIDUE (SOLIDS)
TOTAL SUSPENDED SOLIDS	TOTAL VOLATILE RESIDUE

DEMANDS

BOD
CARBONACEOUS BOD
TOTAL ORGANIC CARBON

COD

MISCELLANEOUS

CYANIDE (AMENABLE)	CYANIDE (TOTAL)
FOAMING AGENTS (MBAS)	FORMALDEHYDE

PHENOLICS

INORGANIC DISINFECTION BY-PRODUCTS

BROMIDE

VOLATILE ORGANICS

VOLATILE ORGANICS - 624.1

PESTICIDES/ PCB'S

ORGANOCHLORINE PESTICIDES - 608.3
PCB IN OIL
TOXAPHENE

PCBs - 608.3

SOLVENTS

ET Extractable Petroleum Hydrocarbons (ETPH)
MA Extractable Petroleum Hydrocarbons (EPH)
OIL & GREASE

MA Volatile Petroleum Hydrocarbons (VPH)
TPH (HEMISGT)

HERBICIDES

2,4,5-T
2,4,5-TP (SILVEX)
2,4-DB
DICAMBA

2,4-D
DALAPON

TRIAZINE PESTICIDES

ALACHLOR
SIMAZINE

ATRAZINE

RADIOCHEMICALS

URANIUM

SEMIVOLATILES

SEMIVOLATILES - 625.1

RECREATIONAL WATER

STATUS REPORTED ON 6/18/2018

ANALYTE NAME

MICROBIOLOGY/BACTERIA

ENTEROCOCCUS - MP mEI Agar (EPA1600)

SOLID WASTE/SOIL (RCRA)

STATUS REPORTED ON 6/18/2018

ANALYTE NAME

PHYSICALS

pH

MINERALS

SULFIDE

NUTRIENTS

AMMONIA

KJELDAHL NITROGEN

TOTAL PHOSPHOROUS

METALS

ALUMINUM

ANTIMONY

BARIUM

BORON

CALCIUM

CHROMIUM - Hexavalent

COPPER

LEAD

MANGANESE

MOLYBDENUM

POTASSIUM

SILVER

STRONTIUM

TIN

VANADIUM

ARSENIC

BERYLLIUM

CADMIUM

CHROMIUM

COBALT

IRON

MAGNESIUM

MERCURY

NICKEL

SELENIUM

SODIUM

THALLIUM

TITANIUM

ZINC

RESIDUE

TOTAL RESIDUE (SOLIDS)

TOTAL VOLATILE RESIDUE

DEMANDS

TOTAL ORGANIC CARBON

MISCELLANEOUS

CORROSMITY

CYANIDE (TOTAL)

PHENOLICS

SPLP LEACH (1312)

IGNITABILITY

REACTMITY

TCLP LEACH (1311)

PESTICIDES/ PCB'S

CHLORDANE (TECHNICAL)

ORGANOCHLORINE PESTICIDES (Single Response)

PCB IN OIL

POLYCHLORINATED BIPHENYLS

TOXAPHENE

SOLVENTS

CT Extractable Petroleum Hydrocarbons (ETPH)

MA Extractable Petroleum Hydrocarbons (EPH)

MA Volatile Petroleum Hydrocarbons (VPH)

OIL & GREASE

TOTAL ORGANIC HALIDES

TPH (HEMSGT)

HERBICIDES

2,4,5-T

2,4,5-TP (SILVEX)

2,4-D

DICAMBA

TRIAZINE PESTICIDES

ALACHLOR

ATRAZINE

SIMAZINE

RCRA (SW-846) ORGANICS

ACID EXTRACTABLES (PHENOLS) (SW 8270)

BENZIDINES (SW 8270)

CHLORINATED HYDROCARBONS (SW 8270)

HALOETHERS (SW 8270)

NITROAROMATICS & CYCLIC KETONES (SW 8270)

NITROSOAMINES (SW 8270)

PAH's (SW 8270)

PHthalATES (SW 8270)

VOLATILE ORGANICS (SW 8260)

RADIOCHEMICALS

URANIUM

ENVIRONMENTAL HEALTH & HOUSING

LEAD (PAINT) IN SOIL

LEAD IN DUST WIPES

LEAD IN PAINT

Report Profile: Lab Name : Phoenix Environmental Laboratories, Inc.

Test Name : *

Matrix Name : *

Matrix Selection = ALL OR SOME MATRICES SELECTED

Certifications approved or provisional on 6/18/2018

THIS IS THE LAST PAGE OF THE REPORT

State of Connecticut, Department of Public Health

Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH PURSUANT TO APPLICABLE PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT, FOR MAKING THE EXAMINATIONS, DETERMINATIONS OR TESTS SPECIFIED BELOW WHICH HAVE BEEN AUTHORIZED IN WRITING BY THAT DEPARTMENT.

PHOENIX ENVIRONMENTAL LABORATORIES, INC.

LOCATED AT 587 East Middle Turnpike IN Manchester, Connecticut 06040
AND REGISTERED IN THE NAME OF Allan E. Caffyn WHO HAS BEEN DESIGNATED
THIS CERTIFICATE IS ISSUED IN THE NAME OF Phyllis Shiller (Chemistry)
Kathleen Cressia (Microbiology)

BY THE REGISTERED OWNER AUTHORIZED AGENT TO BE IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE OF APPROVAL AS FOLLOWS:

DRINKING WATER, NON-POTABLE/WASTEWATER, SOLID WASTE/SOIL ENVIRONMENTAL HEALTH & HOUSING

Examination For:

BACTERIA
INORGANIC CHEMICALS
ORGANIC CHEMICALS
RADIOCHEMICALS

Examination For:

LEAD IN PAINT
LEAD IN DUST WIPES
LEAD (PAINT) IN SOIL

SEE COMPUTER PRINT-OUT FOR SPECIFIC TESTS APPROVED

EFFECTIVE RENEWAL DATE July 1, 2016
THIS CERTIFICATE EXPIRES June 30, 2018 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH
DATED AT HARTFORD, CONNECTICUT, THIS 12th DAY OF October, 2016



Registration
No.
PH - 0618

SUZANNE BLAKEMORE, MS, MPH
CHIEF, ENVIRONMENTAL HEALTH SECTION

State of Connecticut, Department of Public Health

Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH PURSUANT TO APPLICABLE PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT, FOR MAKING THE EXAMINATIONS, DETERMINATIONS OR TESTS SPECIFIED BELOW WHICH HAVE BEEN AUTHORIZED IN WRITING BY THAT DEPARTMENT.

COMPLETE ENVIRONMENTAL TESTING

LOCATED AT 80 LUPES DRIVE IN STRATFORD, CT 06615
AND REGISTERED IN THE NAME OF DAVID DITTA

THIS CERTIFICATE IS ISSUED IN THE NAME OF DAVID DITTA - DIRECTOR WHO HAS BEEN DESIGNATED
BY THE REGISTERED OWNER/AUTHORIZED AGENT TO BE IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE OF APPROVAL AS FOLLOWS:

DRINKING WATER, NON-POTABLE WATER/WASTEWATER


SOIL/ SOLID WASTE
BACTERIA
INORGANIC CHEMICALS
ORGANIC CHEMICALS
RADIOCHEMICALS

ENVIRONMENTAL HEALTH & HOUSING

LEAD IN PAINT
LEAD IN SOIL
LEAD IN DUST WIPES

SEE COMPUTER PRINT-OUT FOR SPECIFIC TESTS APPROVED

EFFECTIVE RENEWAL DATE October 1, 2018
THIS CERTIFICATE EXPIRES September 30, 2020 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH
DATED AT HARTFORD, CONNECTICUT, THIS 10th DAY OF September, 2018



Registration No.


PH-0116

SUZANNE BLANCAFLOR, MS
CHIEF, ENVIRONMENTAL HEALTH SECTION

APPENDIX E

**TRC ASBESTOS BULK SAMPLE
CHAIN OF CUSTODY FORMS**

ASBESTOS BULK SAMPLING CHAIN OF CUSTODY



21 GRIFFIN ROAD NORTH
WINDSOR, CONNECTICUT 06095
TELEPHONE (860) 298-9692
FAX (860) 298-6380

LAB ID # 50551

PROJECT NAME CTDOT - Brookfield Maintenance Facility, Brookfield, CT	PARAMETERS		TURNAROUND TIME				
INSPECTOR Tom Martin	PLM: <input type="checkbox"/> 8hr <input checked="" type="checkbox"/> 24hr <input type="checkbox"/> 48hr <input type="checkbox"/> 7day	ANALYZE BY LAVER	TEMP COUNT (R > 1% & < 10%)	TEMP NY N011984 (IF PLAN SHEETS REQ)	PLM: <input type="checkbox"/> 8hr <input checked="" type="checkbox"/> 24hr <input type="checkbox"/> 48hr <input type="checkbox"/> 7day	TEMP: <input type="checkbox"/> 24hr <input checked="" type="checkbox"/> 48hr <input type="checkbox"/> 7day	5day
PROJECT NUMBER 222165-5616-0710	PLM: <input type="checkbox"/> 8hr <input checked="" type="checkbox"/> 24hr <input type="checkbox"/> 48hr <input type="checkbox"/> 7day	PLM EPA 600/R93/116 (W/gravimetric reduction) (POSITIVE STOP)	PLM EPA 600/R93/116 (POSITIVE STOP)	PLM EPA 600/R93/116 (POSITIVE STOP)			

FIELD SAMPLE NUMBER	DATE	TIME	TYPE	SAMPLE LOCATION	MATERIAL	REQUIREMENTS	
						CONC	GRAB
1	7/5/17	1402		Bay 4 loft	CP11 - white fiberglass end sealant	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2	7/5/17	0954		Women's room	CP11 - white fiberglass end sealant	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3	7/5/17	1328		Office 2	PI1 - paper/foil/tar pipe insulation wrap on fiberglass 1" line	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4	7/5/17	1400		Bay 4 loft	PI1 - paper/foil/tar pipe insulation wrap on fiberglass 1" line	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5	7/5/17	1138		Bay 9	PI1 - paper/foil/tar pipe insulation wrap on fiberglass 1" line	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6	7/5/17	0934		Generator room	DWG1 - sticky, grey door window glaze	<input type="checkbox"/>	<input checked="" type="checkbox"/>
7	7/5/17	0936		Generator room	DWG1 - sticky, grey door window glaze	<input type="checkbox"/>	<input checked="" type="checkbox"/>
8	7/5/17	1124		Bay 5	DWG2 - black, soft door window glaze	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9	7/5/17	1125		Bay 5	DWG2 - black, soft door window glaze	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10	7/5/17	1144		Bay 4	DWG3 - black, pliable door window glaze	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Relinquished by: (Signature) <i>Tom Martin</i>	Date: 7/7/17	Received by: (Signature) <i>Cathryn Lamice</i>	Date: 7/7/17
(Printed) Tom Martin	Time: 1141	(Printed) Cathryn Lamice	Time: 1300
Remarks:		Condition of Samples: Acceptable: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	



ASBESTOS BULK SAMPLING CHAIN OF CUSTODY

21 GRIFFIN ROAD NORTH
WINDSOR, CONNECTICUT 06095
TELEPHONE (860) 298-9692
FAX (860) 298-6380

LAB ID #: **50581**

PROJECT NUMBER 222165-5616-0710	PROJECT NAME CTDOT - Brookfield Maintenance Facility, Brookfield, CT		TURNAROUND TIME				
	INSPECTOR Tom Martin	SAMPLE LOCATION	PLM:	8hr	24hr	48hr	3day
SIGNATURE <i>Tom Martin</i>	DATE	TIME	TEMP:	24hr	48hr	3day	5day

FIELD SAMPLE NUMBER	DATE	TIME	TYPE	GRAB	COMB	PROJECT NAME	INSPECTOR	SAMPLE LOCATION	PARAMETERS				MATERIAL	
									PLM EPA 600/R9/116 (POSITIVE STOP)	PLM EPA 600/R9/116 (w/ Ruvimetric reduction) (POSITIVE STOP)	ANALYZE BY LAYER	POINT COUNT (P < 1% & L 0%)		TECHNIQUE (IF PLM SERIES NEG)
11	7/5/17	1145				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Bay 4	X				X	DWG3 - black, pliable door window glaze
12	7/5/17	0955				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Library	X					EJ1 - black, tar-like floor expansion joint material
13	7/5/17	1002				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Bay 13	X					EJ1 - black, tar-like floor expansion joint material
14	7/5/17	1005				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Bay 13	X					EJ2 - brown, fibrous floor expansion joint material
15	7/5/17	1056				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Bay 11	X					EJ2 - brown, fibrous floor expansion joint material
16	7/5/17	1317				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Office 1					X	C1 - white, flexible door caulk
17	7/5/17	1400				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Exterior - D side o/s Generator room	X					C2 - exterior, beige brittle vent caulk
18	7/5/17	1401				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Exterior - D side o/s Generator room	X					C2 - exterior, beige brittle vent caulk
19	7/5/17	1537				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Office 1						WG1 - interior, brittle grey window glazing on 9 pane metal sash windows
20	7/5/17	1321				CTDOT - Brookfield Maintenance Facility, Brookfield, CT	Tom Martin	Office 1						G1 - tan glue associated with former co-base in Offices 1 & 2

Relinquished by (Signature) <i>Tom Martin</i>	Date 7/7/17	Relinquished by (Signature) <i>Tom Martin</i>	Date 7/7/17
(Printed) Tom Martin	Time 1141	(Printed) Tom Martin	Time 1320
Remarks:		Condition of Samples: Acceptable: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Page 2 of 2

APPENDIX F

TRC ASBESTOS PLM LABORATORY ANALYSIS DATA

BULK ASBESTOS ANALYSIS REPORT

CLIENT: CT Department of Transportation

Lab Log #: 0050881
 Project #: 222165.5616.0710
 Date Received: 07/07/2017
 Date Analyzed: 07/07/2017

Site: Brookfield Maintenance Facility, Brookfield, CT

POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogenous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
1	White/Yellow (sealant)	Yes	No	--	20% fibrous glass	ND	None
2	White/Yellow (sealant)	Yes	No	--	20% fibrous glass	ND	None
3	Black/Silver (foil insulation)	Yes	No	--	20% fibrous glass	ND	None
4	Black/Silver (foil insulation)	Yes	No	--	20% fibrous glass	ND	None
5	Black/Silver (foil insulation)	Yes	No	--	20% fibrous glass	ND	None
6	Grey (glaze)	Yes	No	--	---	ND	None
7	Grey (glaze)	Yes	No	--	---	ND	None
8	Black (glaze)	Yes	No	--	---	ND	None
9	Black (glaze)	Yes	No	--	---	ND	None
10	Black (glaze)	Yes	No	--	---	ND	None
11	Black (glaze)	Yes	No	--	---	ND	None
12	Black (expansion joint)	Yes	No	--	30% cellulose	ND	None
13	Black (expansion joint)	Yes	No	--	30% cellulose	ND	None
14	Brown (expansion joint)	Yes	No	--	80% cellulose	ND	None
15	Brown (expansion joint)	Yes	No	--	80% cellulose	ND	None
16	White (caulk)	Yes	No	--	---	ND	None
17	Beige (caulk)	Yes	No	--	---	3%	Chrysotile

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0 ABIA-LAP,LLC 4100122 CT #PH-0436 ME LA-0075, LB-0071 MA #A000052 NY #10080 WV# L1000411
 RI #AAL-007 TN #300384 VT #AL014538 LA#05011 VA #3333000283 AZ #A20944 HI #L-09-004 NJ #CT004 CA #2907
 CO# AL-15020 PHIL# 461 PA#68-05387



POLARIZED LIGHT MICROSCOPY by EPA 600/R-93/116

Sample No.	Color	Homogeneous	Multi-Layered	Layer No.	Other Matrix Materials	Asbestos %	Asbestos Type
18	--	--	--	--	--	NA/PS	--
19	Grey (glaze)	Yes	No	--	---	ND	None
20	Tan (glue)	Yes	No	--	---	ND	None

Reporting limit- asbestos present at 1%
 ND - asbestos was not detected
 Trace - asbestos was observed at level of less than 1%
 NA/PS - Not Analyzed / Positive Slop
 SNA- Sample Not Analyzed- See Chain of Custody for details

Note: Polarized light microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. In those cases, EPA recommends, and certain states (e.g. NY) require, that negative results be confirmed by quantitative transmission electron microscopy.

The Laboratory at TRC follows the EPA's Interim Method for the Determination of Asbestos in Bulk Insulation 1982 (EPA 600/M4-82-020) Bulk Analysis Code 18/A01 and the EPA recommended Method for the Determination of Asbestos in Bulk Building Materials July 1993, R.L. Perkins and B.W. Harvey, (EPA/600/R-93/116) Bulk Analysis Code 18/A03, which utilize polarized light microscopy (PLM). Our analysts have completed an accredited course in asbestos identification. TRC's Laboratory is accredited under the National Voluntary Laboratory Accreditation Program (NVLAP), for Bulk Asbestos Fiber Analysis, NVLAP Code 18/A01, effective through June 30, 2018. TRC is accredited by the AIHA Laboratory Accreditation Programs (AIHA-LAP), LLC in the Industrial Hygiene Program (IHLAP) for PLM effective through October 1, 2018. Asbestos content is determined by visual estimate unless otherwise indicated. Quality Control is performed in-house on at least 10% of samples and QC data related to the samples is available upon written request from client.

This report shall not be reproduced, except in full, without the written approval of TRC. This report must not be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the items tested.

Analyzed by: K. Williamson Reviewed by: Cathryn Lomire Date Issued: 07/10/2017
 Kathleen Williamson, Laboratory Manager Cathryn Lomire, Approved Signatory

TRC LABORATORY ASBESTOS ANALYTICAL ACCREDITATIONS

NVLAP Lab Code 101424-0 AIHA-LAP, LLC #100122 CT #911-0436 MI# LA-0075, LH-0071 MA #AA000052 NY #10980 WV# L17000111
 RI #AAL-007 TX #300354 VT #A1.014538 LA#05011 VA #3333 000283 AZ #A20944 DE #L-09-004 NJ #CT001 CA #2907
 CO# AL-15020 PHIL# 461 PA#68-03387

APPENDIX G

TRC ASBESTOS TEM LABORATORY ANALYSIS DATA

ProScience Analytical Services, Inc.

22 Cummings Park, Woburn, Massachusetts 01801
 781-935-3212 - Fax 781-932-4857 - E-Mail general@proscience.net

Laboratory Report

Batch: **NT 16536**
 Method: **NOB**
 Date Received: **7/10/2017**
 Date Analyzed: **7/12/2017**
 Date of Report: **7/12/2017**

Client Project #: **222166.5616.0710**
 Client References: **CT DOT - Brookfield Maintenance Facility, Brookfield, CT**
 PO #: **CZZ2166**
 Client #: **297**
 Client Name: **TRC Environmental Corp. (CT)**

LAB ID	Field ID	Description:	Color	Initial Weight	% Asbestos Types			TRE	% Other Non-aso.	% Organic	% Carb. Asbestos	Total % Analyzed / Charged	Prepared / Charged
					CHR	AMO	ACT						
NT124645	17	Stacky, Grey Door Window Glaze		.1053	.00	.00	.00	.00	41.79	3.04	ND	Yes	No
NT124646	19	Black, Soft Door Window Glaze		.1206	.00	.00	.00	.00	31.92	58.37	ND	Yes	No
NT124647	11	Black, Pliable Door Window Glaze		.1746	.00	.00	.00	.00	54.18	9.45	ND	Yes	No
NT124648	13	Black, Tar-like Floor Expansion Joint Material		.1237	.30	.00	.00	.00	75.91	8.97	TR	Yes	No
NT124649	16	White, Flexible Door Caulk		.2617	.02	.00	.00	.00	26.90	70.84	TR	Yes	No
NT124650	19	Interior, Brittle Grey Window Glazing		.1904	.07	.00	.00	.00	12.61	84.14	TR	Yes	No
NT124651	20	Tan Glue		.1034	.00	.00	.00	.00	58.32	9.96	ND	Yes	No

Comments:

Key: CHR = Chrysotile AMO = Amosite CRO = Crocidolite ACT = Actinolite TRE = Tremolite ANT = Anthophyllite TR = Trace = < 1% ND = None Detected


 Mark Derosier, Analyst

APPENDIX H

TRC LEAD PAINT XRF MEASUREMENT TABLE



Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X-Ray Fluorescence (XRF) Spectrum Analyzer
 Site: Brookfield Maintenance Facility, Brookfield, Connecticut
 Project #: 222165-5616-0710
 Date(s): 7/3/2017
 Inspector: Kelly Grey (Lead Inspector #002267)

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm2)	Precision (mg/cm2)	Depth Index	Duration (sec)	Date/Time
1								< LOD	0.0	1	2.32	7/3/2017 9:29
2								0.7	0.1	1.1	5.02	7/3/2017 9:29
3								1.5	0.1	1.14	5.39	7/3/2017 9:30
4	Office 1	A	Wall		Block	White	Intact	0.6	0.1	2.5	6.51	7/3/2017 10:40
5	Office 1	B	Wall		Block	White	Intact	0.3	0.1	1.96	5.78	7/3/2017 10:41
6	Office 1	B	Window	Casing	Metal	White	Intact	1.2	0.3	3.7	4.61	7/3/2017 10:42
7	Office 1	B	Window	Casing	Metal	White	Intact	0.8	0.1	2.44	5.74	7/3/2017 10:42
8	Office 1	C	Window	Casing	Metal	Brown	Intact	< LOD	0.6	4.09	13.47	7/3/2017 10:43
9	Office 1	C	Window	Casing	Metal	Brown	Intact	< LOD	0.6	5.13	15.76	7/3/2017 10:43
10	Office 1	C	Window	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.84	7/3/2017 10:44
11	Office 1	C	Door	Casing	Metal	Brown	Intact	0.3	0.1	1.92	5.75	7/3/2017 10:45
12	Office 1	A	Door		Metal	Brown	Intact	0.5	0.1	2.73	5.4	7/3/2017 10:45
13	Office 1	A	Door	Jamb	Metal	Brown	Intact	< LOD	1.2	2.67	5.37	7/3/2017 10:45
14	Office 1	A	Door	Jamb	Metal	Brown	Intact	< LOD	0.8	2.75	13.46	7/3/2017 10:46
15	Office 1	A	Door	Jamb	Metal	Brown	Intact	0.1	0.1	1.77	3.83	7/3/2017 10:46
16	Office 2	A	Door	Jamb	Wood	Brown	Intact	< LOD	0.0	1	1.92	7/3/2017 10:47
17	Office 2	A	Door	Casing	Wood	Brown	Intact	< LOD	0.0	1	1.93	7/3/2017 10:47
18	Office 2	A	Door		Wood	Brown	Intact	< LOD	0.0	1	1.95	7/3/2017 10:48
19	Office 2	A	Door		Metal	Brown	Intact	0.7	0.2	3.18	4.98	7/3/2017 10:48
20	Office 2	A	Door	Casing	Metal	Brown	Intact	0.6	0.2	2.97	3.85	7/3/2017 10:50
21	Office 2	C	Window	Casing	Metal	Brown	Intact	< LOD	0.0	1.44	9.59	7/3/2017 10:50
22	Office 2	C	Wall		Block	White	Intact	0.2	0.1	3.28	4.24	7/3/2017 10:50
23	Office 2	C	Wall	Beam	Metal	White	Intact	1.3	0.5	3.41	3.08	7/3/2017 10:51
24	Office 2	C	Wall	Beam	Metal	White	Intact	1.4	0.3	3.64	4.23	7/3/2017 10:52
25	Office 2	D	Wall		Block	White	Intact	0.2	0.1	3.28	3.84	7/3/2017 10:52
26	Office 2	-	Floor		Concrete	Grey	Defective	< LOD	0.0	1.59	4.21	7/3/2017 10:53
27	Office 2	-	Floor		Concrete	Grey	Defective	< LOD	0.0	1	3.84	7/3/2017 10:53
28	Generator Room	B	Wall		Block	Tan/Beige	Intact	< LOD	0.0	1	2.32	7/3/2017 10:57
29	Generator Room	B	Generator		Metal	Green	Intact	0.1	0.0	1.05	4.23	7/3/2017 10:58
30	Generator Room	B	Generator		Metal	Green	Intact	0.1	0.0	1	4.6	7/3/2017 10:59
31	Generator Room	C	Door		Metal	Brown	Intact	< LOD	0.0	1	3.45	7/3/2017 11:00
32	Generator Room	C	Door	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.09	7/3/2017 11:00
33	Exterior Generator Room	C	Door	Threshold	Metal	Yellow	Intact	0.8	0.1	1.14	6.92	7/3/2017 11:02

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise



Lead Based Paint Measurement Summary Table

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm2)	Precision (mg/cm2)	Depth Index	Duration (sec)	Date/Time
34	Generator Room	C	Door	--	Metal	Brown	Intact	< LOD	0.0	1	1.93	7/3/2017 11:03
35	Boiler Room	C	Door	--	Metal	Brown	Intact	< LOD	0.0	1.65	2.68	7/3/2017 11:04
36	Boiler Room	C	Door	--	Metal	Brown	Intact	< LOD	0.0	1	1.93	7/3/2017 11:04
37	Boiler Room	C	Door	Jamb	Metal	Brown	Intact	< LOD	0.0	1	1.93	7/3/2017 11:04
38	Boiler Room	C	Door	Casing	Metal	Brown	Intact	< LOD	0.0	1	1.91	7/3/2017 11:05
39	Boiler Room	C	Door	Threshold	Concrete	Yellow	Defective	< LOD	0.0	1.18	4.6	7/3/2017 11:06
40	Boiler Room	--	Floor	--	Concrete	Red	Defective	< LOD	0.0	2.51	6.9	7/3/2017 11:06
41	Boiler Room	A	Wall	--	Block	White	Intact	< LOD	0.0	1.63	4.23	7/3/2017 11:07
42	Boiler Room	C	Wall	--	Block	White	Intact	< LOD	0.0	1	3.85	7/3/2017 11:07
43	Boiler Room	D	Wall	--	Brick	White	Intact	< LOD	0.0	1	3.46	7/3/2017 11:08
44	Boiler Room	D	Wall	Vent	Metal	White	Intact	< LOD	0.0	1	1.95	7/3/2017 11:08
45	Hallway	A	Wall	--	Block	White	Intact	0.4	0.1	3.11	5.74	7/3/2017 11:18
46	Hallway	C	Wall	--	Block	White	Intact	0.4	0.1	2.8	5.01	7/3/2017 11:18
47	Hallway	B	Door	--	Wood	Brown	Intact	1.0	0.3	5.26	4.61	7/3/2017 11:19
48	Hallway	B	Door	--	Wood	Brown	Intact	0.7	0.2	3.84	5.38	7/3/2017 11:19
49	Hallway	B	Door	Casing	Metal	Brown	Intact	0.6	0.3	2.49	3.08	7/3/2017 11:20
50	Hallway	--	Floor	--	Brick	Grey	Defective	< LOD	0.0	2.79	6.15	7/3/2017 11:21
51	Hallway	--	Floor	--	Brick	Grey	Defective	< LOD	0.0	1.22	3.45	7/3/2017 11:21
52	Hallway	A	Door	Baseboard	Block	Brown	Intact	0.3	0.1	4.48	6.92	7/3/2017 11:22
53	Library	C	Door	Casing	Wood	Brown	Intact	0.3	0.1	2.56	4.99	7/3/2017 11:23
54	Library	D	Door	Casing	Wood	Brown	Intact	1.8	0.6	2.31	2.92	7/3/2017 11:23
55	Library	D	Door	--	Wood	Brown	Intact	< LOD	0.0	1.55	2.68	7/3/2017 11:24
56	Library	--	Floor	--	Concrete	Grey	Intact	< LOD	0.1	3.64	6.15	7/3/2017 11:24
57	Library	B	Wall	--	Wood	Tan/Beige	Intact	0.2	0.1	1.84	4.24	7/3/2017 11:25
58	Library	B	Wall	--	Wood	White	Intact	< LOD	0.0	1	3.07	7/3/2017 11:25
59	Library	C	Wall	--	Block	White	Intact	< LOD	0.1	7.46	5	7/3/2017 11:26
60	Library	C	Wall	--	Block	Tan/Beige	Intact	0.2	0.1	1.93	5	7/3/2017 11:26
61	Locker Room	A	Wall	--	Block	White	Intact	< LOD	0.0	1.8	4.23	7/3/2017 11:27
62	Locker Room	D	Wall	--	Wood	White	Intact	< LOD	0.0	1	2.68	7/3/2017 11:28
63	Locker Room	D	Floor	--	Concrete	Grey	Intact	< LOD	0.0	1	3.84	7/3/2017 11:29
64	Locker Room	D	Lockers	--	Metal	Brown	Intact	< LOD	0.0	1	1.92	7/3/2017 11:29
65	Locker Room	C	Wall	I-beam	Metal	White	Intact	3.5	0.4	2.5	5.39	7/3/2017 11:38
66	Locker Room	--	Ceiling	--	Sheetrock	White	Intact	< LOD	0.1	4.48	2.29	7/3/2017 11:39

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).



Lead Based Paint Measurement Summary Table

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
67	Locker Room	-	Ceiling	-	Sheetrock	White	Intact	< LOD	0.0	1	1.92	7/3/2017 11:39
68	Womens Bath	-	Floor	-	Concrete	Grey	Intact	< LOD	0.1	3.16	5.87	7/3/2017 11:42
69	Womens Bath	-	Shower	-	Block	Grey	Intact	< LOD	0.0	1	3.83	7/3/2017 11:43
70	Womens Bath	-	Stall	-	Metal	Tan/Beige	Intact	0.2	0.1	1.65	2.7	7/3/2017 11:43
71	Womens Bath	-	Stall	-	Metal	Tan/Beige	Intact	0.2	0.1	1.47	3.84	7/3/2017 11:44
72	Womens Bath	D	Window	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.86	7/3/2017 11:44
73	Womens Bath	A	Door	Casing	Metal	Brown	Intact	0.4	0.1	1.56	3.46	7/3/2017 11:45
74	Womens Bath	A	Door	-	Wood	Brown	Intact	0.4	0.2	1.46	3.07	7/3/2017 11:45
75	Womens Bath	A	Door	Vent	Metal	Grey	Intact	< LOD	0.0	1	1.93	7/3/2017 11:46
76	0.0 calibration	-	-	-	-	-	-	< LOD	0.0	1	1.92	7/3/2017 13:01
77	0.7 calibration	-	-	-	-	-	-	0.8	0.1	1.12	9.25	7/3/2017 13:01
78	1.6 calibration	-	-	-	-	-	-	1.5	0.1	1.1	5.76	7/3/2017 13:02
79	Library	A	Cabinet	-	Wood	Green	Intact	< LOD	0.0	1	1.93	7/3/2017 13:06
80	Library	A	Cabinet	Top	Metal	Green	Intact	< LOD	0.0	1	3.47	7/3/2017 13:06
81	Mens Bath	-	Floor	-	Concrete	Grey	Intact	< LOD	0.1	4.89	5.35	7/3/2017 13:09
82	Mens Bath	C	Wall	I-beam	Metal	Tan/Beige	Intact	1.1	0.1	2.39	16.17	7/3/2017 13:10
83	Mens Bath	C	Window	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.95	7/3/2017 13:11
84	Mens Bath	C	Stall	Casing	Metal	Tan/Beige	Intact	0.2	0.1	1.76	4.24	7/3/2017 13:11
85	Mens Bath	C	Stall	Door	Metal	Tan/Beige	Intact	0.3	0.1	1.51	4.23	7/3/2017 13:12
86	Mens Bath	C	Stall	Wall	Metal	Tan/Beige	Intact	0.2	0.0	1.12	4.23	7/3/2017 13:12
87	Mens Bath	B	Door	Casing	Metal	Brown	Intact	0.6	0.1	1.85	4.22	7/3/2017 13:13
88	Mens Bath	B	Door	Door	Wood	Brown	Intact	0.7	0.2	2.84	4.98	7/3/2017 13:13
89	Hallway	-	Ceiling	-	Concrete	White	Intact	< LOD	0.0	3.27	3.84	7/3/2017 13:16
90	Hallway	-	Ceiling	I-beam	Concrete	White	Intact	0.3	0.1	4.19	4.62	7/3/2017 13:16
91	Hallway	-	Ceiling	I-beam	Concrete	White	Intact	< LOD	0.8	3.29	0.39	7/3/2017 13:16
92	Hallway	-	Ceiling	I-beam	Concrete	White	Intact	0.3	0.1	5.38	7.69	7/3/2017 13:17
93	Hallway	-	Ceiling	Cross beam	Metal	White	Intact	0.2	0.1	3.04	4.21	7/3/2017 13:17
94	Bay 1	A	Wall	-	Block	White	Intact	< LOD	0.1	2.32	3.46	7/3/2017 13:19
95	Bay 1	A	Wall	-	Block	Grey	Intact	0.1	0.0	1.89	5.01	7/3/2017 13:20
96	Bay 1	C	Wall	-	Block	Grey	Intact	< LOD	0.1	2.73	3.06	7/3/2017 13:21
97	Bay 1	C	Wall	-	Block	Red	Intact	0.1	0.0	1.19	5.4	7/3/2017 13:21
98	Bay 1	C	Wall	-	Block	White	Intact	< LOD	0.0	1.56	3.86	7/3/2017 13:22
99	Bay 1	C	Wall	-	Block	White	Intact	< LOD	0.0	1.01	3.44	7/3/2017 13:22

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B, C, D follow clockwise



Lead Based Paint Measurement Summary Table

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm2)	Precision (mg/cm2)	Depth Index	Duration (sec)	Date/Time
100	Bay 1	C	Door	-	Metal	Brown	Intact	< LOD	0.0	1	4.23	7/3/2017 13:23
101	Bay 1	C	Door	Casing	Metal	Brown	Intact	< LOD	0.0	1	2.7	7/3/2017 13:23
102	Exterior Bay 1	C	Door	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.08	7/3/2017 13:23
103	Bay 1	-	Floor	Lines	Concrete	White	Intact	< LOD	0.0	1.29	4.61	7/3/2017 13:24
104	Bay 1	-	Floor	Lines	Concrete	Yellow	Intact	< LOD	0.0	1	4.23	7/3/2017 13:25
105	Bay 1	C	Wall	I-beam	Metal	Grey	Intact	1.4	1.1	3.44	0.77	7/3/2017 13:26
106	Bay 1	C	Wall	I-beam	Metal	White	Intact	0.2	0.1	1.93	3.45	7/3/2017 13:26
107	Bay 1	C	Wall	I-beam	Metal	White	Intact	0.5	0.2	1.19	2.3	7/3/2017 13:27
108	Bay 1	D	Vent duct	-	Metal	White	Intact	0.5	0.2	1.53	3.08	7/3/2017 13:28
109	Bay 1	D	vent duct	-	Metal	Grey	Intact	< LOD	0.0	1	3.1	7/3/2017 13:29
110	Bay 1	B	Overhead door frame	-	Metal	Grey	Intact	0.9	0.1	1.9	11.94	7/3/2017 13:29
111	Bay 1	B	Overhead door frame	-	Wood	Grey	Intact	1.2	0.2	4.03	9.26	7/3/2017 13:30
112	Bay 1	B	Overhead door frame	-	Wood	Grey	Intact	0.0	0.0	1.27	8.04	7/3/2017 13:31
113	Bay 1	A	Old door stop	-	Metal	Grey	Intact	< LOD	0.0	1	3.84	7/3/2017 13:32
114	Bay 1	A	Wall	-	Block	Grey	Intact	< LOD	0.0	1.45	5.35	7/3/2017 13:34
115	Bay 1	A	Pipe	-	Metal	Grey	Intact	< LOD	0.0	1	3.86	7/3/2017 13:34
116	Bay 1	D	Wall	-	Block	Grey	Intact	< LOD	0.0	1.44	3.08	7/3/2017 13:34
117	Bay 1	D	Wall	-	Block	White	Intact	< LOD	0.0	1.83	2.32	7/3/2017 13:35
118	Bay 1	A	Door	Lentil	Metal	White	Intact	1.3	0.2	1.76	4.52	7/3/2017 13:36
119	Bay 2	C	Door	Lentil	Metal	White	Intact	< LOD	0.0	1	4.25	7/3/2017 13:37
120	Bay 2	B	Overhead door	Frame	Metal	Grey	Intact	0.6	0.1	2.23	3.85	7/3/2017 13:38
121	Bay 2	B	Overhead door	Frame	Wood	Grey	Intact	< LOD	0.0	1.82	3.84	7/3/2017 13:39
122	Bay 2	-	Floor	Line	Concrete	Yellow	Defective	< LOD	0.0	1.73	4.97	7/3/2017 13:40
123	Bay 3	C	Wall	-	Block	Red	Intact	< LOD	0.0	3.45	8.04	7/3/2017 13:40
124	Bay 3	C	Wall	-	Block	Grey	Intact	< LOD	0.1	2.28	2.7	7/3/2017 13:41
125	Bay 3	C	Wall	-	Block	White	Intact	< LOD	0.1	2.28	2.7	7/3/2017 13:41
126	Bay 3	C	Lift frame	I-beam	Metal	White	Intact	10.0	1.7	3.05	4.24	7/3/2017 13:42
127	Bay 3	C	Lift frame	I-beam	Metal	Grey	Intact	11.4	1.6	5.37	5	7/3/2017 13:43
128	Bay 3	A	Lift frame	I-beam	Metal	Grey	Intact	11.8	2.0	6.53	3.46	7/3/2017 13:43
129	Bay 3	A	Wall	-	Block	Grey	Intact	< LOD	0.0	1.36	4.23	7/3/2017 13:44
130	Bay 4	B	Wall	-	Block	White	Intact	< LOD	0.0	1.11	5.01	7/3/2017 13:50
131	Bay 4	C	Wall	-	Block	White	Intact	< LOD	0.1	4.18	5.99	7/3/2017 13:50
132	Bay 4	C	Wall	-	Block	Grey	Intact	< LOD	0.0	2.72	4.6	7/3/2017 13:51

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B, C, D follow clockwise



Lead Based Paint Measurement Summary Table

Device(s): Niton XLP301-A (Serial #24792) X-Ray Fluorescence (XRF) Spectrum Analyzer
 Site: Brookfield Maintenance Facility, Brookfield, Connecticut
 Project #: 222165-5616-0710
 Date(s): 7/3/2017
 Inspector: Kelly Grey (Lead Inspector #002267)

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
133	Bay 4	B	Door	Jamb	Metal	Brown	Intact	< LOD	0.0	1	2.3	7/3/2017 13:51
134	Bay 4	B	Door	Jamb	Metal	Brown	Intact	< LOD	0.0	1	3.47	7/3/2017 13:52
135	Bay 4	--	Floor	--	Concrete	Grey	Defective	< LOD	0.1	2.75	5.75	7/3/2017 13:53
136	Bay 4	--	Floor	--	Concrete	White	Defective	< LOD	0.1	4.26	5.01	7/3/2017 13:54
137	Bay 4 Tools Room	A	Wall	--	Wood	Grey	Intact	< LOD	0.0	1.2	3.45	7/3/2017 13:55
138	Bay 4 Tools Room	A	Wall	--	Metal	Grey	Intact	< LOD	0.0	1.54	4.22	7/3/2017 13:56
139	Bay 4 Tools Room	C	Wall	--	Wood	Blue	Intact	2.1	0.2	1.6	4.61	7/3/2017 13:57
140	Bay 4 Tools Room	B	Shelf	--	Wood	Blue	Intact	< LOD	0.0	1.75	3.08	7/3/2017 13:57
141	Bay 4 Tools Room	B	Shelf	Support	Metal	Blue	Intact	< LOD	0.0	1	4.23	7/3/2017 13:58
142	Bay 4 Tools Room	C	Shelf	--	Wood	Blue	Intact	2.7	0.6	1.68	2.71	7/3/2017 13:59
143	Bay 4 Tools Room	A	Door	Jamb	Wood	Grey	Intact	< LOD	0.0	1	3.08	7/3/2017 13:59
144	Bay 4 Tools Room	A	Door	Jamb	Wood	Grey	Intact	< LOD	0.1	2.27	3.83	7/3/2017 13:59
145	Bay 4 Compressor Room	B	Wall	--	Wood	White	Intact	< LOD	0.1	3.24	6.11	7/3/2017 14:01
146	Bay 4 Compressor Room	C	Wall	--	Block	White	Intact	< LOD	0.0	2.17	5.35	7/3/2017 14:02
147	Bay 4 Compressor Room	A	Column	--	Metal	Grey	Intact	1.5	0.2	2.15	4.99	7/3/2017 14:03
148	Bay 4 Compressor Room	--	Stair	Tread	Wood	Grey	Intact	< LOD	0.0	1	3.84	7/3/2017 14:04
149	Bay 4 Compressor Room	--	Stair	Tread	Wood	Yellow	Intact	0.1	0.1	2.96	4.99	7/3/2017 14:05
150	Bay 4 Compressor Room	--	Stair	Tread	Wood	Yellow	Intact	< LOD	0.0	1.58	3.45	7/3/2017 14:05
151	Bay 4 Compressor Room	--	Stair	Stringer	Wood	Grey	Intact	0.1	0.0	2.45	5.75	7/3/2017 14:06
152	Bay 4 Compressor Room	--	Stair	Railing	Metal	Grey	Intact	0.1	0.0	2.14	4.97	7/3/2017 14:07
153	Bay 4	--	Floor	--	Wood	Grey	Intact	< LOD	0.0	1	3.05	7/3/2017 14:08
154	Bay 4	D	Wall	--	Block	White	Intact	< LOD	0.0	1	3.88	7/3/2017 14:10
155	Bay 4	A	Railing	Panel	Wood	Grey	Intact	0.1	0.0	1.59	4.61	7/3/2017 14:11
156	Bay 4	A	Railing	Support	Metal	Grey	Intact	< LOD	0.0	1.02	4.28	7/3/2017 14:12
157	Bay 4	--	Ceiling	I-beam	Metal	Grey	Intact	0.3	0.1	1.17	4.59	7/3/2017 14:13
158	Bay 4	--	Ceiling	Cross beam	Metal	Grey	Intact	0.2	0.1	1.15	4.24	7/3/2017 14:14
159	Bay 4	--	Ceiling	Lift	Metal	Orange	Intact	1.1	0.1	1	6.15	7/3/2017 14:15
160	Bay 4	--	Ceiling	Lift	Metal	Orange	Intact	1.8	0.1	1.06	5.8	7/3/2017 14:16
161	Bay 4	--	Ceiling	Large I-beam	Metal	Grey	Intact	0.2	0.1	1.06	4.23	7/3/2017 14:18
162	Bay 5	B	Wall	I-beam	Metal	Grey	Intact	0.2	0.1	1.51	3.86	7/3/2017 14:32
163	Bay 5	D	Wall	--	Block	Red	Intact	2.1	0.5	2.5	3.47	7/3/2017 14:33
164	Bay 5	D	Wall	--	Block	Grey	Intact	< LOD	0.1	3.83	4.59	7/3/2017 14:33
165	Bay 9	D	Wall	--	Block	White	Intact	< LOD	0.0	1.28	3.08	7/3/2017 14:34

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise



Lead Based Paint Measurement Summary Table

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm ²)	Precision (mg/cm ²)	Depth Index	Duration (sec)	Date/Time
166	Bay 9	A	Wall		Block	Grey	Intact	< LOD	0.0	1	3.84	7/3/2017 14:34
167	Bay 9	A	Wall	Panel	Metal	Black	Intact	< LOD	0.1	1.14	2.32	7/3/2017 14:35
168	Bay 9	A	Window	Casing	Metal	Brown	Intact	< LOD	0.0	1	2.32	7/3/2017 14:35
169	Bay 9	A	Vent pipe		Metal	Grey	Intact	< LOD	0.8	9.79	8.09	7/3/2017 14:36
170	Bay 9	A	Vent pipe		Metal	Grey	Intact	< LOD	0.2	4.54	1.92	7/3/2017 14:36
171	Bay 9	A	Door		Metal	Brown	Intact	< LOD	0.0	1	3.45	7/3/2017 14:37
172	Bay 9	A	Door	Casing	Metal	Brown	Intact	< LOD	0.0	1	5.01	7/3/2017 14:38
173	Bay 10	C	Wall		Block	Tan/Beige	Intact	0.0	0.1	3.43	5.77	7/3/2017 14:39
174	Bay 10	C	Column		Metal	Tan/Beige	Intact	< LOD	0.1	1.85	2.29	7/3/2017 14:40
175	Bay 10	C	Column		Metal	White	Intact	< LOD	0.1	2.29	4.23	7/3/2017 14:40
176	Bay 10	B	Wall		Block	White	Intact	0.1	0.2	2.33	4.23	7/3/2017 14:41
177	Bay 10	C	Wall		Block	Tan/Beige	Intact	< LOD	0.0	1	1.92	7/3/2017 14:41
178	Bay 10	C	Wall		Wood	Tan/Beige	Intact	< LOD	0.0	1	2.32	7/3/2017 14:41
179	Bay 10	C	Wall		Wood	White	Intact	< LOD	0.0	1	3.84	7/3/2017 14:42
180	Bay 10	A	Wall		Block	White	Intact	< LOD	0.0	1.9	3.46	7/3/2017 14:42
181	Bay 10	A	Wall		Block	Tan/Beige	Intact	< LOD	0.0	1	2.69	7/3/2017 14:43
182	Bay 10	A	Wall	I-beam	Metal	Tan/Beige	Intact	0.3	0.2	1.62	2.68	7/3/2017 14:43
183	Bay 10	A	Wall	I-beam	Metal	Tan/Beige	Intact	0.3	0.2	1.72	3.85	7/3/2017 14:44
184	Bay 10	A	Overhead door frame		Wood	Tan/Beige	Intact	1.5	0.2	2.19	1.94	7/3/2017 14:44
185	Bay 10	A	Overhead door		Metal	White	Intact	< LOD	0.0	1	7.3	7/3/2017 14:46
186	Bay 10	A	Column		Metal	Red	Intact	< LOD	0.0	0.6	10.01	7/3/2017 14:47
187	Bay 10	D	Door		Metal	Red	Intact	< LOD	0.2	3.07	2.68	7/3/2017 14:48
188	Bay 10	D	Door		Metal	Red	Intact	< LOD	0.0	1	2.3	7/3/2017 14:48
189	Bay 10	D	Door	Casing	Wood	Tan/Beige	Intact	< LOD	0.0	1	3.46	7/3/2017 14:49
190	Bay 10	C	Ceiling	Support beam	Metal	Red	Intact	< LOD	0.0	1	4.82	7/3/2017 14:49
191	Bay 10	C	Ceiling	Support beam	Metal	Red	Intact	< LOD	0.0	1.69	4.82	7/3/2017 14:49
192	Bay 10	C	Ceiling	Support beam	Metal	White	Intact	< LOD	0.0	1	1.92	7/3/2017 14:49
193	Bay 10	C	Stair	Stringer	Metal	Grey	Intact	< LOD	0.0	1	1.54	7/3/2017 14:50
194	Bay 10	A	Window	Casing	Metal	Brown	Intact	< LOD	1.3	5.46	4.99	7/3/2017 14:51
195	Bay 10	A	Window	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.47	7/3/2017 14:51
196	Bay 10	A	Window	Lentil	Metal	Grey	Intact	0.9	0.1	1.72	9.62	7/3/2017 14:52
197	Bay 11	B	Column		Metal	Green	Intact	0.8	0.1	1.03	4.25	7/3/2017 14:53
198	Bay 11	B	Overhead door		Metal	White	Intact	< LOD	0.0	1	1.91	7/3/2017 14:54

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise



Lead Based Paint Measurement Summary Table

Device(s): Niton XLP201-A (Serial #24792) X Ray Fluorescence (XRF) Spectrum Analyzer
 Site: Brookfield Maintenance Facility, Brookfield, Connecticut
 Project #: 222165-5616-0710
 Date(s): 7/3/2017
 Inspector: Kelly Grey (Lead Inspector #102267)

Number	Room	Side	Structure	Feature	Material	Color	Condition	Reading (mg/cm2)	Precision (mg/cm2)	Depth Index	Duration (sec)	Date/Time
199	Bay 11	--	Ceiling	Beam	Metal	Grey	Intact	< LOD	0.1	1	2.98	7/3/2017 14:55
200	Bay 11	--	Ceiling	Beam	Metal	Grey	Intact	0.3	0.1	1.13	2.89	7/3/2017 14:55
201	Bay 12, 13	D	Wall	--	Block	Grey	Intact	2.9	0.6	2.23	3.46	7/3/2017 14:57
202	Bay 12, 13	B	Wall	--	Wood	Grey	Intact	2.1	0.5	1.99	3.1	7/3/2017 14:58
203	Bay 12, 13	B	Column	--	Metal	Grey	Intact	0.8	0.2	1.2	3.45	7/3/2017 14:58
204	Bay 12, 13	A	Railing	Trimwork	Wood	White	Intact	< LOD	0.0	1.21	3.06	7/3/2017 14:59
205	Bay 12, 13	A	Beam	Trimwork	Metal	White	Intact	0.9	0.1	1.72	10.77	7/3/2017 15:00
206	Exterior Bay 12, 13	D	Door	--	Metal	Brown	Intact	< LOD	0.0	1	3.09	7/3/2017 15:01
207	Exterior Bay 12, 13	D	Door	Casing	Metal	Brown	Intact	< LOD	0.0	1	3.06	7/3/2017 15:01
208	Exterior	D	Gutter	--	Metal	Brown	Intact	< LOD	0.0	1	1.53	7/3/2017 15:02
209	Exterior	C	Window	Sash ext	Metal	Brown	Intact	< LOD	0.0	1	3.46	7/3/2017 15:03
210	Exterior	A	Gas island	Trimwork	Metal	Yellow	Intact	< LOD	0.1	2.23	2.7	7/3/2017 15:08
211	Exterior	A	Gas island	Bumper	Metal	Yellow	Intact	< LOD	0.0	1	1.92	7/3/2017 15:09
212	0.0 calibration	--	--	--	--	--	--	< LOD	0.0	1	1.92	7/3/2017 15:10
213	0.7 calibration	--	--	--	--	--	--	0.7	0.2	1.08	3.45	7/3/2017 15:10
214	1.6 calibration	--	--	--	--	--	--	1.6	0.3	1.15	3.44	7/3/2017 15:11

Lead paint includes paint found to contain any detectable amount of lead by Atomic Absorption Spectrophotometry (AAS) or X-Ray Fluorescence (XRF).

Side A = Street side; Sides B,C,D follow clockwise

APPENDIX I

**COMPOSITE BUILDING MATERIAL WASTE
CHARACTERIZATION DATA**

80 Lupes Drive
Stratford, CT 06615



Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cet1@celabs.com

Client: Mr. Erik Plimpton
TRC Environmental Consultants
21 Griffin Rd., North
Windsor, CT 06095

Analytical Report

CET# 8120027



Report Date: December 07, 2018
Project: CT DOT, Brookfield MF
Project Number: 222165.5616.0710

Connecticut Laboratory Certificate: PH 0116
Massachusetts Laboratory Certificate: M-C1903
Rhode Island Laboratory Certificate: 199



New York NELAP Accreditation: 11982
Pennsylvania Certificate: 68-02927

CET # : 8120027

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

SAMPLE SUMMARY

The sample(s) were received at 23.6°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
01 Bays 10,11,12	8120027-01	Solid	11/29/2018	12/03/2018

Analyte: **TCLP Lead (EPA 6020A)**

Analyst: **CED**

Prep: **EPA 3005A-1311**

Matrix: **Extract**

Laboratory ID	Client Sample ID	Result	RL	Units	Dilution	Batch	Prepared	Date/Time Analyzed	Notes
8120027-01	01 Bays 10,11,12	1.9	0.013	mg/L	1	B8L0626	12/06/2018	12/06/2018 16:33	

CASE NARRATIVE

No collection times provided by client on chain of custody for the following samples: 8120027-01.

CET # : 8120027


Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta
Laboratory Director

Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analyses exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- *C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- *C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- *F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- *F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit.

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET # : 8120027
Project: CT DOT, Brookfield MF
Project Number: 222165.5616.0710

CERTIFICATIONS

Certified Analytes included in this Report

Analyte	Certifications
<i>EPA 6020A in Water</i>	
Lead	CT

Complete Environmental Testing operates under the following certifications and accreditations:

Code	Description	Number	Expires
CT	Connecticut Public Health	PH0116	09/30/2020

APPENDIX J

PCB CAULK/GLAZE LABORATORY ANALYSIS DATA



Thursday, September 28, 2017

Attn: Mr. Erik Plimpton
TRC Environmental Corp.
21 Griffin Rd North
Windsor, CT 06095

Project ID: DOT BROOKVIEW MF MAIN BLDG
Sample ID#s: BZ06769 - BZ06773

This laboratory is in compliance with the NELAC requirements of procedures used except where indicated.

This report contains results for the parameters tested, under the sampling conditions described on the Chain Of Custody, as received by the laboratory. This report is incomplete unless all pages indicated in the pagination at the bottom of the page are included.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

A scanned version of the COC form accompanies the analytical report and is an exact duplicate of the original.

If you have any questions concerning this testing, please do not hesitate to contact Phoenix Client Services at ext. 200.

Sincerely yours,

A handwritten signature in black ink that reads "Phyllis Shiller". The signature is written in a cursive style.

Phyllis Shiller
Laboratory Director

NELAC - #NY11301
CT Lab Registration #PH-0618
MA Lab Registration #M-CT007
ME Lab Registration #CT-007
NH Lab Registration #213893-A,B

NJ Lab Registration #CT-003
NY Lab Registration #11301
PA Lab Registration #68-03530
RI Lab Registration #83
VT Lab Registration #VT11301



Environmental Laboratories, Inc.
557 East Middle Turnpike, P.O. Box 370, Manchester, CT 06045
Tel. (860) 645-1102 Fax (860) 645-0823



SDG Comments

September 28, 2017

SDG I.D.: GBZ06769

Sample BZ06769 was received past hold time for Caulk Extraction for PCB (SW3540C).
Sample BZ06770 was received past hold time for Caulk Extraction for PCB (SW3540C).
Sample BZ06771 was received past hold time for Caulk Extraction for PCB (SW3540C).
Sample BZ06772 was received past hold time for Caulk Extraction for PCB (SW3540C).
Sample BZ06773 was received past hold time for Caulk Extraction for PCB (SW3540C).



Environmental Laboratories, Inc.
 687 East Middle Turnpike, P.O. Box 370, Manchester, CT 06046
 Tel. (860) 646-1102 Fax (860) 646-0823

Analysis Report
 September 28, 2017

FOR: Attn: Mr. Erik Plimpton
 TRC Environmental Corp.
 21 Griffin Rd North
 Windsor, CT 06095

Sample Information

Matrix: BULK
 Location Code: TRC-PCB
 Rush Request: 72 Hour
 P.O.#: 222165-5818.710

Custody Information

Collected by: TM
 Received by: B
 Analyzed by: see "By" below

Date Time
 07/06/17 12:00
 09/21/17 18:33

Laboratory Data

SDG ID: GBZ06768
 Phoenix ID: BZ08769

Project ID: DOT BROOKVIEW MF MAIN BLDG
 Client ID: WG1-A

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
Caulk Extraction for PCB	Completed				09/21/17	BB/Q	8W3640C
<u>PCB (Soxhlet 8W3640C)</u>							
PCB-1016	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1221	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1232	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1242	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1248	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1254	0.40	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1280	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1282	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
PCB-1288	ND	0.33	mg/Kg	2	09/22/17	AW	8W8082A
<u>QA/QC Surrogate</u>							
% DCBP	65		%	2	09/22/17	AW	30 - 160 %
% TCMX	69		%	2	09/22/17	AW	30 - 160 %

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
-----------	--------	------------	-------	----------	-----------	----	-----------

RL/PQL=Reporting/Practical Quantitation Level ND=Not Detected BRL=Below Reporting Level
QA/QC Surrogates: Surrogates are compounds (preceded with a %) added by the lab to determine analytical efficiency. Surrogate results(%) listed in the report are not "detected" compounds.


Comments:

Results are reported on an "as received" basis, and are not corrected for dry weight.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services.

This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director

September 28, 2017

Reviewed and Released by: Kathleen Crasels, QA/QC Officer



Environmental Laboratories, Inc.
 587 East Middle Turnpike, P.O. Box 370, Manchester, CT 06045
 Tel. (860) 646-1102 Fax (860) 646-0823

Analysis Report
 September 28, 2017

FOR: Attn: Mr. Erik Plimpton
 TRC Environmental Corp.
 21 Griffin Rd North
 Windsor, CT 06095

Sample Information

Matrix: BULK
 Location Code: TRC-PCB
 Rush Request: 72 Hour
 P.O.#: 222166-5616.710

Custody Information

Collected by: TM
 Received by: B
 Analyzed by: see "By" below

Date Time
 07/06/17 13:09
 09/21/17 18:33

Laboratory Data

SDG ID: GBZ06769
 Phoenix ID: BZ06770

Project ID: DOT BROOKVIEW MF MAIN BLDG
 Client ID: DWG1-A

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
Caulk Extraction for PCB	Completed				09/26/17	BC/Q	SW3540C
<u>PCB (Soxhlet SW3540C)</u>							
PCB-1016	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1221	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1232	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1242	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1248	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1254	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1260	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1282	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
PCB-1288	ND	0.8	mg/Kg	5	09/26/17	AW	SW8082A
<u>QA/QC Surrogate</u>							
% DCBP	42		%	5	09/26/17	AW	30 - 160 %
% TCMX	24		%	5	09/26/17	AW	30 - 160 %

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
-----------	--------	------------	-------	----------	-----------	----	-----------

3 = This parameter exceeds laboratory specified limits.

RL/PQL=Reporting/Practical Quantitation Level ND=Not Detected BRL=Below Reporting Level

QA/QC Surrogates: Surrogates are compounds (preceded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

Comments:

Results are reported on an "as received" basis, and are not corrected for dry weight.

PCB Comment:

For PCBs, in order to reach the desired RL, multiple cleanup steps were performed. The extract was cleaned up with a combination of sulfuric acid, potassium permanganate, copper powder and additional florisil.

PCB Comment:

Poor surrogate recovery was observed for PCBs. Sample was re-extracted with similar results.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services.

This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director

September 26, 2017

Reviewed and Released by: Kathleen Crossis, QA/QC Officer



Environmental Laboratories, Inc.
 697 East Middle Turnpike, P.O. Box 370, Manchester, CT 06046
 Tel. (860) 646-1102 Fax (860) 646-0823

Analysis Report
 September 28, 2017

FOR: Attn: Mr. Erik Plimpton
 TRC Environmental Corp.
 21 Griffin Rd North
 Windsor, CT 06095

Sample Information

Matrix: BULK
 Location Code: TRC-PCB
 Rush Request: 72 Hour
 P.O.#: 222165-5616.710

Custody Information

Collected by: TM
 Received by: B
 Analyzed by: see "By" below

Date Time
 07/08/17 13:05
 09/21/17 18:33

Laboratory Data

SDG ID: GBZ06769
 Phoenix ID: BZ06771

Project ID: DOT BROOKVIEW MF MAIN BLDG
 Client ID: DWG2-A

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
Caulk Extraction for PCB	Completed				09/28/17	BC/Q	8W3540C
<u>PCB (Soxhlet 8W3540C)</u>							
PCB-1016	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1221	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1232	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1242	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1248	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1254	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1260	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1262	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
PCB-1268	ND	0.74	mg/Kg	5	09/28/17	AW	8W8082A
<u>QA/QC Surrogates</u>							
% DCBP	82		%	5	09/28/17	AW	30 - 160 %
% TCMX	34		%	5	09/28/17	AW	30 - 150 %

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
-----------	--------	------------	-------	----------	-----------	----	-----------

RL/PQL=Reporting/Practical Quantitation Level ND=Not Detected BRL=Below Reporting Level
QA/QC Surrogates: Surrogates are compounds (preceded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

Comments:

Results are reported on an "as received" basis, and are not corrected for dry weight.

PCB Comment:

For PCBs, in order to reach the desired RL, multiple cleanup steps were performed. The extract was cleaned up with a combination of sulfuric acid, potassium permanganate, copper powder and additional florist.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director

September 28, 2017

Reviewed and Released by: Kathleen Crossia, QA/QC Officer



Environmental Laboratories, Inc.
 687 East Middle Turnpike, P.O. Box 370, Manchester, CT 06046
 Tel. (860) 846-1102 Fax (860) 846-0823

Analysis Report
 September 28, 2017

FOR: Attn: Mr. Erik Plimpton
 TRC Environmental Corp.
 21 Griffin Rd North
 Windsor, CT 06095

Sample Information

Matrix: BULK
 Location Code: TRC-PCB
 Rush Request: 72 Hour
 P.O.#: 222185-5816.710

Custody Information

Collected by: TM
 Received by: B
 Analyzed by: see "By" below

Date Time
 07/06/17 13:27
 09/21/17 18:33

Laboratory Data

SDG ID: GBZ06769
 Phoenix ID: BZ08772

Project ID: DOT BROOKVIEW MF MAIN BLDG
 Client ID: DWG3-A

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
Caulk Extraction for PCB	Completed				09/21/17	BB/Q	SW3540C
<u>PCB (Soxhlet SW3540C)</u>							
PCB-1016	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1221	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1232	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1242	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1246	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1254	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1260	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1282	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
PCB-1288	ND	0.32	mg/Kg	2	09/23/17	AW	SW8082A
<u>QA/QC Surrogates</u>							
% DCSP	40		%	2	09/23/17	AW	30 - 150 %
% TCMX	34		%	2	09/23/17	AW	30 - 150 %

Project ID: DOT BROOKVIEW MF MAIN BLDG
Client ID: DWG3-A

Phoenix I.D.: BZ06772

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
-----------	--------	------------	-------	----------	-----------	----	-----------

RL/PQL=Reporting/Practical Quantitation Level ND=Not Detected BRL=Below Reporting Level

QA/QC Surrogates: Surrogates are compounds (preceded with a %) added by the lab to determine analysts efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

Comments:

Results are reported on an "as received" basis, and are not corrected for dry weight.


PCB Comment:

For PCBs, in order to reach the desired RL, multiple cleanup steps were performed. The extract was cleaned up with a combination of sulfuric acid, potassium permanganate, copper powder and additional florisol.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services.

This report must not be reproduced except in full as defined by the attached chain of custody.



Phyllis Shiller, Laboratory Director

September 29, 2017

Reviewed and Released by: Kathleen Cressa, QA/QC Officer



Environmental Laboratories, Inc.
 587 East Middle Turnpike, P.O.Box 370, Manchester, CT 06045
 Tel. (860) 646-1102 Fax (860) 646-0823

Analysis Report
 September 28, 2017

FOR: Attn: Mr. Erik Plimpton
 TRC Environmental Corp.
 21 Griffin Rd North
 Windsor, CT 06095

Sample Information

Matrix: BULK
 Location Code: TRC-PCB
 Rush Request: 72 Hour
 P.O.#: 222165-5616.710

Custody Information

Collected by: TM
 Received by: B
 Analyzed by: see "By" below

Date Time
 07/06/17 11:16
 09/21/17 18:33

Laboratory Data

SDG ID: GBZ06769
 Phoenix ID: BZ06773

Project ID: DOT BROOKVIEW MF MAIN BLOG
 Client ID: C2-A

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
Caulk Extraction for PCB	Completed				09/21/17	BB/Q	8W3540C
<u>PCB (Soxhlet SW3540C)</u>							
PCB-1016	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1221	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1232	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1242	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1248	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1254	1.7	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1260	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1262	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
PCB-1268	ND	0.75	mg/Kg	5	09/23/17	AW	8W8082A
<u>QA/QC Surrogate</u>							
% DCBP	53		%	5	09/23/17	AW	30 - 150 %
% TOMK	59		%	5	09/23/17	AW	30 - 150 %

Parameter	Result	RL/ PQL	Units	Dilution	Date/Time	By	Reference
-----------	--------	------------	-------	----------	-----------	----	-----------

RL/PQL=Reporting/Practical Quantitation Level ND=Not Detected BRL=Below Reporting Level
QA/QC Surrogates: Surrogates are compounds (preceded with a %) added by the lab to determine analysis efficiency. Surrogate results(%) listed in the report are not "detected" compounds.

Comments:

Results are reported on an "as received" basis, and are not corrected for dry weight.

PCB Comment:

For PCBs, in order to reach the desired RL, multiple cleanup steps were performed. The extract was cleaned up with a combination of sulfuric acid, potassium permanganate, copper powder and additional florisol.

All soils, solids and sludges are reported on a dry weight basis unless otherwise noted in the sample comments.

If there are any questions regarding this data, please call Phoenix Client Services.
This report must not be reproduced except in full as defined by the attached chain of custody.

Phyllis Shiller, Laboratory Director

September 28, 2017

Reviewed and Released by: Kathleen Cresala, QA/QC Officer



Environmental Laboratories, Inc.
 687 East Middle Turnpike, P.O. Box 370, Manchester, CT 06046
 Tel. (860) 845-1102 Fax (860) 845-0823

QA/QC Report

September 28, 2017

QA/QC Data

SDG I.D.: GBZ06769

Parameter	Blank	Blk RL	LCS %	LCSD %	LCS RPD	MS %	MSD %	MS RPD	% Rec Limits	% RPD Limits
QA/QC Batch 402828 (mg/Kg), QC Sample No: BZ06114 10X (BZ06770, BZ06771)										
<u>Polychlorinated Biphenyls - Bulk</u>										
PCB-1016	ND	0.17	87	101	14.9				40 - 140	30
PCB-1221	ND	0.17							40 - 140	30
PCB-1232	ND	0.17							40 - 140	30
PCB-1242	ND	0.17							40 - 140	30
PCB-1248	ND	0.17							40 - 140	30
PCB-1254	ND	0.17							40 - 140	30
PCB-1260	ND	0.17	95	92	3.2				40 - 140	30
PCB-1262	ND	0.17							40 - 140	30
PCB-1268	ND	0.17							40 - 140	30
% DCBP (Surrogate Rec)	126	%	102	100	2.0				30 - 150	30
% TCMX (Surrogate Rec)	91	%	94	109	14.8				30 - 150	30

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

QA/QC Batch 402441 (mg/Kg), QC Sample No: BZ06769 10X (BZ06769, BZ06772, BZ06773)

Polychlorinated Biphenyls - Bulk

PCB-1016	ND	0.17	87	90	3.4				40 - 140	30
PCB-1221	ND	0.17							40 - 140	30
PCB-1232	ND	0.17							40 - 140	30
PCB-1242	ND	0.17							40 - 140	30
PCB-1248	ND	0.17							40 - 140	30
PCB-1254	ND	0.17							40 - 140	30
PCB-1260	ND	0.17	84	88	4.7				40 - 140	30
PCB-1262	ND	0.17							40 - 140	30
PCB-1268	ND	0.17							40 - 140	30
% DCBP (Surrogate Rec)	108	%	90	103	13.5				30 - 150	30
% TCMX (Surrogate Rec)	90	%	83	92	10.3				30 - 150	30

Comment:

A LCS and LCS Duplicate were performed instead of a matrix spike and matrix spike duplicate.

If there are any questions regarding this data, please call Phoenix Client Services at extension 200.

- RPD - Relative Percent Difference
- LCS - Laboratory Control Sample
- LCSD - Laboratory Control Sample Duplicate
- MS - Matrix Spike
- MS Dup - Matrix Spike Duplicate
- NC - No Criteria
- Intf - Interference

Phyllis Shiller
 Phyllis Shiller, Laboratory Director
 September 28, 2017

Thursday, September 28, 2017

Criteria: None

State: CT

Sample Criteria Exceedances Report

GBZ06769 - TRC-PCB

Sample No	Acode	Phoenix Analyte	Criteria	Result	RL	Criteria	RL	Analysis Units
0206773	SPCB_SOXR	PCB-1254	CT / Requested PCB RL /	1700	760	1000	1000	ug/Kg

Phoenix Laboratories does not assume responsibility for the data contained in this report. It is provided as an additional tool to identify requested criteria exceedances. All efforts are made to ensure the accuracy of the data (obtained from appropriate agencies). A lack of exceedance information does not necessarily suggest conformance to the criteria. It is ultimately the site professional's responsibility to determine appropriate compliance.



Environmental Laboratories, Inc.
667 East Middle Turnpike, P.O. Box 370, Manchester, CT 06048
Tel. (860) 648-1102 Fax (860) 648-0823



Analysis Comments

September 28, 2017

SDG I.D.: GBZ08769

The following analysis comments are made regarding exceptions to criteria not already noted in the Analysis Report or QA/QC Report: None.

80 Lupes Drive
Stratford, CT 06615



Tel: (203) 377-9984
Fax: (203) 377-9952
e-mail: cet1@cetlabs.com

Client: Mr. Erik Plimpton
TRC Environmental Consultants
21 Griffin Rd., North
Windsor, CT 06095

Analytical Report

CET# 8110852R



Report Date: December 10, 2018
Project: CT DOT, Brookfield MF
Project Number: 222165.5616.0710

Connecticut Laboratory Certificate: PH 0116
Massachusetts Laboratory Certificate: M-CT903
Rhode Island Laboratory Certificate: 199



New York NELAP Accreditation: 11982
Pennsylvania Laboratory Certificate: 68-02927

CET # : 8110852

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

SAMPLE SUMMARY

The sample(s) were received at 22.0°C.

This report contains analytical data associated with following samples only.

Sample ID	Laboratory ID	Matrix	Collection Date/Time	Receipt Date
Office 1&2 Door Frames	8110852-01	Caulk	11/29/2018 11:00	11/30/2018
Ext Bay 10 Around Conduit	8110852-02	Caulk	11/29/2018 11:30	11/30/2018
Exterior Boiler Door	8110852-03	Caulk	11/29/2018 11:45	11/30/2018

Client Sample ID Office 1&2 Door Frames

Lab ID: 8110852-01

PCBs by Soxhlet

Method: EPA 8082A

Analyst: PJB

Matrix: Caulk

Analyte	Result (mg/kg (As Rec))	RL (mg/kg (As Rec))	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
PCB-1016	ND	0.40	4	EPA 3540C	B81.0317	12/03/2018	12/05/2018 11:13	
PCB-1221	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1232	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1242	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1248	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1254	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1260	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1268	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
PCB-1262	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:13	
Surrogate: TC/MX [1C]	76.0 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:13	
Surrogate: TC/MX [2C]	74.7 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:13	
Surrogate: DCH [1C]	73.1 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:13	
Surrogate: DCH [2C]	71.2 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:13	

CET #: 8110852

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

Client Sample ID Ext Bay 10 Around Conduit

Lab ID: 8110852-02

PCBs by Soxhlet

Method: EPA 8082A

Analyst: PJB

Matrix: Caulk

Analyte	Result (mg/kg (As Rec))	RL (mg/kg (As Rec))	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
PCB-1016	ND	0.40	4	EPA 3540C	B81.0317	12/03/2018	12/05/2018 11:32	
PCB-1221	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
PCB-1232	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
PCB-1242	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
PCB-1248	ND	0.40	4	EPA 3540C	B81.0317	12/03/2018	12/05/2018 11:32	
PCB-1254	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
PCB-1260	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
PCB-1268	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
PCB-1262	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:32	
Surrogate: TCMX [1C]	70.2 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:32	
Surrogate: TCMX [2C]	70.9 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:32	
Surrogate: DCB [1C]	69.4 %	30 - 150			B81.0317	12/03/2018	12/05/2018 11:32	
Surrogate: DCB [2C]	68.0 %	30 - 150			B8L0317	12/03/2018	12/05/2018 11:32	

CET #: 8110852

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

Client Sample ID Exterior Roller Door

Lab ID: 8110852-03

PCBs by Soxhlet

Method: EPA 8082A

Analyst: PJB

Matrix: Caulk

Analyte	Result (mg/kg (As Rec))	RI (mg/kg (As Rec))	Dilution	Prep Method	Batch	Prepared	Date/Time Analyzed	Notes
PCB-1016	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1221	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1232	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1242	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1248	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1254	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1260	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1268	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
PCB-1262	ND	0.40	4	EPA 3540C	B8L0317	12/03/2018	12/05/2018 11:50	
Surrogate: TCMX [1C]	76.4 %	30 - 150			B8L0317	12/03/2018	12/05/2018 11:50	
Surrogate: TCMX [2C]	77.5 %	30 - 150			B8L0317	12/03/2018	12/05/2018 11:50	
Surrogate: DCB [1C]	77.0 %	30 - 150			B8L0317	12/03/2018	12/05/2018 11:50	
Surrogate: DCB [2C]	76.7 %	30 - 150			B8L0317	12/03/2018	12/05/2018 11:50	

CET # : 8110852

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

QUALITY CONTROL SECTION

Batch B8L0317 - EPA 8082A

Analyte	Result (mg/kg (As Rec))	RL (mg/kg (As Rec))	Spike Level	Source Result	% Rec	% Rec Limits	RPD	RPD Limit	Notes
Blank (B8L0317-BLK1)					Prepared: 12/3/2018 Analyzed: 12/5/2018				
PCB-1016	ND	0.10							
PCB-1221	ND	0.10							
PCB-1232	ND	0.10							
PCB-1242	ND	0.10							
PCB-1248	ND	0.10							
PCB-1254	ND	0.10							
PCB-1260	ND	0.10							
PCB-1268	ND	0.10							
PCB-1262	ND	0.10							
<i>Surrogate: TCMX [1C]</i>					67.3	30 - 150			
<i>Surrogate: TCMX [2C]</i>					66.9	30 - 150			
<i>Surrogate: DCB [1C]</i>					76.4	30 - 150			
<i>Surrogate: DCB [2C]</i>					70.9	30 - 150			
LCS (B8L0317-B81)					Prepared: 12/3/2018 Analyzed: 12/5/2018				
PCB-1016	0.699	0.10	1.000		69.9	40 - 140			
PCB-1260	0.744	0.10	1.000		74.4	40 - 140			
<i>Surrogate: TCMX [1C]</i>					68.3	30 - 150			
<i>Surrogate: TCMX [2C]</i>					67.4	30 - 150			
<i>Surrogate: DCB [1C]</i>					69.8	30 - 150			
<i>Surrogate: DCB [2C]</i>					66.1	30 - 150			

CET # : 8110852

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

CASE NARRATIVE

Revision: Original report dated 12/6/2018; added RCP Package per chain of custody.

CET #: 8110852


Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710

All questions related to this report should be directed to David Ditta, Timothy Fusco, or Robert Blake at 203-377-9984.

Sincerely,

This technical report was reviewed by Timothy Fusco



David Ditta
Laboratory Director

Project Manager

Report Comments:

Sample Result Flags:

- E- The result is estimated, above the calibration range.
- H- The surrogate recovery is above the control limits.
- L- The surrogate recovery is below the control limits.
- B- The compound was detected in the laboratory blank.
- P- The Relative Percent Difference (RPD) of dual column analysis exceeds 40%.
- D- The RPD between the sample and the sample duplicate is high. Sample Homogeneity may be a problem.
- + - The Surrogate was diluted out.
- *C1- The Continuing Calibration did not meet method specifications and was biased low for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased low.
- *C2- The Continuing Calibration did not meet method specifications and was biased high for this analyte. Increased uncertainty is associated with the reported value which is likely to be biased high.
- *F1- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the low side.
- *F2- The Laboratory Control Sample recovery is outside of control limits. Reported value for this analyte is likely to be biased on the high side.
- I- The Analyte exceeds %RSD limits for the Initial Calibration. This is a non-directional bias.

All results met standard operating procedures unless indicated by a data qualifier next to a sample result, or a narration in the QC report.

For Percent Solids, if any of the following prep methods (3050B, 3540C, 3545A, 3550C, 5035 and 9013A) were used for samples pertaining to this report, the percent solids procedure is within that prep method.

Complete Environmental Testing is only responsible for the certified testing and is not directly responsible for the integrity of the sample before laboratory receipt.

ND is None Detected at or above the specified reporting limit

RL is the Reporting Limit

All analyses were performed in house unless a Reference Laboratory is listed.

Samples will be disposed of 30 days after the report date.

CET #: 8110852

Project: CT DOT, Brookfield MF

Project Number: 222165.5616.0710



80 Lupes Drive
Stratford, CT 06615

Tel: (203) 377-9984
Fax: (203) 377-9952
email: cet1@cetlabs.com

Quality Control Definitions and Abbreviations

Internal Standard (IS)	An Analyte added to each sample or sample extract. An internal standard is used to monitor retention time, calculate relative response, and quantify analytes of interest.
Surrogate Recovery	The % recovery for non-target organic compounds that are spiked into all samples. Used to determine method performance.
Continuing Calibration Batch	An analytical standard analyzed with each set of samples to verify initial calibration of the system. Samples that are analyzed together with the same method, sequence and lot of reagents within the same time period.
ND	Not detected at or above the specified reporting limit.
RL	Reporting Limit
Dilution	Multiplier added to detection levels (MDL) and/or sample results due to interferences and/or high concentration of target compounds.
Duplicate	Result from the duplicate analysis of a sample.
Result	Amount of analyte found in a sample.
Spike Level	Amount of analyte added to a sample
Matrix Spike Result	Amount of analyte found including amount that was spiked.
Matrix Spike Dup	Amount of analyte found in duplicate spikes including amount that was spike.
Matrix Spike % Recovery	% Recovery of spiked amount in sample.
Matrix Spike Dup % Recovery	% Recovery of spiked duplicate amount in sample.
RPD	Relative percent difference between Matrix Spike and Matrix Spike Duplicate.
Blank	Method Blank that has been taken through all steps of the analysis.
LCS % Recovery	Laboratory Control Sample percent recovery. The amount of analyte recovered from a fortified sample.
Recovery Limits	A range within which specified measurements results must fall to be compliant.
CC	Calibration Verification

Flags:

- H- Recovery is above the control limits
- L- Recovery is below the control limits
- B- Compound detected in the Blank
- P- RPD of dual column results exceeds 40%
- #- Sample result too high for accurate spike recovery.



Connecticut Laboratory Certification P110116
Massachusetts Laboratory Certification M-CT1903

New York NYSAP Accreditation 11982
Rhode Island Certification 199

Complete Environmental Testing, Inc.

80 Lupes Drive, Stratford, CT 06615 • Tel: 203-377-9984 • Fax: 203-377-9952 • www.cetlabs.com



REASONABLE CONFIDENCE PROTOCOL LABORATORY ANALYSIS QA/QC CERTIFICATION FORM

Laboratory Name: Complete Environmental Testing, Inc.

Client: TRC Environmental Consultants

Project Location: CT DOT, Brookfield MP

Project Number: 222165.5616.0710

Laboratory Sample ID(s):

Sample Date(s):

8110852-01 thru 8110852-03

11/29/2018

List RCP Methods Used:

CET #: 8110852

EPA #082A

1	For each analytical method referenced in this laboratory report package, were all specified QA/QC performance criteria followed, including the requirement to explain any criteria falling outside of acceptable guidelines, as specified in the CTDEP method-specific Reasonable Confidence Protocol documents?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
1A	Were the method specified preservation and holding time requirements met?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
1B	VPII and EPII Methods only: Was the VPII and EPII method conducted without significant modifications (see Section 11.3 of respective RCP methods)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
2	Were all samples received by the laboratory in a condition consistent with that described on the associated chain-of-custody document(s)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
3	Were samples received at an appropriate temperature (< 6 degrees C)?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4	Were all QA/QC performance criteria specified in the CT DEP Reasonable Confidence Protocol documents achieved?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
5a	a) Were reporting limits specified or referenced on the chain-of-custody?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
5b	b) Were these reporting limits met?	<input type="checkbox"/> Yes <input type="checkbox"/> No
6	For each analytical method referenced in this laboratory report package, were results reported for all constituents identified in the method-specific analyte lists presented in the Reasonable Confidence Protocol documents?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
7	Are project specific matrix spikes and laboratory duplicates included with this data set?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

Notes: For all questions to which the response was "No" (with the exception of question #7), additional information must be provided in an attached narrative. If the answer to question #1, #1A, or #1B is "No", the data package does not meet the requirements for "Reasonable Confidence."

This form may not be altered and all questions must be answered.

I, the undersigned, attest under the pains and penalties of perjury that, to the best of my knowledge and belief and based upon my personal inquiry of those responsible for providing the information contained in this analytical report, such information is accurate and complete.

Authorized Signature:

Position: Laboratory Director

Printed Name: David Ditta

Date: 12/10/2018

Name of Laboratory: Complete Environmental Testing, Inc.

This certification form is to be used for RCP methods only.

RCP Case Narrative

3- The samples were received at 22 degrees C.


7- Project specific QC was not requested by the client.

QC Batch/Sequence Report

Batch	Sequence	CET ID	Sample ID	Specific Method	Matrix	Collection Date
B8L0317	S8L0511	8110852-01	Office 1&2 Door Frames	EPA 8082A	Caulk	11/29/2018
B8L0317	S8L0511	8110852-02	Ext Bay 10 Around Conduit	EPA 8082A	Caulk	11/29/2018
B8L0317	S8L0511	8110852-03	Exterior Boiler Door	EPA 8082A	Caulk	11/29/2018



8110852



21 GRIFFIN ROAD NO

WINDSOR, CONNECTICUT 06095

TELEPHONE (860) 298-9692

FAX (860) 298-6380

PROJECT NUMBER

222165-5416-0710

SIGNATURE

Carmen Jacko

PROJECT NAME

CONN DOT
BROOKFIELD MF

INSPECTOR

CARMEN JACKO

PARAMETERS

EPA 8082 (3540)

CONTAINERS

of Amber Glass
of Clear Glass
Mark X2 =
Preservative

TURNAROUND TIME

X Standard TAT 7-10 Days

Rush TAT Date Needed:

LAB ID #.

TYPE
COMP GRAB

SAMPLE LOCATION

DATE TIME

Lab ID: SAMPLE ID:

1

11/29/18 1100

X

X

OFFICE 1-2 DOOR FRAME

2

1130

X

X

EXT. BAY 10 AROUND ROUGH

3

1145

X

X

EXTERIOR BOLLER DOOR

WHITE PLYABLE DOOR FRAME CAULK

WHITE/LOSY SOFT CAULK

WHITE/RASHY SOFT CAULK

NOTES

DAS RATES APPLY

CHAIN OF CUSTODY

Relinquished by: (Signature)

Carmen Jacko

Date: 11/29/18

Received by: (Signature)

Greg Gilroy

Date: 11/30/18

Relinquished by: (Signature)

Greg Gilroy

Date: 11/30/18

Received by: (Signature)

M. J. Jacko

(Printed) CARMEN JACKO

Time: 11/29/18

(Printed) GREG GILROY

Date: 11/30/18

(Printed) GREG GILROY

Time: 13:50

(Printed) M. J. Jacko

Remarks: SEND TO EPLIMPTON@TRCSOLUTIONS.COM

Report to: Include CT DPH RCP Report

Condition upon Receipt

APPENDIX K

**ITEMIZED COST ESTIMATE FOR ASBESTOS
ABATEMENT**

TRC
Asbestos Abatement Cost Estimate
CTDAS Contract # 16PSX0110
(Effective: May 1, 2017 – April 30, 2022)

Site: Brookfield Maintenance Facility - Main Building, Brookfield, CT

TRC Project #: 222165.5616.0710

DOT Project #: 34-350

<u>ITEM DESCRIPTION</u>	<u>QTY</u>	<u>UNIT</u>	<u>COST</u>	<u>MULT</u>	<u>TOTAL</u>
ASBESTOS REMOVAL					
HEPA VACUUMING		SF	\$ 0.24	1 \$	-
PIPING REMOVAL <6" INCL FITTINGS		LF	\$ 1.50	1 \$	-
PIPING REMOVAL 6"-12" INCL FITTINGS		LF	\$ 2.25	1 \$	-
PIPING REMOVAL >12" INCL FITTINGS		LF	\$ 3.15	1 \$	-
GLOVE BAG FIRST 25		EA	\$ 22.50	1 \$	-
GLOVEBAG 25-50		EA	\$ 19.50	1 \$	-
GLOVEBAG OVER 50		EA	\$ 17.00	1 \$	-
REMOVE EQUIPMENT INSULATION		SF	\$ 3.25	1 \$	-
REMOVE HVAC DUCT INSULATION		SF	\$ 3.25	1 \$	-
REMOVE HVAC DUCT FLEX CONN		SF	\$ 2.50	1 \$	-
FLOOR TILE AND MASTIC		SF	\$ 1.00	1 \$	-
FLOOR TILE (NO MASTIC)		SF	\$ 0.60	1 \$	-
SPRAY ON FIREPROOFING		SF	\$ 2.25	1 \$	-
PLASTER LATHE AND BLACK IRON		SF	\$ 2.25	1 \$	-
ACCOUSTIC OR METAL PAN CEILING INCL GRID		SF	\$ 1.50	1 \$	-
ACCOUSTIC PANELS CLEAN GRID FOR REUSE		SF	\$ 1.25	1 \$	-
ACCOUSTIC PLASTER FINISH MTL (SCRAPE)		SF	\$ 2.00	1 \$	-
PATCH/SEAL DAMAGED INSULATION		SF	\$ 1.00	1 \$	-
CONTAMINATED SOIL (2" DEPTH)		SF	\$ 1.30	1 \$	-
TRANSITE MATERIAL		SF	\$ 0.80	1 \$	-
ROOFING OR FLASHING	4	SF	\$ 1.20	1 \$	4.80
UNDERGROUND PIPE OR INSULATION (HAND EXCAVATION)		LF	\$ 9.50	1 \$	-
CARPET OVER TILE		SF	\$ 0.72	1 \$	-
WALL BASE AND MASTIC		LF	\$ 0.72	1 \$	-
REMOVAL OF DRYWALL PARTITIONS INCL FRAMING		SF	\$ 0.90	1 \$	-
REMOVAL OF CMU WALL		SF	\$ 1.65	1 \$	-
PREP WORK AREA	600	SF	\$ 0.97	1 \$	485.00
SOLID BARRIER OR ACCESS TUNNELS 2X4 AND PLYWOOD		SF/SA	\$ 1.00	1 \$	-
STANDBY ABATEMENT PERSONNEL	8	HR	\$ 77.00	1 \$	616.00
SELECTIVE DEMOLITION TO ACCESS ACM		SF	\$ 1.00	1 \$	-
REMOVAL OF FLOOR LEVELING MATERIAL		SF	\$ 0.75	1 \$	-
MISCELLANEOUS ITEMS					
MOBILIZATION (1 PER WORK AREA)	1	EA	\$ 250.00	1 \$	250.00
WORKER DECON (1 PER WORK AREA)	1	EA	\$ 250.00	1 \$	250.00
TEMP ELECTRICAL CONNECTION (LICENSED ELECTRICIAN)		EA	\$ 250.00	1.1 \$	-
TEMP GENERATOR		DY	\$ 20.00	1.1 \$	-
ACM DISPOSAL (INCLUDES TRANSPORTATION)	2	CY	\$ 55.00	1.1 \$	121.00
HAZARDOUS WASTE DISPOSAL (INCLUDES TRANS)		CY	\$ 250.00	1.1 \$	-
CONSTRUCTION DEBRIS DISPOSAL (INCLUDES TRANS)		CY	\$ 25.00	1.1 \$	-
FIXED SCAFFOLDING		SF	\$ 10.00	1.1 \$	-
EXCAVATION TO EXPOSE UNDERGROUND PIPE		CY	\$ 15.00	1.1 \$	-
PROJECT NOTIFICATION (1% OF ABATEMENT COST)	1	EA	\$ 69.87	1.1 \$	76.85
PROJECT BOND (3% OF TOTAL CONTRACT)		EA		1.1 \$	-
ESCALATION FACTORS					
WORK SURFACES 10-20 FEET HIGH				15% \$	-
WORK SURFACES OVER 20 FEET HIGH				30% \$	-
NON REGULAR WORK HOURS 6:00PM-6:00AM AND WEEKEND				30% \$	-
EMERGENCY RESPONSE (<24 hr)				30% \$	-
CONFINED SPACE WORK				15% \$	-
REMOVAL OF MULTIPLE LAYERS OF TILE (EACH ADDIT LAYER)				50% \$	-
REMOVE ON LIVE STEAM EQUIPMENT				25% \$	-
EXTERIOR WORK			\$ 200.00	30% \$	60.00
NEGOTIATED ITEMS					
Exterior vent caulk	1	EA	\$ 200.00	1 \$	200.00
		SF		1 \$	-
				1 \$	-
				1 \$	-
				1 \$	-
CONTINGENCY (10%)				10% \$	206.37
TOTAL				\$	2,270.02

APPENDIX L

**HAZARDOUS/REGULATED MATERIALS,
WASTES AND ITEMS REMOVAL COST ESTIMATE .**

TRC
Hazardous/Regulated Materials, Wastes & Items Removal Cost Estimate
(excluding asbestos abatement)
CTDAS Contract # 14PSX0314
(Effective: March 3, 2015 – February 28, 2020)

Item	Item #	Quantity	Units	Rate	Total
Operations Supervisor	1	4	hrs	\$50.00	\$200.00
Equipment Operator	4	0	hrs	\$46.00	\$0.00
Equipment Operator OT	4	0	hrs	\$69.00	\$0.00
Laborer	8	32	hrs	\$46.00	\$1,472.00
Laborer OT	8	0	hrs	\$69.00	\$0.00
Driver (Mobilization/Disposal/Vac)	5	8	hrs	\$46.00	\$368.00
Driver (Mobilization/Disposal/Vac) OT	5	0	hrs	\$69.00	\$0.00
Vacuum Truck (oil)	12	0	hrs	\$56.10	\$0.00
Box truck	18	24	hrs	\$16.00	\$384.00
Utility Trucks (< 18000 GVW)	17	0	hrs	\$16.00	\$0.00
Loader/Backhoe (12' dig depth)	33	0	hrs	\$43.00	\$0.00
Loader/Backhoe (15' dig depth)	34	0	hrs	\$45.00	\$0.00
Lowbed Trailer/Tractor	27	0	hrs	\$50.00	\$0.00
Triaxle Dump Truck	23	0	hrs	\$45.00	\$0.00
Roll-off Truck	30	0	hrs	\$48.00	\$0.00
Roll-off Container (30 CY)	31	0	hrs	\$5.00	\$0.00
Roll-off Liners (haz waste/CRW soil)	130	0	ea	\$65.00	\$0.00
* Highlift		0	hrs	\$35.00	\$0.00
Water Wagon	29	0	hrs	\$20.00	\$0.00
*Hoses (dust suppression)		0	hrs	\$15.00	\$0.00
Frac Tank (20,000 gal)	89	0	hrs	\$7.50	\$0.00
5,000 psi Hi-Pressure Cleaner	82	0	hrs	\$20.00	\$0.00
Silt Fence	131	0	LF	\$1.00	\$0.00
Level C PPE (Pb)	90	8	person-hrs	\$22.00	\$176.00
Poly (10-mil sheeting 20'x100')	124	1	ea	\$95.00	\$95.00
Speedi-Dry (50 lb bag)	132	0	bag	\$10.00	\$0.00
17C DOT 55 gal Drums (haz items)	119	5	ea	\$40.00	\$200.00
Generator (5 kw)	80	0	hrs	\$20.00	\$0.00
* Dispose of haz-waste/regulated items		20	ea	\$100.00	\$2,000.00
* Dispose of AST/UST/sump contents (oil)		0	gal	\$1.00	\$0.00
* Dispose of trench/drain sludge (CRW)		0	CY	\$50.00	\$0.00
* Dispose of sediment/concrete (CRW)		0	CY	\$50.00	\$0.00
* Dispose of contaminated soil (CRW)		0	CY	\$50.00	\$0.00
* Dispose of PCB (CRW)		1	CY	\$125.00	\$125.00
* Dispose of contaminated wood (haz)		0	CY	\$125.00	\$0.00
* Dispose of boiler/fly ash (haz)		0	CY	\$125.00	\$0.00
* CFC Reclaim (subcontractor)		1	day	\$1,000.00	\$1,000.00
Contingency (10%)					\$602.00
TOTAL ESTIMATE					\$6,622.00

* Line items not included in Contract 14PSX0314, rate estimated by TRC
Cost estimate based on assumption of 2 days for hazardous/regulated item removal excluding USTs, fuel island, oil/water separator, hydraulic lifts, floor trench/drains and any potential PCB impacted substrates.

APPENDIX M
PRIOR HAZMAT INSPECTION DATA

I. PROJECT NARRATIVE

Overview

On March 9, 2001, a state-licensed inspector from EnviroMed Services, Inc. (EnviroMed) performed a limited inspection at the Department of Transportation - Maintenance Garage located in Brookfield, Connecticut. The purpose of this limited inspection was to identify the presence of asbestos in suspect building materials in the selected areas as identified by the client, so that any asbestos-containing material could be removed prior to renovation.

Samples were collected according to 40 CFR Part 763.86 and 29 CFR Part 1926.1101, and analyzed using Polarized Light Microscopy (PLM).

A total of sixty-two (62) bulk samples were collected. The bulk materials sampled include: breaching cement, mudded pipe joint insulation, 12"x12" tan vinyl floor tile, mastic under 12"x12" tan vinyl floor tile, 4" brown cove molding, glue behind 4" brown cove molding, 2'x4' suspended ceiling tile (with worm and hole pattern), window glazing (type I), window glazing (type II), window glazing (type III), window glazing (type IV), door frame caulking, patching cement, flashing cement, brown caulking, all layers of built-up roofing material, wallboard/sheetrock, and wallboard joint compound.

Refer to Section II, Bulk Sample Location Diagrams, for bulk sample locations and identification.

Summary of Results

EnviroMed Services, Inc. accredited asbestos laboratory (NVLAP #1514) analyzed the bulk samples. Section III presents the complete list of analytical results for samples collected. The following presents the locations and estimated quantities of materials found to contain asbestos greater than 1.0 percent.

Ground Floor

Boiler Room

There is approximately 1 square foot of breaching cement located at the interface between the boiler breaching and the chimney. This material was found to contain 5-50 percent asbestos.

Generator Room

There is approximately 1 square feet of mudded pipe joint insulation located in this area. This material was found to contain 50 percent asbestos.

Office #1

There is approximately 325 square feet of 12"x12" tan vinyl floor tile and associated mastic located in this area. The 12"x12" tan vinyl floor tile was found to contain 4-5 percent asbestos. The mastic under 12"x12" tan vinyl floor tile was found to contain no asbestos.

Roof

Roofs #1, 2 and 3

There is approximately 85 square feet of patching cement located in these areas. This material was found to contain 10-12 percent asbestos.

There is approximately 650 square feet of flashing cement along the parapet walls, along roof edges and around the two chimneys and mechanical units located on these three roofs. This material was found to contain 30-45 percent asbestos.

Non-Asbestos Containing Materials Found During the Inspection

The following materials were found to contain legally insignificant amounts (0-1 percent) of asbestos: 4" brown cove molding, glue behind 4" brown cove molding, 2'x 4' suspended ceiling tile (with worm and hole pattern), window glazing (type I), window glazing (type II), window glazing (type III), window glazing (type IV), door frame caulking, brown caulking, all layers of built-up roofing material, wallboard/sheetrock, and wallboard joint compound.

See Section IV for a copy of the laboratory analysis sheets for the samples collected.

Sample Number	Location	Material Sampled	Percent Asbestos
25	ground floor office #1 window	window glazing (type III)	NAD
26	ground floor women's room window	window glazing (type IV)	NAD
27	ground floor men's room window	window glazing (type IV)	NAD
28	ground floor office #1 window	window glazing (type IV)	NAD
29	void	void	void
30	void	void	void
31	ground floor office #1	door frame caulking	NAD
32	ground floor hall	door frame caulking	NAD
33	roof #2	patching cement	10
34	roof #1	patching cement	12
35	roof #2 wall	flashing cement	45
36	roof #3 wall	flashing cement	40
37	roof #2 edge	flashing cement	45
38	roof #1 edge	flashing cement	30
39	roof #2 counter flashing	brown caulking	NAD
40	roof #1 parapet cap	brown caulking	NAD
41	roof #2	built-up roofing material top layer	NAD
42	roof #2	built-up roofing material second layer	NAD
43	roof #2	built-up roofing material third layer	NAD
44	roof #2	built-up roofing material fourth layer	NAD
45	roof #2	built-up roofing material fifth layer	NAD
46	roof #2	built-up roofing material sixth layer	NAD
47	roof #2	built-up roofing material seventh layer	NAD
48	roof #2	built-up roofing material bottom layer	NAD

WGS-1

01

done

done

NAD = No Asbestos Detected

Sample Number	Location	Material Sampled	Percent Asbestos
49	roof #1	built-up roofing material top layer	NAD
50	roof #1	built-up roofing material second layer	NAD
51	roof #1	built-up roofing material third layer	NAD
52	roof #1	built-up roofing material fourth layer	NAD
53	roof #1	built-up roofing material fifth layer	NAD
54	roof #1	built-up roofing material sixth layer	NAD
55	roof #1	built-up roofing material seventh layer	NAD
56	roof #1	built-up roofing material eighth layer	NAD
57	roof #1	built-up roofing material bottom layer	NAD
58	ground floor locker room	wallboard/sheetrock	NAD
59	ground floor locker room	wallboard/sheetrock	NAD
60	ground floor locker room	wallboard joint compound	NAD
61	ground floor locker room	wallboard joint compound	NAD
62	ground floor locker room	wallboard joint compound	NAD

58-62

gone

NAD = No Asbestos Detected

III. SUMMARY OF TOXIC LEVEL (≥ 1.0 mg/cm²) XRF SAMPLE RESULTS

**Summary of
Toxic Level (≥ 1.0 mg/cm²) Results**


Sample Number	Sample Location (mg/cm²)	Component (s) Tested	Results
7	Office #1	column	1.2
28	Hall	bulletin board	4.4
37	Men's Room	lower column	1.2
50	Library	door casing	1.9
60	Locker Room	column	1.9
65	Mechanical Room	column	1.5
84	Exterior	garage door lintel	1.5
85	Exterior	garage door lintel	3.0
95	Bay #1	door jamb	1.1
101	Bay #1	garage door casing	1.2
107	Bay #2	window mullion	1.3
114	Bay #3	overhead crane beams	16
115	Bay #3	overhead crane beams	15
120	Bay #3	window mullion	1.5
132	Bays 4-9	metal rack	1.3
139	Bays 4-9	window mullion	1.4
140	Bays 4-9	truck lift diamond plate	1.9
148	Tool Room	wall tool hanger	2.4
164	Bay #10	garage door casing	1.8
165	Bay #10	window mullion	1.7
168	Bay #11	vertical I-Beam	1.2
174	Bay 12-13	wall	5.6
175	Bay 12-13	window mullion	2.1
176	Bay 12-13	metal column	2.6
177	Bay 12-13	upper wall	2.4
178	Bay 12-13	garage door casing	2.4

LEAD INSPECTION DATA PAGE

PROJECT NAME Brockfield Repair Garage
 UNIT NUMBER: Bldg # 81-160

NO. DOORS: _____
 NO. WINDOWS: _____

SAMPLE NUMBER	RESULTS (Mg/cm ²)	SURFACE TYPE	SUBSTRATE	CONDITION	COMMENT
81	0.8	metal	metal	1	Green
82	0.41	Metal	metal	1	Green
83	0.03	metal	metal	1	Brown
84	1.5	Concrete	metal	1	Brown +
85	3.0	Concrete	Wood	1	Brown +
86	5.7	DR	metal	1	Brown
87	0.5	DC	metal	1	Brown
88	0.22	Conduit	metal	1	Tan
89	0.5	metal	metal	1	White
90	0.1	UWL	Concrete	1	White
91	0.24	I-Beam	metal	1	White
92	0.02	CL	Concrete	1	White
93	0.13	Bath stall	Bath stall	1	Tan
94	0.11	Bath stall	metal	1	Tan
95	1.1	DJ	Wood	1	Brown +
96	0.9	DC	Wood	1	Brown
97	0.9	DR	Wood	1	Brown
98	5.02	LWL	Concrete	1	Green
99	0.03	UWL	Concrete	1	White
100	0.74	Tool	metal	1	Green



Legend :
 ◆ = Sample Number & Location

Drawing Title:		Lead Sample Location Diagram	
Prepared by:	EnviroMed Services, Inc. 25 Science Park, New Haven, CT 06511	Date:	7/25/01
Project:	Brookfield DOT Maintenance Garage Floor Plan Brookfield, Connecticut	Scale:	N.T.S.
Prepared for:	State of Connecticut Department of Transportation Newington, Connecticut	Drawn By:	DER
		Approved By:	I.K.
		Drawing No.	1 of 2
EMS 411-01-018			

APPENDIX N
RELATED CORRESPONDENCE

Plimpton, Erik

From: Bedson, Michael F. <Michael.Bedson@ct.gov>
Sent: Wednesday, December 19, 2018 8:35 AM
To: Plimpton, Erik
Cc: Arienti, Stephen
Subject: FW: Project No. 34-350 Construction of a new Brookfield Repair Facility - Re-Kickoff
Attachments: Scope - Brookfield Repair - 12-18-18.doc.pdf; Brookfield Site Plan(02-07-18).pdf; Brookfield Floor Plan.pdf; FW: Project No. 34-350-Brookfield Repair Facility-Lead, Asbestos & Soil Investigations Request

Erik,

We already knew what was going on, but looks like Brookfield maintenance facility is 100% a go. If we could try to get specs and estimates in by the 60% in February that would be great (see date below further down in email). Give me a call if you have any questions.

Thanks,

Mike

From: Bordonaro, Joseph S <Joseph.Bordonaro@ct.gov>
Sent: Wednesday, December 19, 2018 8:09 AM
To: Bedson, Michael F. <Michael.Bedson@ct.gov>
Cc: Strong, Michael J <Michael.Strong@ct.gov>; Maines, Amie B <Amie.Maines@ct.gov>
Subject: FW: Project No. 34-350 Construction of a new Brookfield Repair Facility - Re-Kickoff

Michael,

Project No. 34-350 design has been restarted. See the attached plans and updated scope. Additionally see the attached email with the Environmental Investigations memo that was forwarded to your office earlier this year.

Please let me know if you have any questions.

Thanks,

Joseph Bordonaro
Project Engineer
Connecticut Department of Transportation
Facilities Design
2800 Berlin Turnpike
Newington, CT 06111
Phone: (860) 594-3310

From: Bordonaro, Joseph S
Sent: Wednesday, December 19, 2018 8:00 AM
To: Easdon, Matthew L <Matthew.Easdon@ct.gov>; Carvalho, Malissa <Malissa.Carvalho@ct.gov>; Mercado, Shinel M. <Shinel.Mercado@ct.gov>; Mangiafico, Sebastiano L <Sebastiano.Mangiafico@ct.gov>; Libatique, Ranolfo P <Ranolfo.Libatique@ct.gov>; Silva, Deborah C <Deborah.Silva@ct.gov>; Johnson, Shawn K. <Shawn.Johnson@ct.gov>; Benson, Jesse A <Jesse.Benson@ct.gov>; Mitto, Eaton <Eaton.Mitto@ct.gov>; Witik, Michael P. <Michael.Witik@ct.gov>; Walton, Samara K. <Samara.Walton@ct.gov>
Cc: Strong, Michael J <Michael.Strong@ct.gov>
Subject: Project No. 34-350 Construction of a new Brookfield Repair Facility - Re-Kickoff

Designers are authorized to start the design for Project No. 34-350 per the attached updated scope, proposed site plan, and floor plan, as discussed in yesterday's meeting.

60% Submission Due from Designers: **2/13/2019**

90% Submission Due from Designers: **6/19/2019**

FDP Submission Due from Designers: **9/4/2019**

Please contact me with any concerns.

Thanks,

Joseph Bordonaro

Project Engineer

Connecticut Department of Transportation

Facilities Design

2800 Berlin Turnpike

Newington, CT 06111

Phone: (860) 694-3310

SCOPE FOR CONSTRUCTION OF A NEW BROOKFIELD REPAIR FACILITY
Project No. 0034-0350
12/18/18

GENERAL:

The current "Design Manual for Major Capital Program Facilities and Salt Sheds" is hereby made a part of this scope.

CONSTRUCTION PHASING/COORDINATION:

The new building will be constructed while personnel are located in the existing building. Therefore, no personnel office trailers, restroom trailer, or typical storage containers will be required, and no temporary fuel during construction.

Phasing will consist of the following:

Phase 1: Demolish the cold storage building, three repair bays on north end of the existing building, and motor fuel tanks/island.

Since this project NTP Construction is 3/2020, and 5/2020 is the expiration of unleaded, diesel, waste oil, fuel oil tanks, need to provide temporary waste oil tank and temporary fuel oil tank under this phase.

Phase 2: Construct new building, new motor fuel tanks/dispensers, and perform site work as required for the new facility to be fully operational.

Phase 3: Perform remaining selective demolition of the existing building.

EMPLOYEE AND VEHICLE COUNT:

1. Crews assigned to this facility: N/A.
2. Employees: (11) [(1) female]; optimal (12); plus (0) winter.
3. Vehicles and Equipment: N/A.

NEW BUILDING:

Refer to Preliminary Design Floor Plan dated 01/29/18.

REPAIR OFFICE AREA:

1. Equipment General Supervisor Office, 1 person, half-glass hall door.
2. Garage Supervisor Office, 1 person, half-glass door.
3. Repair Office, 2 people, half-glass door, window overlooking bays.
4. Repair Media Storage Room, Include built-in casework and shelves for manuals, computers, etc.
5. Conference Room, with half-glass hall door, Cot Room.
6. Break Room, with half-glass hall door.

STORES OFFICE AREA:

7. Stores Field Supervisor Office, 1 person, half-glass door, located off the Stockroom, with a window overlooking Stockroom.
8. Stores Material Management Office, including Stores Storeroom Supervisor and Service Vestibule, 2 people, half-glass door, located off the Stockroom, with a window overlooking the Stockroom. Stores Service Vestibule will include a commercial grade sliding parts window/shelf to Repair Bays and voice/data outlet.

GENERAL AREAS:

1. Men's Room and Locker Room.
2. Women's Room and Locker Room.
3. Janitor's Closet.
4. Halls and Vestibule.
5. Electrical Room and Communications Room sized as required.
6. Mechanical Room and Sprinkler Room sized as required, allowing space for a diesel fire pump in case one becomes required.

STORES STOCKROOM:

The following features will be included in the Stockroom for Stores:

1. Install double door between the Stockroom and Repair Bays adjacent to the Service Vestibule.
2. Install appropriate shelving for stock, based on the previous projects with the layout determined during design (TBD with Stores). Add a built-in workbench for Receiving (with a voice/data outlet) and tire racks for storage of tires. Install racks on walls. Install secondary containment detention basin 30-foot long for 55-gallon drums, 5-gallon oil containers, batteries, and cases of antifreeze. Basin design shall match DOT standard recessed design.
3. Include wash fountain and eye/face wash.
4. Provide well-lit aisles.
5. Install a door bell at the Service Vestibule and at the exterior Stockroom door to alert Stores personnel that someone is waiting for assistance. System should ring in the Stockroom and the Stores Material Management Office. Each door bell will ring a different tone to alert personnel to the correct location.

REPAIR BAYS:

The Repair Bays will include:

1. Repair Bays:
 - a. (1) Mobile Column Hydraulic 4-post lift system, 72,000 lbs. Basis-of-design manufacturer shall be Rotary Lift Wireless Mach4 with Mohawk Lift as an equal.
 - b. (1) 2-post lift, 18,000 lbs. Basis-of-design manufacturer shall be Rotary Lift model SP018.
 - c. (1) 90,000 lbs. max capacity modular in-ground scissor lift (instead of parallelogram). Basis-of-design manufacturer shall be Rotary Lift model EFX60/90.
 - d. 3 ton (labeled 2 ton) crane. Basis-of-design matches recent projects.
 - e. Vehicle exhaust system with high temperature hoses servicing all bays.
 - f. Chain link Tool Crib (with Stores No Charge Area) with double doors. Shelving and storage layout (TBD with Repair).
 - g. Workbenches (quantity and location TBD with Repair). Task lighting and electrical receptacles will be provided.
 - h. Specialty Electrical Receptacles: identify type and locations of specialty electrical receptacles (220V, etc.) (TBD with Repair).

- i. Separate oxygen and acetylene bulk storage areas (location TBD with Repair).
 - j. Flammable storage cabinet (location TBD with Repair).
 - k. Radiant floor heating with its own in-line circulating pump.
 - l. Overhead coiling doors.
 - m. Oil and antifreeze disposal systems to pump waste oil or antifreeze into the waste oil or waste antifreeze aboveground storage tanks.
2. Lubricant Storage/Compressor Room:
- a. Fluid storage and distribution system (types and quantities of fluids/areas served, and system basis of design TBD).
 - b. Secondary containment detention basin sized for 55-gallon drums (size and location TBD with Repair). Basin design shall match DOT standard recessed design.
 - c. (2) 330-gallon tanks (motor oil and hydraulic oil).
 - d. Air compressor and related accessories.
3. Weld Shop:
- a. Overhead coiling door.
 - b. 3 ton (labeled 2 ton) crane. Basis-of-design matches recent projects.
 - c. Two fixed welding exhaust systems, one on each side, and one portable welding exhaust unit. All fixed welding exhaust systems shall terminate above the roof.
 - d. Floor anchors.
 - e. Workbenches (quantity and location TBD with Repair). Task lighting and electrical receptacles will be provided.
 - f. Specialty Electrical Receptacles: Identify type and locations of specialty electrical receptacles (220V, etc.) (TBD with Repair).
4. Wash Bay.

SITE IMPROVEMENTS:

Refer to Preliminary Design Site Plan dated 02/07/18.

The following site improvements will be made:

- 1. Include parking spaces for employees plus visitors, plus handicap parking.
- 2. Install perimeter site fencing and gate.
- 3. Site drainage included as required.
- 4. Paving (full depth) as required.
- 5. Install concrete apron adjacent to Weld Shop.
- 6. Site lighting included as required.
- 7. Install block heaters, tied into the BAS System (quantity and location TBD with Repair).
- 8. Install flagpole.
- 9. Install generator with diesel base tank. No sound attenuating enclosure.
- 10. Install 1000 gallon oil-water separator.
- 11. Install 500 gallon aboveground waste oil and waste antifreeze storage tanks.
- 12. Install 3000 gallon diesel fuel and 3000 gallon unleaded gasoline aboveground storage tanks with motor fuel dispensers (DEF requirements TBD with Repair).

13. Utilities:

- a. Natural Gas: New.
- b. Public Water Supply: New.
- c. Public Sewer System: New.
- d. Power: New.
- e. Communications: New.
- f. Cable TV: New.

EXISTING BUILDING AND SITE SELECTIVE DEMOLITION:

The existing facility contains a National Geodetic Survey (NGS) Continuously Operating Reference Station (CORS) Global Positioning System (GPS) that must remain operational at all times from its existing location in the building. A portion of the building will remain for off-season equipment storage. The following selective demolition will be performed:

- 1. Remove the motor fuel island, unleaded, diesel, fuel oil, waste oil tanks, oil-water separator, propane tank, and tank monitoring system. The Brookfield tank replacement programmed for 2019 construction in advance of the 2020 expiration date will not be performed.
- 2. Remove the cold storage building.
- 3. Remove and relocate equipment for Repair & Stores operations.
- 4. Demolish stores stockroom, three repair bays on north end of building, and mechanical and electrical spaces.
- 5. Remove all non-loadbearing interior walls, office areas, bathrooms, etc.
- 6. Perform required roof work and masonry work on building envelope.
- 7. Abandon well.
- 8. Retain bay area floor drains and connect to new oil-water separator.
- 9. Remove all plumbing and mechanical systems.
- 10. Electrical and communication systems required for GPS survey station will remain.
- 11. Remove obsolete electrical systems.

ENVIRONMENTAL:

Environmental Compliance investigations for soil and groundwater, asbestos and lead, and other hazards will be performed.

\\DOT-SDCENG07\ACTDOT_Projects\0034-0350\Facilities_all_other_data\Correspondence\1-Design 0-60% Brookfield\Scope - Brookfield Repair - 2-23-18 rev061918.doc

Plimpton, Erik

From: Bedson, Michael F. <Michael.Bedson@ct.gov>
Sent: Thursday, March 15, 2018 7:20 AM
To: Plimpton, Erik
Cc: Arienti, Stephen; Laliberte, Henry
Subject: RE: Project 0034-0350
Attachments: Env. Compl-Brookfield_FA_Final_0034-0350.pdf

Erik,

Attached is the revised scope from facilities design for the Brookfield, no longer Danbury project. They would like reports, specs, etc...by August of 2018 but FDP isn't until September of 2019. Probably doesn't make sense to conduct pcb sampling anytime soon if it is going to sit and wait to be demolished for such a long period of time. I will speak with the designers and ask if they have any issue with us holding off on completing the sampling until closer to the FDP date late next summer. Just wanted to keep you up to date on what is going on.

Thanks,

Mike

From: Plimpton, Erik [mailto:EPlimpton@trcsolutions.com]
Sent: Friday, January 19, 2018 10:30 AM
To: Bedson, Michael F.
Cc: Arienti, Stephen; Laliberte, Henry
Subject: RE: Project 0034-0350

Yes report was issued for main building (and for CSB)
Word doc of main building attached here, along with full pdf of CSB
Set up a meeting with mike strong or whomever it is and we can go over what they want to do for reno/demo and what will be impacted so we can do specs
We will need to go do a bit more field work in the main building as well, to collect a tcpb waste sample once we know what the projected waste stream will be, and possibly to sample one of the caulks for pcb that for now we have left unsampled and noted as potentially pcb containing.

Erik R. Plimpton, PE, CHMM, CMC
Vice President
Eastern Region Practice Leader
Building Sciences & Industrial Hygiene



21 Griffin Road North, Windsor, CT 06095
T: 860.298.6280 | F: 860.298.6380 | C: 860.798.4699

[LinkedIn](#) | [Twitter](#) | [Blog](#) | [Flickr](#) | www.trcsolutions.com



[WorkCare \(888\) 449-7787](#)



[Incident Notification Report](#)



[Auto Incident Report](#)



[Safe Catch Report](#)

5016

Also look Above CT
for old photos &
sample of
land.
(photos)

From: Bedson, Michael F. [<mailto:Michael.Bedson@ct.gov>]
Sent: Friday, January 19, 2018 10:16 AM
To: Plimpton, Erik <EPlimpton@trcsolutions.com>
Subject: Project 0034-0350

Erik,

Just got a call from the designer of 0034-0350 regarding the Brookfield Facility. Apparently the construction cost of building a new Danbury facility has become so cost prohibitive they are now looking to demo some of the main Brookfield building and add onto it. I can't remember exactly what we did for the Brookfield main building. I believe you guys did run through there and perform a survey, but I don't remember if I received a hard copy report from you, or if we put one together at all.

Let me know if we have a report, and if not let's put one together based on the information we have. Designer would like to have a meeting with us in the near future to go over the changes that will be taking place. Who knows if the Cold Storage Building gets demolished now.

Thanks,

Mike

Michael Bedson, EIT
Environmental Compliance
Department of Transportation
2800 Berlin Tpke, Newington, CT 06111
D. 860-594-3004 M. 860-816-4656

STATE OF CONNECTICUT
DEPARTMENT OF TRANSPORTATION




memorandum

subject: Lead, Asbestos, and Soil Investigations
Brookfield Repair Facility
Project No.: 34-350

date: March 6, 2018

to: Mr. Adam G. Fox, P.E.
Transportation Principal Engineer
Bureau of Engineering and Construction

from: Mr. Christopher J. Bonsignore, P.E. 
Transportation Principal Engineer
Bureau of Engineering and Construction

Christopher J.
Bonsignore
P.E.
2018-03-06
17:00:43-09:00

This office is requesting the following:

Perform a Task 210 to fully characterize the existing site. The existing UST's will be removed and replaced with AST's (motor fuel) or UST's (OWS) as part of this project.

Perform a Task 710/720 and hazardous materials investigation in the existing building and cold storage building. The existing building will be partially demolished and used for cold storage. The existing cold storage building will be demolished.

A preliminary site plan with proposed boring locations, floor plan, and the current scope of work are attached. PE efforts for this project will be under the above-noted project number. A previous request was put in under this PE number for another site (Danbury) - see attached.

The FDP for the project is September 2019, although it would be desirable to receive the reports by August 2018 to coincide with the Design Development submission.

Should you have any questions or need any additional information, please contact Matthew Easdon at 860-594-3393 or the Project Engineer, Joseph Bordonaro, at 860-594-3310.

Attachments

Matthew Easdon/me/sk



cc: James A. Fallon
David A. Hartley
Christopher J. Bonsignore – Michael J. Strong – Joseph S. Bordonaro



D:\program files\bentley\projectwise\d0217994\Env. Compl- Brookfield_FA_Final_0034-0350.doc



FUEL OIL UNDERGROUND STORAGE TANK TO BE REMOVED. 2000 GALLON FUEL OIL ABOVEGROUND STORAGE TANK AND ASSOCIATED PIPING TO BE INSTALLED

BUILDING TO REMAIN, TANK MONITORING SYSTEM TO REMAIN, REMOVAL AND RELOCATION OF EQUIPMENT FOR REPAIR AND STORES OPERATIONS TBD


APPROXIMATE CONSTRUCTION LIMITS

COLD STORAGE BUILDING TO BE REMOVED

MOTOR FUEL UNDERGROUND STORAGE TANKS AND MOTOR FUEL ISLAND TO BE REMOVED

WASTE OIL TANK TO BE REMOVED

OWS TO REMAIN



1050 Federal Rd

202

Industrial Park Dr

Federal Rd

Plimpton, Erik

From: Plimpton, Erik
Sent: Friday, January 19, 2018 10:29 AM
To: 'Bedson, Michael F.'
Cc: Arienti, Stephen; Laliberte, Henry
Subject: RE: Project 0034-0350
Attachments: 5616 DOT rpt INSPECTION SURVEY_Brookfield MF Main Building.doc; 5616 Brookfield Maintenance Facility - CSB - IR (reduced).pdf

TBS

Yes report was issued for main building (and for CSB)

Word doc of main building attached here, along with full pdf of CSB

Set up a meeting with mike strong or whomever it is and we can go over what they want to do for reno/demo and what will be impacted so we can do specs

We will need to go do a bit more field work in the main building as well, to collect a tcip pb waste sample once we know what the projected waste stream will be, and possibly to sample one of the caulks for pcb that for now we have left unsampled and noted as potentially pcb containing.

Erik R. Plimpton, PE, CHMM, CMC
Vice President
Eastern Region Practice Leader
Building Sciences & Industrial Hygiene



21 Griffin Road North, Windsor, CT 06095
T: 860.298.6280 | F: 860.298.6380 | C: 860.798.4699

[LinkedIn](#) | [Twitter](#) | [Blog](#) | [Flickr](#) | www.trcsolutions.com



[WorkCare \(888\) 449-7787](#)



[Incident Notification Report](#)



[Auto Incident Report](#)



[Safe Catch Report](#)

From: Bedson, Michael F. [mailto:Michael.Bedson@ct.gov]
Sent: Friday, January 19, 2018 10:16 AM
To: Plimpton, Erik <EPlimpton@trcsolutions.com>
Subject: Project 0034-0350

Erik,

Just got a call from the designer of 0034-0350 regarding the Brookfield Facility. Apparently the construction cost of building a new Danbury facility has become so cost prohibitive they are now looking to demo some of the main Brookfield building and add onto it. I can't remember exactly what we did for the Brookfield main building. I believe you guys did run through there and perform a survey, but I don't remember if I received a hard copy report from you, or if we put one together at all.

Let me know if we have a report, and if not let's put one together based on the information we have. Designer would like to have a meeting with us in the near future to go over the changes that will be taking place. Who knows if the Cold Storage Building gets demolished now.

Thanks,

Mike

Michael Bedson, EIT
Environmental Compliance
Department of Transportation
2800 Berlin Tpke, Newington, CT 06111
D. 860-594-3004 M. 860-816-4656