

Appendix H  
UConn Usage by  
pool 10-1-14 to  
Present

			Memo	Name	Item	Qty
UConn						
	<b>Brundage Pool</b>					
			CARTRIDGE 10" X 20 1/16" 120 S 22006 C9481 P	UConn:Brundage Pool	MATERIAL SERVICE	2.00
			FREIGHT - UPS / FEDEX	UConn:Brundage Pool	FREIGHT (FREIGHT)	1.00
			9/2 - 9/25 - LABOR TO DIAGNOSE ISSUES WITH A	UConn:Brundage Pool	Labor	5.50
			PULSAR PUMP	UConn:Brundage Pool	MATERIAL SERVICE	1.00
			MALE ADAPTER 1.5" SCD40	UConn:Brundage Pool	MALE ADAPT 1.5 (MALE ADAPTER 1.5" SCD40)	1.00
			1-1/2" S40 90° ELBOW SKT-SKT	UConn:Brundage Pool	90 1.5 S40 (1-1/2" S40 90° ELBOW SKT-SKT)	1.00
			PIPE RIGID 1-1/2" SCD40 (FOOT)	UConn:Brundage Pool	PIPE 1.5 S40 (PIPE RIGID 1-1/2" SCD40 (FOOT))	2.00
			COUPLER S40 1-1/2" SKT - SKT	UConn:Brundage Pool	COUP 1.5 S40 (COUPLER S40 1-1/2" SKT - SKT)	1.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Brundage Pool	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION ORI	12.00
	Total Brundage Pool					26.50
	<b>Burton Family Football Complex</b>					
			HC170 HARMSCO FILTER CARTRIDGES	UConn:Burton Family Football Complex	MATERIAL SERVICE	2.00
			2/11 - TROUBLESHOOT CHLORINE INJECTOR LE	UConn:Burton Family Football Complex	Labor	0.50
			2/13 - CHANGED CHLORINE INJECTOR & CHECK	UConn:Burton Family Football Complex	Labor	1.00
			CHECK VALVE - ROLA CHEM	UConn:Burton Family Football Complex	ROLACHEM CHECK VALVE (CHECK VALVE INLIN	1.00
			COMPLETE HOSE ASSEMBLY COMPLETE - ROLA	UConn:Burton Family Football Complex	ROLA HOSE ASSY COMPLETE-- ROLAC (COMPL	1.00
			6/15 - REPLACE PUMP AND ADJACENT PLUMBIN	UConn:Burton Family Football Complex	Labor	4.50
			2" SCD 80 90 ELBOW	UConn:Burton Family Football Complex	90 2 S80 (2" SCD 80 90 ELBOW)	4.00
			MALE ADAPTER 2" SCD 80	UConn:Burton Family Football Complex	MALE ADAPT 2 S80 (MALE ADAPTER 2" SCD 80)	2.00
			PRESSURE GAUGE 1/4" - BOTTOM MOUNT	UConn:Burton Family Football Complex	PRESSURE GAUGE - BOTTOM MOUNT (PRESSU	1.00
			ASTRAL PVC TRUE UNION BALL VALVE	UConn:Burton Family Football Complex	MATERIAL SERVICE	1.00
			2" SCD80 COUPLER	UConn:Burton Family Football Complex	COUP 2 S80 (2" SCD80 COUPLER)	1.00
			2" RIGID PIPE GRAY SCD80	UConn:Burton Family Football Complex	PIPE 2 S80 (2" RIGID PIPE GRAY SCD80 )	2.00
			PENTAIR BULKHEAD UNION	UConn:Burton Family Football Complex	MATERIAL SERVICE	1.00
			3/4 HP WHISPERFLO PUMP	UConn:Burton Family Football Complex	MATERIAL SERVICE	1.00
			CHLORINE NEUTRALIZER - 25# PAIL	UConn:Burton Family Football Complex	CHLOR NEUT 25 (CHLORINE NEUTRALIZER - 25#	2.00
			8/20 - LABOR & PARTS TO INSTALL 2 LADDER SC	UConn:Burton Family Football Complex	Labor	1.00
			8/17 - LABOR TO RETAPE FITTINGS AT THE PUM	UConn:Burton Family Football Complex	Labor	1.50
			UN1791, 1 IBC HYPOCHLORITE SOLUTION, 8, PC	UConn:Burton Family Football Complex	SH IBC (UN1791, 1 IBC HYPOCHLORITE SOLUTIC	200.00
			UN1791, 1 IBC HYPOCHLORITE SOLUTION, 8, PC	UConn:Burton Family Football Complex	SH IBC (UN1791, 1 IBC HYPOCHLORITE SOLUTIC	250.00
			UN1791, 1 IBC HYPOCHLORITE SOLUTION, 8, PC	UConn:Burton Family Football Complex	SH IBC (UN1791, 1 IBC HYPOCHLORITE SOLUTIC	250.00
	Total Burton Family Football Complex					727.50
	<b>Gampel Pavillion</b>					
			10/10 - EVALUATE HOT TUB FOR NOT HEATING;	UConn:Gampel Pavillion	Labor	1.00
			10/15 - LABOR TO REPLACE THE PRESSURE SW	UConn:Gampel Pavillion	Labor	0.50
			PRESSURE SWITCH	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			UN1479., OXIDIZING SOLID, N.O.S. (BROMO-CHL	UConn:Gampel Pavillion	BRO 15 (UN1479., OXIDIZING SOLID, N.O.S. (BRC	2.00
			25 # SODA ASH PH RISE	UConn:Gampel Pavillion	PHRI 25 (25 # SODA ASH PH RISE)	4.00
			25# PHLO (MINUS) NOT DOT REGULATED	UConn:Gampel Pavillion	PHLO 25 (25# PHLO (MINUS) NOT DOT REGULAT	1.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Gampel Pavillion	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION ORI	3.00
			COMMERCIAL LIQUID DPD TEST KIT DPD TEST P	UConn:Gampel Pavillion	TK K2005 (COMMERCIAL LIQUID DPD TEST KIT E	1.00
			4/6 - LABOR TO REPLACE CHLORINATOR FEED	UConn:Gampel Pavillion	Labor	3.00
			ROLACHEM CHLORINATOR SILICONE FEEDER T	UConn:Gampel Pavillion	ROLACHEM FEEDER TUBE (ROLACHEM CHLOR)	2.00
			CHECK VALVE - ROLA CHEM	UConn:Gampel Pavillion	ROLACHEM CHECK VALVE (CHECK VALVE INLIN	1.00
			UN1479., OXIDIZING SOLID, N.O.S. (BROMO-CHL	UConn:Gampel Pavillion	BRO 25 (UN1479., OXIDIZING SOLID, N.O.S. (BRC	2.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Gampel Pavillion	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION ORI	3.00
			5/1 - LABOR TO REPLACE MOTOR ON TUB	UConn:Gampel Pavillion	Labor	1.75
			3/4 HP MOTOR, IMPELLER & SEAL	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			1 QUART STAIN & SCALE CONTROL	UConn:Gampel Pavillion	STAIN & SCALE (1 QUART STAIN & SCALE CONT	12.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Gampel Pavillion	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION ORI	2.00
			DROP N VAC NON ALUM FLOC - QUART - GLB	UConn:Gampel Pavillion	DROP N VAC (DROP N VAC NON ALUM FLOC - Q	1.00

UConn Usage by pool  
10-1-14 to Present

			UN1791, HYPOCHLORITE SOLUTION, 8, PG III (S)	UConn:Gampel Pavillion	SH 5 (UN1791, HYPOCHLORITE SOLUTION, 8, PG III (S))	12.00
			DEPOSIT CONTAINER - 5 GL CARBOY	UConn:Gampel Pavillion	905 (DEPOSIT CONTAINER - 5 GL CARBOY)	12.00
			2/4 - LABOR TO TROUBLESHOOT HEATER; REPL	UConn:Gampel Pavillion	Labor	4.00
			2/8 - LABOR TO INSTALL CARTRIDGE FILTER; RE	UConn:Gampel Pavillion	Labor	3.00
			CLEAN & CLEAR 150 SQ FT FILTER	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			PUMP DIFFUSER	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			PRESSURE SWITCH FOR HEATER	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			2" SCD40 90° ELBOW	UConn:Gampel Pavillion	90 2 S40 (2" SCD40 90° ELBOW)	3.00
			2" SCD40 STREET 90°	UConn:Gampel Pavillion	90 2 STREET S40 (2" SCD40 STREET 90°)	1.00
			COUPLER 2" SCD40	UConn:Gampel Pavillion	COUP 2 S40 (COUPLER 2" SCD40)	2.00
			PIPE RIGID 2" SCD40 (FOOT)	UConn:Gampel Pavillion	PIPE 2 S40 (PIPE RIGID 2" SCD40 (FOOT))	2.00
			UNION 2" SCD40 SXS	UConn:Gampel Pavillion	UNION 2 S40 SXS (UNION 2" SCD40 SXS)	1.00
			SHEPARDS CROOK	UConn:Gampel Pavillion	SHEPARDS CROOK (SHEPARDS CROOK)	2.00
			SHEPERD'S CROOK BRASS NUT /BOLT	UConn:Gampel Pavillion	SHEPARDS CROOK HARDWARE (SHEPERD'S CROOK)	4.00
			POLE FOR SHEPARDS CROOK - 16' ONE PIECE	UConn:Gampel Pavillion	SHEPARDS CROOK POLE (POLE FOR SHEPARD	2.00
			1 QUART STAIN & SCALE CONTROL	UConn:Gampel Pavillion	STAIN & SCALE (1 QUART STAIN & SCALE CONT	12.00
			PHOS FREE - 3 LITER	UConn:Gampel Pavillion	PHOS FREE 3 LITER (PHOS FREE - 3 LITER)	4.00
			FC0688 CARTRIDGE 10 1/16" X 31 1/8" 200 SQ FT	UConn:Gampel Pavillion	MATERIAL SERVICE	4.00
			FREIGHT	UConn:Gampel Pavillion	FREIGHT (FREIGHT)	1.00
			7/20 - LABOR TO REPAIR BROMINE FEEDER	UConn:Gampel Pavillion	Labor	2.00
			NIPPLE, CONTROL VALVE, TUBE, SPRING & ELB	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Gampel Pavillion	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION OR	2.00
			TAYLOR #1 DPD REAGENT 3/4oz	UConn:Gampel Pavillion	R0001A (TAYLOR #1 DPD REAGENT 3/4oz)	1.00
			CALCIUM HYPOCHLORITE HYDRATED 5.1 UN28	UConn:Gampel Pavillion	CH 50 (UN 2880, CALCIUM HYPOCHLORITE HYD	1.00
			WALL BRUSH 18"	UConn:Gampel Pavillion	BRUSH 18" (WALL BRUSH 18")	2.00
			2 oz THIOSULFATE #7 - TAYLOR	UConn:Gampel Pavillion	R0007C (2 oz THIOSULFATE #7 - TAYLOR)	3.00
			FREIGHT	UConn:Gampel Pavillion	FREIGHT (FREIGHT)	1.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Gampel Pavillion	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION OR	4.00
			LEAF RAKE	UConn:Gampel Pavillion	LEAF RAKE (LEAF RAKE)	1.00
			1 QUART STAIN & SCALE CONTROL	UConn:Gampel Pavillion	STAIN & SCALE (1 QUART STAIN & SCALE CONT	20.00
			UN1791, HYPOCHLORITE SOLUTION, 8, PG III (S)	UConn:Gampel Pavillion	SH 5 (UN1791, HYPOCHLORITE SOLUTION, 8, PG III (S))	4.00
			DEPOSIT CONTAINER - 5 GL CARBOY	UConn:Gampel Pavillion	905 (DEPOSIT CONTAINER - 5 GL CARBOY)	4.00
			DEPOSIT CONTAINER - 5 GL CARBOY	UConn:Gampel Pavillion	905 (DEPOSIT CONTAINER - 5 GL CARBOY)	-9.00
			UN2468, TRICHLOROISOCYANURIC ACID (TRICH	UConn:Gampel Pavillion	CT3 50 (UN2468, TRICHLOROISOCYANURIC ACID	1.00
			40 # 4/1GL HYPOCHLORITE SOLUTION ORM-D C	UConn:Gampel Pavillion	SH 4 (40 # 4/1GL HYPOCHLORITE SOLUTION OR	1.00
			QUART BOTTLE DEFOAMER	UConn:Gampel Pavillion	FOAM (QUART BOTTLE DEFOAMER)	24.00
			6/19 - LABOR TO REPAIR THE SWIMMEX HOT TU	UConn:Gampel Pavillion	Labor	1.00
			SUPER PUMP MOTOR 3/4 HP	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			SEAL & GASKET KIT	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			HC170 FILTER CARTRIDGE	UConn:Gampel Pavillion	MATERIAL SERVICE	4.00
			FREIGHT	UConn:Gampel Pavillion	FREIGHT (FREIGHT)	1.00
			11/8 - LABOR TO REPLACE PULSAR FLOAT VALV	UConn:Gampel Pavillion	Labor	4.50
			PULSAR FLOAT VALVE ASSEMBLY & FLOAT NUT	UConn:Gampel Pavillion	MATERIAL SERVICE	1.00
			UN 2880, CALCIUM HYPOCHLORITE HYDRATED,	UConn:Gampel Pavillion	CH 25 (UN 2880, CALCIUM HYPOCHLORITE HYD	1.00
			Total Gampel Pavillion			191.75
			Total UConn			945.75
			<b>TOTAL</b>			<b>945.75</b>