Page 1 of 1



**Bid Addendum** 

Addendum No.: 2

Date Of Addendum: October 4, 2019

CT DAS ● Construction Services ● Office of Legal Affairs, Policy, and Procurement

Roof Replacement and Repair Carl Robinson Correction Facility Enfield, CT BI - JA - 470-A.

Original Bid Due Date / Time:

October 16, 2019

1:00 PM

Previous Addendums: Addendum #1 dated 9/6/2019

TO:

**Prospective Bid Proposers:** 

This Addendum forms part of the "Contract Documents" and modifies or clarifies the original "Contract Documents" for this Project dated 3/15/2019. Prospective Bid Proposers shall acknowledge receipt of the total number the Addenda issued for this Project on the space provided on Section 00 41 00 Bid Proposal Form.

Failure to acknowledge receipt of the total number the Addenda issued for this Project on the space provided on Section 00 41 00 Bid Proposal Form shall subject Bid Proposers to disqualification.

The following clarifications are applicable to drawings and specifications for the project referenced above.

#### <u>Item 1:</u>

Pre-Bid Attendance Log, Agenda and Minutes (Attached)

All questions must be emailed (not verbal or by phone) to the consulting Architect/Engineer (Martin A. Benassi, AlA, Email: mbenassi@mabarchitect.com) with copies sent to the DAS/CS Project Manager (Steven Udeh, Email: steven.udeh@ct.gov) and Construction Manager (NA, Email: NA)

End of Addendum # 2

Mellanee Walton, Associate Fiscal Administrative Officer

State of Connecticut

Department of Administrative Services, Construction Services

Office of Legal Affairs, Policy, and Procurement

450 Columbus Boulevard, Suite 1302

Hartford, CT 06103

# ROOF REPLACEMENT AND REPAIR DEPARTMENT OF CORRECTIONS CARL ROBINSON CORRECTIONAL INSTITUTION 285 Shaker Road Enfield, Connecticut 06082

### STATE OF CONNECTICUT DEPARTMENT OF CORRECTIONS

Department of Administrative Services DAS Project No.: BI-JA-470-A Architect's Project No.: 17-11

Date: September 26, 2019 @ 11:00 a.m.

#### **Pre-Bid Meeting Minutes**

- 1. The meeting was held at the State of Connecticut Department of Corrections conference room in Building #5, Bilton Road, Enfield, CT.
- The meeting was conducted by Steve Udeh (DAS Project Manager); Paul Bessette (Construction Administrator and Plant Facilities Engineer for the Carl Robinson Correctional Institution); and Martin Benassi (Martin A. Benassi, AIA - Architect, LLC).
- 3. Attendance Log was distributed. (Refer to attached copy.)
- 4. Steve Udeh began meeting.
  - A. This meeting was described as an informal, pre-bid meeting for the project of "Roof Replacement and Repair" at Carl Robinson Correctional Institution.
  - B. Team members were introduced.
  - C. In the future, all questions are to be submitted in writing.
  - D. Bids are due October 16, 2019.
  - E. Currently, the duration of work is held at 90 days.
  - F. Currently, no official start date has been determined.
- 5. Paul Bessette retrieved a site photo used to aid in describing the locations and logistics of work involved.
  - A. Security is of primary importance.
  - B. The expense of transporting men and materials in and out of the institution is the responsibility of the Contractor.
  - C. Contractors are responsible for developing their own methods of entering and exiting job sites in a timely manner.
  - An area of parking lot will be designated for Contractor's use. Security of the area is the responsibility of the Contractor.
- 6. Martin Benassi gave a description of the scope of work as explained in the Construction Documents (Drawings and Specifications).
  - A. To aid in the discussion of the scope of work, the Architect's pre-bid agenda was distributed.
  - B. Included within the agenda were the buildings' "Scope of Work" as described on Sheet SP-1 of the Architect's Drawings.
  - C. Included within the agenda were "Unit Price Quantities" as described within the Architect's Specifications.
- 7. The mandatory pre-bid meeting was adjourned from the conference room. For those wishing, a non-mandatory site visit began afterward at the corrections facility.

To the best of my knowledge, the above represents the important items discussed during the meeting. Please take time to review. Should you take exception to any of the above information, please contact our office immediately.

Submitted by: Jim Harding, AIA Martin A. Benassi, AIA - Architect, LLC

cc: Steven Udeh Steven.Udeh@ct.gov
Paul Bessette Paul.Bessette@ct.gov
Christopher Iwanik Christopher.Iwanik@ct.gov

enc: Attendance Log and Sign-in Sheet

Roof Replacement and Repair Carl Robinson Correctional Institution

Enfield, CT 06082

State Project No.: BI-JA-470-A Architect Project No.: 17-11



#### 6020 Bid Phase Meeting Attendance Log

		hase Meeting Attendance Log		
DAS/CS Project Title:	Roof Replacement and Repair, Carl Robertson Corrections, Enfield CT			
DAS/CS Project No.:	BI-JA-470A	Meeting Purpose (insert "X" below):		
Date:	September 26, 2019	Pre-Bid Meeting X		
Meeting Start Time:	11:00 AM	Post Bid Review Meeting		
Meeting Location:	H5 175 Bilton Rd, Somers, CT 06071			
weeting Location.	no 175 Bilton Rd, Somers, CT 06071	Other:		
Name:	len	Title:		
ompany/Department:	P-5-	E-mail:		
itreet:	1 1/ Esliga	Phone:		
340 Kers	ED DA	860 9283199		
ity/State/Zip	T EXECT	FAX:		
Tacque e				
ame:	()	Title:		
Company/Department:		SENIOR IESTIMATOR		
STIMATING		MIKEB @GAEENWOOD-INDUSTR		
treet:	DR.	Phone: 860 - 798 - 7/00		
ity/State/Zip	200 THE TOTAL TH	FAX:		
DORTH HAVEN,	CT. 06473			
ame: Te De 2	Jaic	Title: FCL'Mc/aC		
ompany/Department:	1011	E-mail: mi		
	velopers	Phone:		
42A Cre	Stuas	203-859-5320		
lity/State/Zip	T 06514	FAX:		
		T		
ame: Edgardo	1/020182	Title: Estimato.		
Company/Department:	2 F. J. T.	E-mail:		
Street:	Ulling the	Phone: The Community Com		
ity/State/Zip O	bey ST	413 5 36 1624		
Sphh	eld, MA 01104	FAM		
lame: a	1	Title;		
WIM HO	EDING, AIA	HECHITECT		
ompany/Department:	7. BENIDSSI AIA	E-mail:		
treet:	01.10.1	Phone: 103) 530 - 8066		
ity/State/Zip		FAX:		
ITAMORN	, CT 06578			
lame: O 0 6	Seeselle	Title: O===		
Company/Department:		E-mail:		
A.	dept of Correction	E-mail: Paul, Besseth @C.L. Gow		
treet:		Phone:		
ity/State/Zip		FAX:		
Market Control of the				
lame:		Title: ACC 2		
Chris	Iwanih	PrE2		
ompany/Department:	of Correction	E-mail: Christopher, Iwanikec		
Dept-	0. 001-01/07	Phone:		
ity/State/Zip		FAX:		
tyrotate/21p		PAA:		

Page 3 of 3

Carl Robinson Correctional Institution

Enfield, CT 06082

State Project No.: BI-JA-470-A Architect Project No.: 17-11



### **Connecticut Department of Correction** District 1 - FM&E 175 Bilton Road, House 5, Somers, CT Attendance Record

Topic: B1-JA-470A - Carl Robinson Roof Replacement & Repair

**Date/Time:** 9/26/19 at 11 am

Location: House 5/Conference Room

Name: (Please Print)	Company or Facility:	Signature:
1. STEVEN UIDEH	DAS/	SAL
MBenago!	Brokitat	Martin tam
3. MIKE BENVIEW	SPEENWOOD IND	iones for
4.50 Mules	comprist for	Elvery Maller
5. Jeff Blair	Young Developers	My Ble
6. Edgardo Vazguez	Tita Rein.	
1. Stephen Pombrowki	CRCI CMS	Ster
8. Lynn HAKDING	MAS DECHITECT	Com /heur K
9. Kunl Bessette	DOC PFEI	the land
10		

# ROOF REPLACEMENT AND REPAIR CARL ROBINSON CORRECTIONAL INSTITUTION 285 Shaker Road Enfield, Connecticut

## STATE OF CONNECTICUT DEPARTMENT OF ADMINISTRATIVE SERVICES

DAS Project No.: BI-JA-470-A Architect's Project No.: 17-11

#### PRE-BID MEETING AGENDA

**September 26, 2019** 

- 1. Owner's Requirements by DAS
- 2. Time to substantial completion (90 calendar days from Authorization to Proceed)
- 3. Contract Documents:
  - A. Drawings and Specifications Dated: March 15, 2019
- 4. Review Scope of Work (includes, but not limited to):
  - A. Roof replacement at Visitor Center and Indoor Recreation Building:
    - 1) New EPDM roof system at low slope areas.
    - 2) Remove existing membrane roofing and insulation system down to the metal deck. Inspect metal roof deck and repair/replace any damaged or defective areas. Where required per FM Global Assembly, include deck reinforcement to structure.
    - 3) Temporary removal and reinstallation of razor wire and bracket assembly.
    - 4) Install new mechanically fastened rigid insulation, protection board, and fully adhered 90 mil EPDM membrane roofing, roofing system, and all related flashings for 25-year warranty.
    - 5) Remove existing and install new pre-fab aluminum coping system.
    - 6) Additional wood blocking as required. Replace damaged wood blocking as per unit pricing.
    - 7) All new sealant work as noted on drawings.
    - 8) Resetting of mechanical equipment and utilities on new curbing and supports.
    - 9) Install fully adhered EPDM new walkway pads as shown to access roof mounted equipment.
    - 10) New roof drawings and roof drain domes (strainers) painted OSHA yellow.
    - 11) Install new guardrails as shown on drawings.
  - B. Low slope repairs at Modular Building, Medical and Activity Building, Housing Units 1-6, and Cafeteria:
    - 1) Repairs and patching to damaged or defective areas of EPDM membrane and flashings as shown on these drawings and where defective as per unit pricing.
    - 2) Miscellaneous EPDM flashing repairs at roof penetrations.
    - 3) EPDM repairs at parapets and curbs as shown on drawings and where defective as per unit pricing.
    - 4) Rigid board insulation replacement where shown on drawings and where damaged as per unit pricing. New rigid board insulation where shown on drawings for additional drainage.
    - 5) Steel deck replacement, reinforcement, and painting where necessary.
    - 6) Wood blocking installation and replacement at curbs and copings necessary for repairs.
    - 7) Clean, paint, reinstall roof drain domes (strainers). Replace missing or damaged roof domes.
    - 8) New roof drains at north and south sides of modular building.
    - 9) Replace sealant work where defective. See unit pricing.
    - 10) Install new guardrails as shown on drawings.
  - C. Metal roof and coping repairs and re-line metal built-in gutters at all buildings:
    - 1) Inspection and repair to metal roofing system as shown on these drawings and where damaged as per unit pricing.
    - 2) Patch damaged metal roofing with PMMA liquid applied flashing.
    - 3) Replace missing, damaged, or rusted fasteners at metal roofing and metal copings.
    - 4) Replace missing foam closures.
    - 5) Reseal metal roofing and coping joints where defective as per unit pricing.
    - Re-line built-in gutters with PMMA liquid flashing, insulated ceiling below where shown on drawings.

Roof Replacement and Repair Carl Robinson Correctional Institution 285 Shaker Road Enfield, Connecticut

DAS Project No.: BI-JA-470-A
Architect's Project No.: 17-11
PAGE 2 OF 4

D. All other related work as shown on the drawings and/or indicated in the specifications.

- E. The Authorities Having Jurisdiction for Threshold Projects, Non-Threshold Projects, and/or Connecticut State University System (CSUS) 2020 Projects, as defined by the Connecticut General Statutes, are the Connecticut Department of Administrative Services (DAS) / Construction Services (CS), Office of State Building Inspector (OSBI), and Office of State Fire Marshal (OSFM).
- 5. General Warranties: When discrepancies exist between general warranties and product specific warranties, the longer warranty will always take precedence.
  - 00 72 13 Article 22
    - 22.1 Unless expressly provided for otherwise in the Contract Documents, the Contractor shall provide a Warranty on the Work for an 18-month period from the date of Substantial Completion. The Contractor shall warrant that the equipment, materials, and workmanship are of good quality and new, unless permitted elsewhere by the Contract Documents, and that the Work shall be free from defects not inherent in the quality required or permitted and that the Work conforms to the Contract Documents.
    - 22.2 Disclaimers and limitation from manufacturers, subcontractors, suppliers, or installer to the Contractor shall not relieve the Contractor of the Warranty on the Work. The Contract Documents detail the related damages, reinstatement of Warranty, replacement cost, and Owner's recourse.
- 6. Product Specific Warranties: When discrepancies exist between general warranties and product specific warranties, the longer warranty will always take precedence.
  - 07 53 23 Single-Ply Membrane Roofing, Flashing, and Insulation:

25-year manufacturer's full system / no dollar limit 2-year General Contractor's materials and workmanship

32 man-hours per year for accidental punctures

07 56 00 Fluid Applied Roofing:

5-year manufacturer's full system / no dollar limit

5-year waterproofing Contractor's applicator maintenance warranty

07 62 00 Sheet Metal Flashing and Trim:

3-year materials and workmanship and General Contractor's installation

20-year manufacturer's materials 20-year manufacturer's Kynar finish

20-year manufacturer's color

07 92 00 Joint Sealant:

5-year materials and workmanship

09 91 00 Painting:

3-year materials and workmanship

22 14 26 13 Roof Drains:

2-year materials and workmanship

7. Unit Price quantities to be included in the Base Bid amount.

DAS Project No.: BI-JA-470-A

Architect's Project No.: 17-11 PAGE 3 OF 4

05 31 00 Metal Decking - Replacement, Patching, and Painting: Total area of metal deck work to be included in the Base Bid amount is as follows (measurement will be taken in plain view and not following actual profile of metal decking):

,	3,	
1.	Visitor Center (15,755 SF metal decking total )	
••	a. Preparation and painting of existing rusted metal deck	800 SF
	b. Metal deck replacement	200 SF
	c. Metal deck reinforcement	200 SF
2.	Indoor Recreation Building (1,340 SF metal decking total)	
	a. Preparation and painting of existing rusted metal deck	75 SF
	b. Metal deck replacement	15 SF
	c. Metal deck reinforcement	15 SF
3.	All Other Buildings in Total	
	<ul> <li>a. Preparation and painting of existing rusted metal deck</li> </ul>	1000 SF
	b Metal deck replacement	500 SF
	c. Metal deck reinforcement	500 SF
06 10 53 Mis	cellaneous Wood Blocking:	
4	Wood Blocking, Linconfeet listed heleville for Olevers of Oversed blocking and E	
1.	Wood Blocking: Linear feet listed below is for 3 layers of 2 x wood blocking per LF	75 LF
	a. Visitor Center	75 LF 25 LF
	b. Indoor Recreation Building c. Modular Building	25 LF 75 LF
	c. Modular Building d. Medical and Activity Building	838 LF
	e. Cafeteria Building	610 LF
	f. Housing Units 1-6	2580 LF
	1. Hodding Child 1 C	2000 Ei
2.	Wood Sheathing	
	a. Visitor Center	30 SF
07 22 00 Roo	of Insulation:	
4	Madulan Duildian	444.05
1.	Modular Building	144 SF
2.	Medical and Activity Building	370 SF
3. 4.	Cafeteria Building Housing Units 1-6	220 SF 924 SF
٦.	Trousing Office 1 0	324 61
07 56 00 Flu	id Applied Roofing:	
1.	Patching and repair of damaged metal roofing	
	a. Visitor Center	50 SF
	b. Indoor Recreation Building	30 <b>2</b> .
	Pyramid Roof	15 SF
	Main Roof	295 SF
	c. Administrative Building	1250 SF
	d. Program Building	40 SF
	e. Vocational Education Building	190 SF
	f. Restrooms	12 SF
	g. Medical and Activity Building	180 SF
	h. Housing Units 1-6	365 SF
	I. Cafeteria Building	36 SF
2.	Patching and repair of damaged metal coping	
۷.	a. Visitor Center	10 SF
	b. Indoor Recreation Building	10 SF
	c. Modular Building	10 SF
	d. Medical and Activity Building	30 SF
	e. Housing Units 1-6	100 SF
	f. Cafeteria Building	32 SF
07 59 00 Roo	of Maintenance and Repairs:	
1.	EPDM membrane and flashing repairs	4400 07
	a. Modular Building	1400 SF
	b. Medical and Activity Building	3696 SF

9216 SF

2210 SF

Housing Units 1-6

Cafeteria Building

DAS Project No.: BI-JA-470-A Architect's Project No.: 17-11 PAGE 4 OF 4

2	2.	Metal roo a. b. c. d. e. f. g.	ofing repairs - Assume 3 fasteners per 1 LF of metal roofing Visitor Center Indoor Recreation Building Misc. metal roofing buildings (Program, Vocational Ed, Res Administrative Building Medical and Activity Building Housing Units 1-6 Cafeteria Building	trooms)		64 LF 254 LF 150 LF 1000 LF 84 LF 390 LF 56 LF
07 62 00 A		a. b. c. d. e. f. g.	ofing repairs - New foam closures at open metal roofing seam Visitor Center Indoor Recreation Building Misc. metal roofing buildings (Program, Vocational Ed, Res Administrative Building Medical and Activity Building Housing Units 1-6 Cafeteria Building Repair and Metal Flashing:			13 LF 6 LF 150 LF 123 LF 17 LF 78 LF 12 LF
1	١.		ping repair - Remove and replace damaged and rusted faster	ners.		
		Assume a. b. c. d.	6 fasteners per 10 LF. Visitor Center Indoor Recreation Building Modular Building Medical and Activity Building	(9" copin	gs) (10" EJ copings) (8" EJ copings) (10" Penthouse copings)	25 LF 5 LF 10 LF 233 LF 26 LF 18 LF 42 LF
		e.	Housing Units 1-6	(8" copin	gs) (15" copings) (10.75" EJ copings)	475 LF 273 LF 150 LF
		f.	Cafeteria Building	(8" copin	gs) (18.5" copings) (20.5" copings)	62 LF 96 LF 21 LF
2	2.	Replace a.	flashing, counter flashing, copings All buildings			300 LF
07 92 00 Jo	oint Sea	lant:				
1 2 3 4 5 6 7 8	2. 3. 4. 5. 5.	Modular Program Administ Medical Housing	ecreation Building			200 LF 200 LF 100 LF 500 LF 400 LF 300 LF 1200 LF 250 LF
22 14 26.13						200 2.
1		Unit Pric	ing			
2	2.	Base Bio a. b. c.	Set (bowl, clamping ring, dome, drain receiver) Clamping rings Domes			6 Units 6 Units 6 Units